

New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

Invest: Both vehicles traveling north on Franklin Blvd, V1 changed lanes as they approached the intersection of Franklin Blvd and Easton Ave, he subsequently sideswiped V2.

D1 stated the following; while he was approaching the intersection a vehicle abruptly stopped in front of him, he attempted to avoid striking same by pulling to the right, however, subsequently struck V2.

D2 stated the following; while approaching the intersection he felt impact from the rear and noticed he was sideswiped.

Investigation revealed D1 caused crash due to driver inattention.

Other Descriptions

- 01 - veh stopped short - Field 118a
- 01 - failed to observe veh - Field 118b

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Poling, William	227	Ellington, Ryan	174	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: Franklin Township Police Department/Somerset Co. Code: _____

Station: FTPD Case No: 23055849

144. Crash Diagram (NOT TO SCALE)



NJTR-1B (Rev. 01/17)

Poling, William

Officer's Signature

227

Badge Number