

New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

DRIVER OF V1 STATED HE NOTICED OTHER VEHICLES SLOWING DOWN AND ALSO BEGAN TO SLOW DOWN WHILE DRIVING STRAIGHT AHEAD. HOWEVER, HE DIDN'T REALIZE V2 HAD COME TO A COMPLTE STOP. HE TRIED TO BRAKE BUT WAS UNSUCCESSFUL AND ENDED UP COLLIDING WITH V2.

DRIVER OF V2 STATED HE STOPPED AT THE CROSS PATHWAY TO LET PEDESTRIANS CROSS THE STREET. SUDDENLY, V1 COLLIDED WITH THE BACK BUMPER OF V2.

INVESTIGATION REVEALED DRIVER OF V1 CAUSED THE CRASH DUE TO DRIVER INATTENTION.

Other Descriptions

01 - FAILURE TO OBSERVE V2 STOPPING FOR WALKING PEDESTRIAN - Field 118a

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Gonzalez, Emily	274	Ellington, Ryan	174	☒ Pending ☐ Complete

**New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram**

Police Dept: Franklin Township Police Department/Somerset Co. Code: 01

Station: FTPD Case No: 23056895

144. Crash Diagram (NOT TO SCALE)

