


NJTR - 1 (Rev. 01/17)

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Address of Occupants If Deceased, Date & Time of
E	--	--	--	--	--	--	--	--	--	--	--	--	--	-- --
F	--	--	--	--	--	--	--	--	--	--	--	--	--	-- --
G	--	--	--	--	--	--	--	--	--	--	--	--	--	-- --
H	--	--	--	--	--	--	--	--	--	--	--	--	--	-- --
I	--	--	--	--	--	--	--	--	--	--	--	--	--	-- --
J	--	--	--	--	--	--	--	--	--	--	--	--	--	-- --

144 Crash Diagram



Show North by Arrow
(Not to Scale)



145 Crash Description

DRIVER #1 STATED, IN EFFECT, HE WAS ATTEMPTING TO MAKE A LEFT TURN ONTO INDEPENDENCE WAY WHEN HE STRUCK VEHICLE #2. DRIVER #1 FURTHER STATE, HE UNDERESTIMATED THE DISTANCE BETWEEN HIS HIS VEHICLE AND VEHICLE #2 AS A RESULT CAUSING THE IMPACT. DRIVER #2 STATED, IN EFFECT, HE WAS TRAVELING WEST ON INDEPENDENCE WAY WHEN HIS VEHICLE WAS STRUCK. VEHICLE #1 SUSTAINED MINOR FRONT END DAMAGE. VEHICLE #2 SUSTAINED DAMAGE ON THE PASSENGER'S SIDE. NO INJURIES NO TOWS.