

New Jersey Police Crash Investigation Report												Case Number 2022-00000053			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 struck a curb while making a left turn from RT 88 eastbound to northbound on Jack Martin Boulevard.

The driver of Vehicle #1 stated she was traveling eastbound on RT 88 before attempting to make a left turn on to Jack Martin Boulevard. Driver #1 stated as she was attempting to turn her vehicle hydroplaned causing her vehicle to travel to the right and ultimately struck the curb on the corner of RT 88 and Jack Martin Boulevard. Driver #1 stated she then attempted to regain control of the vehicle and turned her driver wheel to the left to avoid hitting a tree. As a result of her turning her wheel to the left she reentered her path of travel but ultimately came to a complete stop on the opposite side of the road facing northbound in the southbound lane of Jack Martin Boulevard. Vehicle #1 had damage to the passengers side rim and front axle which disabled the vehicle. Glenn's towing responded and removed Vehicle #1 from the scene.


146. Officer's Signature Frank James Giambona	147. Badge # 290	148. Reviewer Glenn C Turner	Badge # 178	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2022-00000053

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Frank James Giambona

Officer's Signature

290

Badge Number