

**New Jersey Police
Crash Investigation Report**


Case Number

2020-00054823

Page 2 of 4

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Two vehicle crash occurred on 9/12/2020 at approximately 1628 hours on Route 88 westbound near the intersection with Old Squan Rd. Ptl. Theibault #258 and I responded to the scene. Our body worn cameras were on during this investigation.

Driver of vehicle #1 advised he was traveling westbound on Route 88 and did not see vehicle #2 slowing in traffic in front of him. Driver of vehicle #1 stated the sun glare made it very difficult to see vehicle #2 and due to this he struck vehicle #2 in the rear with the front of his vehicle.

Driver of vehicle #2 advised he had just made a left turn out of Vantage Auto (2005 Route 88) and was traveling slow in traffic and observed vehicle #1 in his rear view mirror not slowing down behind him. Driver of vehicle #2 stated he was struck in the rear by the front of vehicle #1.

I observed disabling damage and airbag deployment on vehicle #1 and moderate damage to the rear of vehicle #2. Vehicle #2's bicycle rack mounted on his tow hitch was heavily damaged in the crash.

146. Officer's Signature

Matthew C Knehr

147. Badge #

295

148. Reviewer

—

Badge #

—

149. Case Status

☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01
Station: Case No: 2020-00054823

145 Crash Description

Driver of vehicle #1 is at fault for the crash for following too closely and sun glare.

Matthew C Knehr

Officer's Signature

295

Badge Number

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2020-00054823

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Matthew C Knehr

Officer's Signature

295

Badge Number