

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
12/15/22	2018795

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department ATT: Chief Mulholland 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	H 080	
Quantity	Item Code	Description		Price Each	Amount
81	NJSC - Hydro	New Jersey State Contract 17-FLEET-00819 Vendor ID# 00000570. Hydro-Test of SCBA Cylinder, Including New Authorized Scott Valve O-Ring, Recharge Cylinder with Breathing Air, & Delivery.		30.60	2,478.60
		11/14/22 - 26, 11/17/22 - 8, 11/21/22 - 5, 11/28/22 - 17, 11/22/22 - 8, 12/01/22 - 8, 12/05/22 - 2, 12/09/22 - 7			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$2,478.60	

Test System: 507-HP-14S-P
Test Machine Serial#:
License: N068

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
1622 Route 37 East
NJ 08763

Test ID	Cylinder Owner	Serial #	Mfg'r ID	Size (D x L)	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pct Exp.	Test Result
Test Date/Time	Retest Yrs	Operator	Mfg Date	Disposition										
1	LAKEWOOD-36	OK456098	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8018	77.9	5.5	72.4	75.0	7.1	Pass
	11/14/2022 10:09	5	MATT	10/12	AIR	A: Return to service Notes:								
2	LAKEWOOD-36	OK456208	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8219	81.8	6.8	75.0	75.0	8.3	Pass
	11/14/2022 10:18	5	MATT	10/12	AIR	A: Return to service Notes:								
3	LAKEWOOD-42	OK455385	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8036	72.6	5.9	66.7	69.0	8.1	Pass
	11/14/2022 10:23	5	MATT	9/12	AIR	A: Return to service Notes:								
4	LAKEWOOD-120	OK454129	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8030	94.0	28.3	65.7	69.0	30.1	Pass
	11/14/2022 10:39	5	MATT	9/12	AIR	A: Return to service Notes:								
5	LAKEWOOD-39	OK455851	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8034	492.7	425.2	67.5	69.0	66.3	Pass
	11/14/2022 10:46	5	MATT	10/12	AIR	A: Return to service Notes:								
6	LAKEWOOD-122	OK454128	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8029	71.6	5.7	65.9	69.0	8.0	Pass
	11/14/2022 10:57	5	MATT	9/12	AIR	A: Return to service Notes:								
7	LAKEWOOD-77	OK4551401	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8040	110.4	44.0	66.4	69.0	39.9	Pass
	11/14/2022 11:07	5	MATT	9/12	AIR	A: Return to service Notes:								
8	LAKEWOOD-59	OK456218	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8029	79.8	7.1	72.7	75.0	8.9	Pass
	11/14/2022 11:13	5	MATT	10/12	AIR	A: Return to service Notes:								
9	LAKEWOOD-154	OK455113	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8023	81.3	14.9	66.4	69.0	18.3	Pass
	11/14/2022 11:20	5	MATT	9/12	AIR	A: Return to service Notes:								
10	LAKEWOOD-58	OK456032	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8214	375.6	300.9	74.7	75.0	80.1	Pass
	11/14/2022 11:39	5	MATT	10/12	AIR	A: Return to service Notes:								
11	LAKEWOOD-182	OK454504	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8003	71.4	6.0	65.4	69.0	8.4	Pass
	11/14/2022 11:44	5	MATT	9/12	AIR	A: Return to service Notes:								
12	LAKEWOOD-152	OK454514	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8114	82.6	16.0	66.6	69.0	19.3	Pass
	11/14/2022 11:52	5	MATT	9/12	AIR	A: Return to service Notes:								
13	LAKEWOOD-144	OK454498	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8033	89.3	23.3	66.0	69.0	26.1	Pass
	11/14/2022 11:57	5	MATT	9/12	AIR	A: Return to service Notes:								
14	LAKEWOOD-143	OK454522	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8021	98.6	33.3	65.3	69.0	33.8	Pass
	11/14/2022 12:04	5	MATT	9/12	AIR	A: Return to service Notes:								
15	LAKEWOOD-163	OK462364	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8224	272.3	198.7	73.6	75.0	73.0	Pass
	11/14/2022 12:14	5	MATT	1/13	AIR	A: Return to service Notes:								
16	LAKEWOOD-145	OK455203	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8035	71.6	5.1	66.5	69.0	7.1	Pass
	11/14/2022 12:20	5	MATT	9/12	AIR	A: Return to service Notes:								
17	LAKEWOOD-128	OK455209	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	80	8267	124.5	55.5	69.0	69.0	44.6	Pass
	11/14/2022 12:26	5	MATT	9/12	AIR	A: Return to service Notes:								

Test System: 507-HP-14S-P
 Test Machine Serial#:
 License: N065

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1522 Route 37 East
 , NJ 08753

Test ID	Cylinder Owner	Serial #	Mfr's ID	Size (D x L)	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pot Exp.	Test Result
Test Date/Time	Retest Yrs	Operator	Mfg Date	Gas Svc	Disposition									
18	LAKEWOOD-117	OK455908	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	8021	80.7	8.1	72.6	75.0	10.0	Pass
11/14/2022 12:32	5	MATT	10/12	AIR	A: Return to service	Notes:								
19	LAKEWOOD-148	OK455089	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	8042	435.3	368.0	67.3	69.0	84.5	Pass
11/14/2022 12:38	5	MATT	9/12	AIR	A: Return to service	Notes:								
20	LAKEWOOD-149	OK455123	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	8037	72.2	5.7	66.5	69.0	7.9	Pass
11/14/2022 12:43	5	MATT	9/12	AIR	A: Return to service	Notes:								
21	LAKEWOOD-160	OK454521	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	8023	83.0	17.0	66.0	69.0	20.5	Pass
11/14/2022 12:48	5	MATT	9/12	AIR	A: Return to service	Notes:								
22	LAKEWOOD-55	OK454626	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	8260	75.9	8.0	67.9	69.0	10.5	Pass
11/14/2022 13:01	5	MATT	9/12	AIR	A: Return to service	Notes:								
23	LAKEWOOD-37	OK456200	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	8018	86.8	14.6	72.2	75.0	16.8	Pass
11/14/2022 13:07	5	MATT	10/12	AIR	A: Return to service	Notes:								
24	LAKEWOOD-43	OK456211	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	8016	102.8	30.6	72.2	75.0	29.8	Pass
11/14/2022 13:12	5	MATT	10/12	AIR	A: Return to service	Notes:								
25	LAKEWOOD-38	OK456192	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	8026	79.0	7.3	71.7	75.0	9.2	Pass
11/14/2022 13:19	5	MATT	10/12	AIR	A: Return to service	Notes:								
26	LAKEWOOD-123	OK454624	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	8029	72.0	6.3	65.7	69.0	6.8	Pass
11/14/2022 13:25	5	MATT	9/12	AIR	A: Return to service	Notes:								

Test System: 507-HP-14S-P
 Test Machine Serial#:
 License: N065

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1522 Route 37 East
 , NJ 08753

Test ID	Cylinder Owner	Serial #	Mfg's ID	Size (D x L)	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pot Exp.	Test Result
1	Lakewood -139	ok454528	LUXFER	5.4 X 18.4	DOTSP10915-4500	Pass	80	7550	65.9	4.7	61.2	69.0	7.1	Pass
	11/17/2022 10:47	5	Rob Z	09/12	AIR	A: Return to service Notes:								
2	Lakewood -137	OK456094	LUXFER	5.4 X 18.4	DOTSP10915-4500	Pass	80	7530	71.8	4.7	67.1	75.0	6.6	Pass
	11/17/2022 10:51	5	Rob Z	10/12	AIR	A: Return to service Notes:								
3	Lakewood -136	OK462106	LUXFER	5.4 X 18.4	DOTSP10915-4500	Pass	80	7537	73.8	7.0	66.8	75.0	9.5	Pass
	11/17/2022 10:57	5	Rob Z	01/13	AIR	A: Return to service Notes:								
4	Lakewood -130	OK456263	LUXFER	5.4 X 18.4	DOTSP10915-4500	Pass	80	7553	72.1	4.9	67.2	75.0	6.8	Pass
	11/17/2022 11:03	5	Rob Z	10/12	AIR	A: Return to service Notes:								
5	Lakewood -140	OK456212	LUXFER	5.4 X 18.4	DOTSP10915-4500	Pass	80	7553	72.3	5.1	67.2	75.0	7.1	Pass
	11/17/2022 11:08	5	Rob Z	10/12	AIR	A: Return to service Notes:								
6	Lakewood -131	OK454090	LUXFER	5.4 X 18.4	DOTSP10915-4500	Pass	80	7553	65.4	3.9	61.5	69.0	5.9	Pass
	11/17/2022 11:13	5	Rob Z	10/12	AIR	A: Return to service Notes:								
7	Lakewood -133	OK456191	LUXFER	5.4 X 18.4	DOTSP10915-4500	Pass	80	7514	71.5	4.8	66.7	75.0	6.7	Pass
	11/17/2022 11:18	5	Rob Z	10/12	AIR	A: Return to service Notes:								
8	Lakewood -169	OK456075	LUXFER	5.4 X 18.4	DOTSP10915-4500	Pass	80	7543	63.9	18.5	67.4	75.0	19.7	Pass
	11/17/2022 11:24	5	Rob Z	10/12	AIR	A: Return to service Notes:								

Test System: 507-HP-14S-P
 Test Machine Serial#:
 License: N085

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1522 Route 37 East
 , NJ 08763

Test ID	Cylinder Owner	Serial #	Mfg's ID	Size (D x L)	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pot Exp.	Test Result
1	Lakewood	OK454609	LUXFER	5.5X18.5	DOT-SP10915-4500	Pass	60	7558	85.8	3.9	61.7	69.0	5.9	Pass
	11/21/2022 12:44	5	Ken N	09/12	AIR	A: Return to service Notes:								
2	Lakewood	OK455125	LUXFER	5.5X18.5	DOT-SP10915-4500	Pass	60	7520	86.0	3.7	62.3	69.0	5.6	Pass
	11/21/2022 12:52	5	Ken N	09/12	AIR	A: Return to service Notes:								
3	Lakewood	OK454519	LUXFER	5.5X18.5	DOT-SP10915-4500	Pass	60	7553	86.7	4.9	61.8	69.0	7.4	Pass
	11/21/2022 13:02	5	Ken N	09/12	AIR	A: Return to service Notes:								
4	Lakewood	OK454631	LUXFER	5.5X18.5	DOT-SP10915-4500	Pass	60	7548	86.3	4.1	62.2	69.0	6.2	Pass
	11/21/2022 13:07	5	Ken N	09/12	AIR	A: Return to service Notes:								
5	Lakewood	OK456145	LUXFER	5.5X18.5	DOT-SP10915-4500	Pass	60	7528	71.5	4.4	67.1	75.0	6.2	Pass
	11/21/2022 13:23	5	Ken N	01/12	AIR	A: Return to service Notes:								

Test System: 507-HP-14S-P
Test Machine Serial#:
License: N065

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
1522 Route 37 East
NJ 08783

Test ID	Cylinder Owner	Serial #	Mfg Date	Mfg's ID	Size (D x L)	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pct Exp.	Test Result
1	LAKEWOOD-164	OK454082	9/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7562	66.4	4.6	61.8	69.0	6.9	Pass
	11/28/2022 10:22	5	Matt	AIR	A: Return to service Notes:										
2	LAKEWOOD-41	OK454861	9/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7511	65.3	3.7	61.6	69.0	5.7	Pass
	11/28/2022 10:26	5	Matt	AIR	A: Return to service Notes:										
3	LAKEWOOD-195	OK456162	10/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7556	72.0	4.8	67.2	75.0	6.7	Pass
	11/28/2022 10:32	5	Matt	AIR	A: Return to service Notes:										
4	LAKEWOOD-51	OK455788	10/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7557	67.0	4.6	62.4	69.0	6.9	Pass
	11/28/2022 10:38	5	Matt	AIR	A: Return to service Notes:										
5	LAKEWOOD-181	OK456018	10/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7517	71.4	3.7	67.7	69.0	5.2	Pass
	11/28/2022 10:43	5	Matt	AIR	A: Return to service Notes:										
6	LAKEWOOD-185	OK456520	9/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7564	66.7	3.8	62.9	69.0	5.7	Pass
	11/28/2022 10:48	5	Matt	AIR	A: Return to service Notes:										
7	LAKEWOOD-50	OK456268	10/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7528	71.8	4.6	67.3	75.0	6.3	Pass
	11/28/2022 10:53	5	Matt	AIR	A: Return to service Notes:										
8	LAKEWOOD-172	OK454126	9/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7562	65.7	3.8	61.9	69.0	5.8	Pass
	11/28/2022 10:58	5	Matt	AIR	A: Return to service Notes:										
9	LAKEWOOD-166	OK456133	10/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7749	76.2	6.2	70.0	75.0	8.1	Pass
	11/28/2022 11:05	5	Matt	AIR	A: Return to service Notes:										
10	LAKEWOOD-177	OK456210	10/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7549	71.7	4.4	67.3	75.0	6.2	Pass
	11/28/2022 11:09	5	Matt	AIR	A: Return to service Notes:										
11	LAKEWOOD-183	OK455999	10/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7533	71.1	3.2	67.9	75.0	4.5	Pass
	11/28/2022 11:15	5	Matt	AIR	A: Return to service Notes:										
12	LAKEWOOD-191	OK456087	10/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7539	71.3	3.6	67.7	75.0	5.0	Pass
	11/28/2022 11:21	5	Matt	AIR	A: Return to service Notes:										
13	LAKEWOOD-86	OK454621	9/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7563	65.7	4.1	61.6	69.0	6.2	Pass
	11/28/2022 11:27	5	Matt	AIR	A: Return to service Notes:										
14	LAKEWOOD-179	OK456203	10/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7563	73.0	5.2	67.8	75.0	7.1	Pass
	11/28/2022 11:33	5	Matt	AIR	A: Return to service Notes:										
15	LAKEWOOD-175	OK454145	9/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7533	65.8	3.9	61.9	69.0	5.9	Pass
	11/28/2022 11:42	5	Matt	AIR	A: Return to service Notes:										
16	LAKEWOOD-48	OK456056	10/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7558	72.5	4.1	68.4	75.0	5.7	Pass
	11/28/2022 11:50	5	Matt	AIR	A: Return to service Notes:										
17	LAKEWOOD-49	OK456201	10/12	LUXFER	5.5X18.5	DOTSP10915-4500	Pass	60	7557	72.2	4.6	67.6	75.0	6.4	Pass
	11/28/2022 11:55	5	Matt	AIR	A: Return to service Notes:										

Test System: 807-HP-14S-P
 Test Machine Serial#: N065
 License: N065

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1622 Route 37 East
 , NJ 08753

Test ID	Cylinder Owner	Serial #	Mfg's ID	Size (D x L)	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pct Exp.	Test Result
1	LAKEWOOD-155	OK456281	LUXFER	5.5X18.5	DOT-SP10915-4500	Pass	80	7537	71.9	5.5	66.4	75.0	7.6	Pass
	11/22/2022 13:16	5	MATT	10/12	AIR	A: Return to service Notes:								
2	LAKEWOOD-NO NUMBER	OK456102	LUXFER	5.5X16.5	DOT-SP10915-4500	Pass	80	7536	98.3	30.8	67.5	75.0	31.3	Pass
	11/22/2022 13:20	5	MATT	10/12	AIR	A: Return to service Notes:								
3	LAKEWOOD-NO NUMBER	OK578372	LUXFER	5.5X18.5	DOT-SP10915-4500	Pass	80	7799	75.1	7.3	67.8	76.0	9.7	Pass
	11/22/2022 13:42	5	MATT	08/17	AIR	A: Return to service Notes:								
4	LAKEWOOD-NO NUMBER	OK454834	LUXFER	5.5X18.5	DOT-SP10915-4500	Pass	80	7535	75.6	13.9	61.7	69.0	18.4	Pass
	11/22/2022 13:48	5	MATT	9/12	AIR	A: Return to service Notes:								
5	LAKEWOOD-NO NUMBER	OK578806	LUXFER	5.5X18.5	DOT-SP10915-4500	Pass	80	7514	71.7	5.8	65.9	76.0	8.1	Pass
	11/22/2022 13:53	5	MATT	8/17	AIR	A: Return to service Notes:								
6	LAKEWOOD-NO NUMBER	OK578813	LUXFER	5.5X18.5	DOT-SP10915-4500	Pass	80	7527	72.0	8.0	66.0	76.0	8.3	Pass
	11/22/2022 13:57	5	MATT	8/17	AIR	A: Return to service Notes:								
7	LAKEWOOD-84	OK454818	LUXFER	5.5X18.5	DOT-SP10915-4500	Pass	80	7553	65.8	4.0	61.8	69.0	6.1	Pass
	11/22/2022 14:03	5	MATT	9/12	AIR	A: Return to service Notes:								
8	LAKEWOOD-NO NUMBER	OK454509	LUXFER	5.5X18.5	DOT-SP10915-4500	Pass	80	7551	65.3	3.8	61.7	69.0	5.5	Pass
	11/22/2022 14:11	5	MATT	9/12	AIR	A: Return to service Notes:								

Test System: 807-HP-14S-P
 Test Machine Serial#:
 License: N066

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1522 Route 37 East
 , NJ 08753

Test ID	Cylinder Owner	Serial #	Mfg'r's ID	Size (D x L)	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pct Exp.	Test Result
1	LAKEWOOD- 034	OK462337	LUXFER	5.4X18.4	DOTSP10915-4500	Pass	60	7560	85.0	18.3	66.7	75.0	21.5	Pass
	12/01/2022 09:47	5	ROB	01/13	AIR	A: Return to service Notes:								
2	LAKEWOOD- 062	OK462354	LUXFER	5.4X18.4	DOTSP10915-4500	Pass	60	7501	81.4	25.9	65.5	75.0	28.3	Pass
	12/01/2022 09:54	5	ROB	01/13	AIR	A: Return to service Notes:								
3	LAKEWOOD- 085	OK462466	LUXFER	5.4X18.4	DOTSP10915-4500	Pass	60	7529	71.2	5.1	66.1	75.0	7.2	Pass
	12/01/2022 10:00	5	ROB	01/13	AIR	A: Return to service Notes:								
4	LAKEWOOD- 151	OK462465	LUXFER	5.4X18.4	DOTSP10915-4500	Pass	60	7530	71.4	4.8	66.6	75.0	6.7	Pass
	12/01/2022 10:06	5	ROB	01/13	AIR	A: Return to service Notes:								
5	LAKEWOOD- 054	OK462427	LUXFER	5.4X18.4	DOTSP10915-4500	Pass	60	7551	71.4	4.7	66.7	75.0	6.6	Pass
	12/01/2022 10:11	5	ROB	01/13	AIR	A: Return to service Notes:								
6	LAKEWOOD- 173	OK464597	LUXFER	5.4X18.4	DOTSP10915-4500	Pass	60	7516	66.0	5.1	60.9	69.0	7.7	Pass
	12/01/2022 10:18	5	ROB	09/12	AIR	A: Return to service Notes:								
7	LAKEWOOD- NO#	OK462335	LUXFER	5.4X18.4	DOTSP10915-4500	Pass	60	7823	83.2	24.0	69.2	75.0	25.7	Pass
	12/01/2022 10:26	5	ROB	01/13	AIR	A: Return to service Notes:								
8	LAKEWOOD- 118	OK462462	LUXFER	5.4X18.4	DOTSP10915-4500	Pass	60	7546	94.1	27.6	66.5	75.0	29.3	Pass
	12/01/2022 10:38	5	ROB	01/13	AIR	A: Return to service Notes:								

Test System: 507-HP-14S-P
 Test Machine Serial#:
 License: N065

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1522 Route 37 East
 , NJ 08753

Test ID	Cylinder Owner			Serial # Mfg Date	Mfg'r ID Gas Svc	Size (D x L) Disposition	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pct Exp.	Test Result
	Test Date/Time	Retest Yrs	Operator													
1	LAKEWOOD-060			OK455390	LUXFER	5.4X18.4	DOTSP1915-4500	Pass	60	7520	66.7	4.0	62.7	69.0	8.0	Pass
	12/05/2022 09:47	5	ROB	09/12	AIR	A: Return to service Notes:										
2	LAKEWOOD-067			OK462372	LUXFER	5.4X18.4	DOTSP1915-4500	Pass	60	7554	74.1	7.3	66.8	75.0	9.9	Pass
	12/05/2022 09:55	5	ROB	01/13	AIR	A: Return to service Notes:										

Test System: 507-HP-14S-P
 Test Machine Serial#:
 License: N065

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1622 Route 37 East
 , NJ 08753

Test ID	Cylinder Owner	Serial #	Mfg'r's ID	Size (D x L)	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pot Exp.	Test Result
1	LAKEWOOD -015	OK576818	LUXFER	5.4X18.4	DOT-SP10915-4500	Pass	60	7515	71.5	5.9	66.6	76.0	8.2	Pass
	12/09/2022 09:11	5	ROB	08/17	AIR	A: Return to service Notes:								
2	LAKEWOOD -020	OK454189	LUXFER	5.4X18.4	DOT-SP10915-4500	Pass	60	7602	70.6	5.8	64.8	69.0	8.2	Pass
	12/09/2022 09:19	5	ROB	09/12	AIR	A: Return to service Notes:								
3	LAKEWOOD -014	OK454526	LUXFER	5.4X18.4	DOT-SP10915-4500	Pass	60	7558	65.3	3.8	61.5	69.0	5.8	Pass
	12/09/2022 09:25	5	ROB	09/12	AIR	A: Return to service Notes:								
4	LAKEWOOD -016	OK455902	LUXFER	5.4X18.4	DOT-SP10915-4500	Pass	60	7534	72.8	5.5	67.3	75.0	7.6	Pass
	12/09/2022 09:31	5	ROB	10/12	AIR	A: Return to service Notes:								
5	LAKEWOOD -121	OK454813	LUXFER	5.4X18.4	DOT-SP10915-4500	Pass	60	7500	75.4	13.9	61.5	69.0	18.4	Pass
	12/09/2022 09:36	5	ROB	09/12	AIR	A: Return to service Notes:								
6	LAKEWOOD -208	OK454630	LUXFER	5.4X18.4	DOT-SP10915-4500	Pass	60	7511	65.2	4.1	61.1	69.0	6.3	Pass
	12/09/2022 09:42	5	ROB	09/12	AIR	A: Return to service Notes:								
7	LAKEWOOD -021	OK455143	LUXFER	5.4X18.4	DOT-SP10915-4500	Pass	60	7569	66.7	4.1	62.6	69.0	6.2	Pass
	12/09/2022 09:47	5	ROB	09/12	AIR	A: Return to service Notes:								

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
2/27/23	2019657

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department ATT: Chief Mulholland 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	MULTI	
Quantity	Item Code	Description		Price Each	Amount
31	NJSC - Hydro	New Jersey State Contract 17-FLEET-00819 Vendor ID# 00000570. Hydro-Test of SCBA Cylinder, Including New Authorized Scott Valve O-Ring, Recharge Cylinder with Breathing Air, & Delivery.		30.60	948.60
		02/01/23 - 18			
		02/06/23 - 3			
		02/14/23 - 4			
		02/17/23 - 1			
		02/24/23 - 5			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$948.60	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
2/23/23	2019623

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department ATT: Chief Mulholland 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	TRS 102	
Quantity	Item Code	Description		Price Each	Amount
1	803380-02	SCOTT valve body assy 4.5		243.00	243.00
2	36713-00	SCOTT valve seat		8.11	16.22
	NJSC - Scott P...	New Jersey State Contract 17-FLEET-00819 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Cylinder # 023 - IL1017929 - Replaced valve body and plug.			
		Cylinder # 100 - IL1028367 - Replaced valve plug			
Phone #		(732) 968-2121	Fax #	732-968-4724	Total \$349.22

Test System: 507-HP-148-P
Test Machine Serial#:
License: N066

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
1622 Route 37 East
NJ 08763

Test ID	Cylinder Owner	Serial #	Mfg's ID	Size (D x L)	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pot. Exp.	Test Result
1	LAKEWOOD- 125	OK456097	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7531	72.8	4.9	87.9	75.0	6.7	Pass
	02/01/2023 08:44	5	ROB Z	10/12	AIR	A: Return to service Notes:								
2	LAKEWOOD- 210	OK482428	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7541	71.5	4.2	87.3	75.0	5.9	Pass
	02/01/2023 08:50	5	ROB Z	01/13	AIR	A: Return to service Notes:								
3	LAKEWOOD- 168	OK482362	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7551	71.9	4.4	87.5	75.0	6.1	Pass
	02/01/2023 08:55	5	ROB Z	01/13	AIR	A: Return to service Notes:								
4	LAKEWOOD- 083	OK486073	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7553	72.6	4.7	87.9	77.0	6.5	Pass
	02/01/2023 09:03	5	ROB Z	12/13	AIR	A: Return to service Notes:								
5	LAKEWOOD- 211	OK482347	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7535	71.6	4.1	87.5	75.0	5.7	Pass
	02/01/2023 09:10	5	ROB Z	01/13	AIR	A: Return to service Notes:								
6	LAKEWOOD- 178	OK485990	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7624	71.6	3.1	88.5	77.0	4.3	Pass
	02/01/2023 09:18	5	ROB Z	12/13	AIR	A: Return to service Notes:								
7	LAKEWOOD- 141	OK485180	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7516	71.4	4.5	88.9	75.0	6.3	Pass
	02/01/2023 09:32	5	ROB Z	12/13	AIR	A: Return to service Notes:								
8	LAKEWOOD- 142	OK486061	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7562	72.0	4.0	88.0	77.0	5.6	Pass
	02/01/2023 09:38	5	ROB Z	12/13	AIR	A: Return to service Notes:								
9	LAKEWOOD- 074	OK482349	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7605	72.2	4.2	88.0	75.0	5.8	Pass
	02/01/2023 09:46	5	ROB Z	01/13	AIR	A: Return to service Notes:								
10	LAKEWOOD- 017	OK486069	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7526	71.7	4.6	86.9	77.0	6.7	Pass
	02/01/2023 09:59	5	ROB Z	12/13	AIR	A: Return to service Notes:								
11	LAKEWOOD- 030	OK482422	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7546	71.8	4.3	87.3	75.0	6.0	Pass
	02/01/2023 10:10	5	ROB Z	01/13	AIR	A: Return to service Notes:								
12	LAKEWOOD- 174	OK482366	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7515	71.2	4.4	86.6	75.0	6.2	Pass
	02/01/2023 10:17	5	ROB Z	01/13	AIR	A: Return to service Notes:								
13	LAKEWOOD- 019	OK486423	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7532	72.3	5.0	87.3	77.0	6.9	Pass
	02/01/2023 10:35	5	ROB Z	12/13	AIR	A: Return to service Notes:								
14	LAKEWOOD- NO#	OK482491	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7561	71.8	4.4	87.4	75.0	6.1	Pass
	02/01/2023 10:41	5	ROB Z	01/13	AIR	A: Return to service Notes:								
15	LAKEWOOD- 033	OK482493	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7563	71.8	4.9	86.9	75.0	6.8	Pass
	02/01/2023 10:53	5	ROB Z	01/13	AIR	A: Return to service Notes:								
16	LAKEWOOD- 147	OK462357	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7633	72.2	4.0	86.2	75.0	5.5	Pass
	02/01/2023 10:59	5	ROB Z	01/13	AIR	A: Return to service Notes:								
17	LAKEWOOD- NO #	OK485557	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7524	106.9	40.7	86.2	75.0	38.1	Pass
	02/01/2023 11:09	5	ROB Z	12/13	AIR	A: Return to service Notes:								

Test System: 507-HP-14S-P
 Test Machine Serial#:
 License: N065

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1622 Route 37 East
 , NJ 08763

Test ID	Cylinder Owner	Serial #	Mfr's ID	Size (D x L)	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pct Exp.	Test Result
18	LAKEWOOD- 129	OK486306	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7529	71.3	4.4	66.9	77.0	6.2	Pass
	02/01/2023 11:17	5	ROB Z	12/13	AIR	A: Return to service Notes:								
19	LAKEWOOD- 129		LUXFER	5.4X18.4	DOTSP109154500	Pass	60	0	0.0	0.0	0.0	77.0	0.0	Not Tested
	N/A	5	ROB Z	12/13	AIR	H: Not Tested Notes:								

Test System: 507-HP-14S-P
 Test Machine Serial#:
 License: N065

Cylinder Retest Data Sheet

Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1622 Route 37 East
 , NJ 08753

Test ID	Cylinder Owner	Serial #	Mfg'r's ID	Size (D x L)	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pct Exp.	Test Result
10	LAKEWOOD -212	OK482388	LUXFER	5.4X18.4	DOTSP109154500	Pass	80	7534	72.2	5.5	88.7	75.0	7.8	Pass
	02/08/2023 13:52	5	ROB Z	01/13	AIR	A: Return to service Notes:								
11	LAKEWOOD -212	OK482414	LUXFER	5.4X18.4	DOTSP109154500	Pass	80	7537	71.5	4.3	87.2	75.0	6.0	Pass
	02/08/2023 13:57	5	ROB Z	01/13	AIR	A: Return to service Notes:								
12	LAKEWOOD -212	OK456196	LUXFER	5.4X18.4	DOTSP109154500	Pass	80	7546	71.5	3.7	87.8	75.0	5.2	Pass
	02/08/2023 14:02	5	ROB Z	10/12	AIR	A: Return to service Notes:								

Test System: 507-HP-14S-P
 Test Machine Serial#:
 License: N088

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1522 Route 37 East
 , NJ 08763

Test ID	Cylinder Owner	Serial #	Mfg's ID	Size (D x L)	Spec/Svc Press	Visual	Test	Actual	Total	Perm.	Elastic	REE	Pct	Test	
ID	Test Date/Time	Retest Yrs	Operator	Mfg Date	Gas Svc	Insp.	Time	Press	Exp.	Exp.	Exp.		Exp.	Result	
1	LAKEWOOD -068		OK488068	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7611	77.8	10.8	67.2	77.0	13.6	Pass
	02/14/2023 13:43	5	ROB Z	12/13	AIR	A: Return to service Notes:									
2	LAKEWOOD -088 - 026		OK486047	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7539	71.0	4.0	67.0	77.0	5.6	Pass
	02/14/2023 13:56	5	ROB Z	12/13	AIR	A: Return to service Notes:									
3	LAKEWOOD -040		OK482437	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7540	70.8	4.0	66.8	75.0	5.6	Pass
	02/14/2023 14:17	5	ROB Z	01/13	AIR	A: Return to service Notes:									
4	LAKEWOOD -180		OK482441	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7542	71.0	4.0	67.0	75.0	5.6	Pass
	02/14/2023 14:22	5	ROB Z	01/13	AIR	A: Return to service Notes:									
5	LAKEWOOD -180			LUXFER	5.4X18.4	DOTSP109154500	Pass	60	0	0.0	0.0	0.0	75.0	0.0	Not Tested
	N/A	5	ROB Z	01/13	AIR	H: Not Tested	Notes:								

Test System: 607-HP-148-P
 Test Machine Serial#:
 License: N066

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1622 Route 37 East
 , NJ 08753

Test ID	Cylinder Owner	Serial #	Mfg's ID	Size (D x L)	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pct Exp.	Test Result
12	LAKEWOOD -024	OK454505	LUXFER	5.4X18.4	DOTSP109164500	Pass	80	7554	65.8	3.6	62.2	99.0	5.5	Pass
	02/17/2023 09:32	5	ROB Z	09/12	AIR	A: Return to service Notes:								

Test System: 507-HP-14S-P
 Test Machine Serial#:
 License: N065

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1522 Route 37 East
 , NJ 08763

Test ID	Cylinder Owner	Serial #	Mfr's ID	Size (D x L)	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pct Exp.	Test Result
Test Date/Time	Retest Yrs	Operator	Mfg Date	Gas Svc	Disposition									
1	LAKEWOOD -044	OK488038	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7551	72.9	5.6	67.3	77.0	7.7	Pass
	02/24/2023 09:14	5	ROB Z	12/13	AIR	A: Return to service Notes:								
2	LAKEWOOD -157	OK482370	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7530	71.2	4.1	67.1	75.0	5.8	Pass
	02/24/2023 09:19	5	ROB Z	01/13	AIR	A: Return to service Notes:								
3	LAKEWOOD -025	OK488054	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7539	72.2	4.9	67.3	77.0	6.8	Pass
	02/24/2023 09:48	5	ROB Z	12/13	AIR	A: Return to service Notes:								
4	LAKEWOOD -028	OK488063	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7536	72.3	4.4	67.9	77.0	6.1	Pass
	02/24/2023 09:54	5	ROB Z	12/13	AIR	A: Return to service Notes:								
5	LAKEWOOD -184	OK488056	LUXFER	5.4X18.4	DOTSP109154500	Pass	60	7563	70.6	3.1	67.5	77.0	4.4	Pass
	02/24/2023 10:03	5	ROB Z	12/13	AIR	A: Return to service Notes:								

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
3/17/23	2019911

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department ATT: Chief Mulholland 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	H 110,112,114	
Quantity	Item Code	Description		Price Each	Amount
8	NJSC - Hydro	New Jersey State Contract 17-FLEET-00819 Vendor ID# 00000570. Hydro-Test of SCBA Cylinder, Including New Authorized Scott Valve O-Ring, Recharge Cylinder with Breathing Air, & Delivery.		30.60	244.80
		03/03/23 - 2			
		03/10/23 - 5			
		03/17/23 - 1			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$244.80	

Test System: 507-HP-143-P
 Test Machine Serial#: N065
 License: N065

Cylinder Retest Data Sheet

Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1522 Route 37 East
 NJ 08763

Test ID	Test Date/Time	Cylinder Owner	Retest Yrs	Operator	Serial #	Mfg Date	Mfg's ID	Size (D x L)	Disposition	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pct Exp.	Test Result
9	LAKEWOOD -080 03/03/2023 15:16	5	ROB Z	OK486050	12/13	AIR	LUXFER	5.4X18.4	DOTSP109154500	Notes:	Pass	60	7555	72.2	5.2	67.0	77.0	7.2	Pass
10	LAKEWOOD -080 03/03/2023 15:21	5	ROB Z	OK486355	12/13	AIR	LUXFER	5.4X18.4	DOTSP109154500	Notes:	Pass	60	7561	72.4	4.6	67.8	77.0	6.4	Pass

Test System: 507-HP-148-P
 Test Machine Serial#: NJ
 License: N065

Cylinder Retest Data Sheet Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
 1522 Route 37 East
 NJ 08753

Test ID	Cylinder Owner	Test Date/Time	Retest Yrs	Operator	Serial #	Mfg Data	Mfg's ID	Size (D x L)	Disposition	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE	Pct Exp.	Test Result
3	LAKWOOD -221	03/10/2023 11:56	5	ROB Z	OK462433	LUXFER	AIR	5.4X18.4	DOTSP109154500	Notes:	Pass	60	8030	78.3	6.3	72.0	75.0	8.0	Pass
					1/13			A. Return to service											
4	LAKWOOD -216	03/10/2023 12:02	5	ROB Z	OK456189	LUXFER	AIR	5.4X18.4	DOTSP109154500	Notes:	Pass	60	8022	79.1	6.4	72.7	75.0	8.1	Pass
					10/12			A. Return to service											
5	LAKWOOD -220	03/10/2023 12:07	5	ROB Z	OK462339	LUXFER	AIR	5.4X18.4	DOTSP109154500	Notes:	Pass	60	8021	77.8	5.6	72.2	75.0	7.2	Pass
					01/13			A. Return to service											
6	LAKWOOD -222	03/10/2023 12:13	5	ROB Z	OK456086	LUXFER	AIR	5.4X18.4	DOTSP109154500	Notes:	Pass	60	8014	78.7	5.2	73.5	75.0	6.6	Pass
					10/12			A. Return to service											
7	LAKWOOD -161	03/10/2023 12:18	5	ROB Z	OK486041	LUXFER	AIR	5.4X18.4	DOTSP109154500	Notes:	Pass	60	8024	78.5	5.8	72.7	77.0	7.4	Pass
					12/13			A. Return to service											

Test System: 507-HP-14S-P
Test Machine Serial#:
License: N065

Cylinder Retest Data Sheet
Hydrostatic Volumetric Test Method Report

NJ FIRE EQUIPMENT
1522 Route 37 East
NJ 08753

Test ID	Cylinder Owner	Serial #	Test Date/Time	Retest Yrs	Operator	Test Date	Mfg's ID	Size (D x L)	Disposition	Spec/Svc Press	Visual Insp.	Test Time	Actual Press	Total Exp.	Perm. Exp.	Elastic Exp.	REE Exp.	Pct Exp.	Test Result
1	LAKEWOOD - #219	OK455984	03/17/2023 08:54	5	ROB Z	10/12	LUXFER	5.4X18.4	DOTSP109154500	DOTSP109154500	Pass	60	8020	78.2	4.7	73.5	75.0	6.0	Pass
Notes: A: Return to service																			

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
5/17/23	70480

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department ATT: Chief Mulholland 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	5523	
Quantity	Item Code	Description		Price Each	Amount
1	31001150-02 NJSC - Scott P...	SCOTT Molded cable assy, SE7 New Jersey State Contract 17-FLEET-00819 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.		441.56	441.56
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		115s1309006038 pak 016 Constant alarm. troubleshot, found faulty molded cable, replaced cable, tested electronics			
Phone #		(732) 968-2121	Fax #	732-968-4724	Total
					\$531.56

119-131 Route 22 East
Green Brook, NJ 08812

Invoice

Date	Invoice #
5/23/23	2020734

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department ATT: Chief Mulholland 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.			Terms	Rep	F.O.B.	County	
			Net 30	RWZ	5551		
Quantity	Item Code	Description			Price Each	Amount	
1	31002582	SCOTT Demand Spring			2.78	2.78	
1	31002100	SCOTT "O" rings			3.88	3.88	
1	802210-01	SCOTT piston assy, demand valve			81.55	81.55	
	NJSC - Scott P...	New Jersey State Contract 17-FLEET-00819 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.					
2	Regulator Test ...	Flow Test of Regulator			35.00	70.00	
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.			90.00	90.00	
Phone #		(732) 968-2121	Fax #	732-968-4724	Total \$248.21		

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
7/27/23	2021371

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department ATT: Chief Mulholland 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	5762	
Quantity	Item Code	Description		Price Each	Amount
1	200674-02	SCOTT 4.5 remote Gauge		176.03	176.03
1	804427-01	SCOTT Waist belt - Male		82.55	82.55
1	36713-00	SCOTT valve seat		9.15	9.15
	NJSC - Scott P...	New Jersey State Contract 17-FLEET-00819 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		115s1309004969 pak 012 - Replaced leaking remote gauge and tested.			
		115s1246003700 pak E5 officer - Replaced female waist strap - frayed			
		Cylinder104 IL102929 Complaint: Hard to turn hand wheel. Found seat crushed from over tightening, replaced seat, filled and tested			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$357.73	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
10/24/23	2021656

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department ATT: Chief Mulholland 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
23-00670		Net 30	RWZ	5954	
Quantity	Item Code	Description		Price Each	Amount
77	Flow Test	Flow/POSI Test of Scott SCBA Unit, Including minor adjustments, batteries supplied and installed, custom SCBA test decal, & copy test record issued to end user. All work completed by NJFE/Scott Certified Technicians, utilizing all Scott Authorized Parts & Tools.		45.00	3,465.00
1	200674-02	SCOTT 4.5 remote Gauge		176.03	176.03
1	200455-02	SCOTT circuit board		88.52	88.52
3	Regulator Test ...	Flow Test of Regulator		35.00	105.00
1	200286-01	SCOTT valve seal kit		63.65	63.65
1	31002046	SCOTT Seat (COVERED UNDER WARRANTY)		0.00	0.00
1	200923-010	SCOTT "O" ring (COVERED UNDER WARRANTY)		0.00	0.00
		pak 025 115S1246003700 remote gauge			
		pak 015 115S1309004986 battery board			
		pak 040 115S1740015797 primary seat			
		~~WARRANTY			
		cyl IL1017340 Leaking from bonnet -bent			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$3,898.20	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
10/6/23	2022198

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	TRS 156	
Quantity	Item Code	Description		Price Each	Amount
1	37092-02 NJSC - Scott P...	SCOTT Bonnet (Good Used Part) New Jersey State Contract 17-FLEET-00819 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.		14.14	14.14
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		IL1017413 - Bent bonnett stem. Replaced bonnett with good used part.			
Phone #		(732) 968-2121	Fax #	732-968-4724	Total \$104.14

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
4/2/24	2024447

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	6962	
Quantity	Item Code	Description		Price Each	Amount
1	200951-03 NJSC - Scott P...	SCOTT Electrical connector kit for AP 75 New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.		66.63	66.63
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Pak 059 115s1304004980 Lights on HUD intermittent. Trouble shot, found pig tail wires shorted. Replaced Pigtail and tested HUD - Operational.			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$156.63	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
3/14/24	2024200

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	6821	
Quantity	Item Code	Description		Price Each	Amount
1	201134-01	SCOTT AV3000 HT lens		179.77	179.77
1	804425-02	SCOTT cyl strap assy, AP 75		85.53	85.53
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Face Piece 115s2018011019 - Damaged - Replaced cracked Lens			
		Pak 009 115R0000457509 - Replaced broken cylinder retainer strap.			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$355.30	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
4/25/24	2024733

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	7146	
Quantity	Item Code	Description		Price Each	Amount
1	200455-02	SCOTT circuit board		88.52	88.52
1	200449-02	SCOTT HUD hose std, AP 75		560.90	560.90
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Pak 008 115s1246003646 ALERT 220653 Replaced Low pressure hose - cracked with exposed wires, Checked electronics and leaks - ok			
		Pak 051 115s1309004973 ALERT 211067 Replaced torn waist pad with customer supplied pad.			
		Pak 050 115s13209006044 ALERT 221027 Electronics not functioning. Troubleshoot and found corroded PC board. Cleaned Battery housing, replaced PC board and tightened connections. Checked HUD and PASS alarm -ok			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$739.42	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
5/8/24	2024852

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	7201	
Quantity	Item Code	Description		Price Each	Amount
1	802919-01	SCOTT regulator body sub-assy		435.59	435.59
1	Flow Test	Flow/POSI Test of Scott SCBA Unit, Including minor adjustments, batteries supplied and installed, custom SCBA test decal, & copy test record issued to end user. All work completed by NJFE/Scott Certified Technicians, utilizing all Scott Authorized Parts & Tools.		45.00	45.00
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		PAK 014 115s1246010114 No Vibra Alert. Checked Pak. Initial Pressures: Air Saver Switch Activation Pressure = -4.9 "H2O - Pass Positive Pressure = 1.1 "H2O - Pass Primary Lockup = 90.7 PSI - Pass Primary Creep = 0.1 PSI - Pass Transfer = 1169 PSI - Pass Secondary Lockup = 168.9 PSI - Pass Secondary Creep = 1.1 PSI - Pass Vibra alert hanging up. Disassembled regulator. Replaced regulator body, Adjusted regulator purge and components, functional tested regulator. Operation = ok			
Phone #		(732) 968-2121	Fax #	732-968-4724	Total \$570.59

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
6/7/24	2025144

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	7357	
Quantity	Item Code	Description		Price Each	Amount
1	36713-00	SCOTT valve seat		9.15	9.15
1	804176-03	BAND ASSY, NECK		28.99	28.99
1	200450-03	SCOTT HUD hose QD 75		635.49	635.49
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Face Piece 100006615421 - Frayed neck strap. Replaced Neck strap Cylinder OK462478 - Handwheel over tightened, caused seat to crack. Replaced seat, filled and tested. Pak 043 115s1246003668 - Low pressure hose has exposed HUD wires. Replaced LP hose and tested Pak 063 115s13090006040 - Replaced EBSS pouch - torn			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$763.63	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
6/24/24	2025302

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	7435	
Quantity	Item Code	Description		Price Each	Amount
2	200951-01 NJSC - Scott P...	SCOTT Electrical connector kit, AP50 New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.		57.68	115.36
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Pak 010 115s1309004970 ALERT 225404 - Intermittent HUD. Troubleshoot and found HUD wires shorted. Replaced Pigtail and tested electronics Pak 019 115s1246003657 ALERT 225403 - Intermittent HUD. Troubleshoot and found HUD wires shorted. Replaced Pigtail and tested electronics			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$205.36	

119-131 Route 22 East
Green Brook, NJ 08812

Invoice

Date	Invoice #
11/5/24	2025324

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
24-00509		Net 30	RWZ	7514	
Quantity	Item Code	Description	Price Each	Amount	
78	Flow Test	Flow/POSI Test of Scott SCBA Unit, Including minor adjustments, batteries supplied and installed, custom SCBA test decal, & copy test record issued to end user. All work completed by NJFE/Scott Certified Technicians, utilizing all Scott Authorized Parts & Tools.	34.75	2,710.50	
2	Regulator Test ...	Flow Test of Regulator	25.00	50.00	
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$2,760.50	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
7/19/24	72952

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
24-00545		Net 30	RWZ		
Quantity	Item Code	Description		Price Each	Amount
1	NJSC - Scott	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570			0.00
7	201215-22	SCOTT AV3000 HT w/ Kevlar 4 strap harness (medium)		417.58	2,923.06
3	201215-23	SCOTT AV3000 HT w/ Kevlar 4 strap harness (large)		417.58	1,252.74
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$4,175.80	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
7/25/24	2025659

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	7662	
Quantity	Item Code	Description		Price Each	Amount
1	31002636	SCOTT Grill AV3000HT		8.59	8.59
1	201134-01	SCOTT AV3000 HT lens		179.77	179.77
1	10005368	SCOTT Regulator gasket		16.66	16.66
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Pak 017 115s1737019647 - Replaced torn regulator gasket. Face Piece - 100006615436 - Replaced damaged lens and exhalation grills.			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$295.02	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
8/1/24	2025761

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	7699	
Quantity	Item Code	Description		Price Each	Amount
1	802919-01	SCOTT regulator body sub-assy		435.59	435.59
1	10008734	SCOTT Purge body		57.68	57.68
2	10010666	SCOTT bearing (EZFLO purge body)		3.98	7.96
3	10010667	SCOTT "O" ring (EZFLO purge body)		3.98	11.94
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Regulator Test ...	Flow Test of Regulator		35.00	35.00
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Cylinder IL 1953403 - Replaced broken cylinder bumper Cylinder IL1028198 - ALERT # 228429 Replaced cylinder hanger bracket retaining screw. Pak 050 115s1309006044 - ALERT # 228068 - Complaint: Pak goes into full alarm. Troubleshoot, cleaned and tightened molded cable connections at sensor module and console Pak 042 115s1246003664 -ALERT # 228247 - Leak at regulator. Found leak at regulator body through vibra alert. Purge body and bearings worn. Rebuilt regulatory body and replaced purge body, bearings and packing. Flow tested regulator.			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$638.17	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
9/10/24	2026253

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	7922	
Quantity	Item Code	Description	Price Each	Amount	
1	200951-03	SCOTT Electrical connector kit for AP 75	66.63	66.63	
1	201134-01	SCOTT AV3000 HT lens	179.77	179.77	
1	200802-03	SCOTT AV3000 sure seal - Large	237.01	237.01	
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.		0.00	
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.	90.00	90.00	
		Pak 010 115s1309004970 - ALERT 231022 - No HUD troubleshoot, found hud wires shorted. Replaced pigtail and tested HUD. Facepiece 115s1635019784 - ALERT 230497 - Scratches on Lens.. Replaced Lens and sure seal. Cylinder 056 OK 486068 - ALERT 231325 - Complaint: lens dirty and bumper loose. Replaced bumper and lens. NC			
Phone #		(732) 968-2121	Fax #	732-968-4724	Total \$573.41

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
9/19/24	2026392

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	7981	
Quantity	Item Code	Description		Price Each	Amount
1	10008535	SCOTT Gauge retaining strap		8.56	8.56
1	10012602	SCOTT Display visor		9.50	9.50
1	200237-04	3M™ Scott™ Pouch EBSS, Flap, LH, Kombat (good used part)		60.92	60.92
1	200098-01	SCOTT shoulder pad/strap assy (good used part)		205.86	205.86
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Pak 064 115s1309006039 - ALERT 230519 - Console gauge retaining strap broken. Replaced strap.			
		Pak 066 115s1246003693 - ALERT 228023 - EBSS pouch ripped. Replaced w/ reconditioned EBSS pouch			
		Pak 052 115s1309004972 - ALERT 232281 - Shoulder harness torn. Replaced w/ reconditioned shoulder harness.			
		Pak 33 115s1246003691 - ALERT 232282 - Heads up display visor torn. replaced heads up display visor.			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$374.84	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
10/11/24	2026695

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	8098	
Quantity	Item Code	Description		Price Each	Amount
1	31002809	SCOTT Bezel, upper, AV3000 HT		12.26	12.26
1	201134-01	SCOTT AV3000 HT lens		179.77	179.77
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Face Piece 115s1738003371 - Neck strap frayed. Replaced neck strap.			
		Face Piece 115f0000025711 - Lens has a deep scrape and broken upper bezel. Replaced lens and upper bezel.			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$282.03	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
11/13/24	2026972

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	7514	
Quantity	Item Code	Description	Price Each	Amount	
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.		0.00	
3	200923-010	SCOTT "O" ring	4.00	12.00	
3	31002096	SCOTT "O" ring	4.00	12.00	
4	200951-03	SCOTT Electrical connector kit for AP 75	68.63	274.52	
2	200455-02	SCOTT circuit board	91.17	182.34	
1	200449-01	SCOTT Regulator hose, GQ	489.64	489.64	
5	200674-02	SCOTT 4.5 remote Gauge	181.31	906.55	
4	200450-03	SCOTT HUD hose QD 75	654.55	2,618.20	
1	31000397	SCOTT Pressure transducer	317.55	317.55	
2	804426-01	SCOTT Waist belt - female (good used part)	45.00	90.00	
1	802919-01	SCOTT regulator body sub-assy	448.66	448.66	
1	10005269	SCOTT tab lock plate	6.71	6.71	
1	10007874	SCOTT retainer body plate	4.00	4.00	
3	10010667	SCOTT "O" ring (EZFLO purge body)	4.10	12.30	
2	10010666	SCOTT bearing (EZFLO purge body)	4.10	8.20	
1	10008734	SCOTT Purge body	59.41	59.41	
1	802210-01	SCOTT piston assy, demand valve	84.00	84.00	
Phone #		(732) 968-2121	Fax #	732-968-4724	
			Total		

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
11/13/24	2026972

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.			Terms	Rep	F.O.B.	County	
			Net 30	RWZ	7514		
Quantity	Item Code	Description				Price Each	Amount
		Pak 050115S1309006044 - Primary seat pak 055 115S1309004968 - Pigtail pak 080 115S1246003698 - Primary seat pak 010 115S1309004970 - Secondary seat Pak 003 115S1246003641 - Battery board Pak 050 115S1309006044 - Battery board Pak 026 115S1246003643 - Replaced gauge 115s1246010089/001 - REPLACED REMOTE GAUGE—REPLACED LP HOSE FEMALE—REPLACED FEMALE WAIST BUCKLE/GOOD USED, (NEEDS EBSS POUCH) 115S1309006036/030 - REPLACED FEMALE WAIST BUCKLE(GOOD USED) 115s1246003691/033 - REPLACED PIGTAIL 115s1740015801/007 - NEEDS EBSS POUCH 115S1246010082/013 - REPLACED REMOTE GAUGE—REPLACED TRANSDUCER—NEEDS EBSS POUCH 115s1246003705/077 - REPLACED PIGTAIL 115S1309004969/012 - REPLACED PIGTAIL 115s1422007972/006 - REPLACED REMOTE GAUGE 115s1246010088/021 - NEEEDS EBSS POUCH—REPLACED REMOTE GAUGE 115s1246010114/014 - REPLACED LP HOSE FEMALE 115s1246015386/043 - REPLACED LP HOSE MALE 115s1308016555/063 - REBUILT REGULATOR 115s1246015636/060 - REPLACED LP HOSE FEMALE					
Phone #		(732) 968-2121	Fax #		732-968-4724	Total \$5,526.08	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
12/12/24	2027524

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	8570	
Quantity	Item Code	Description		Price Each	Amount
1	Flow Test	Flow/POSI Test of Scott SCBA Unit, Including minor adjustments, batteries supplied and installed, custom SCBA test decal, & copy test record issued to end user. All work completed by NJFE/Scott Certified Technicians, utilizing all Scott Authorized Parts & Tools.		34.75	34.75
1	36713-00	SCOTT valve seat		9.43	9.43
1	200455-02	SCOTT circuit board		91.17	91.17
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		ALERT 238481 - Cylinder 123 OK454624 Hard to Open under pressure. Disassembled valve found seat and plug damaged. Replaced seat , filled and tested. ALERT 238480 - Pak 70 115s1309004971 - Battery Board corroded from leaking batteries. Cleaned battery housing and cover, replaced PC board and batteries and tested electronics. Pak 029 - No Alert # - 115S1309006037 - Needed flow testing			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$225.35	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
12/31/24	2027703

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	8650	
Quantity	Item Code	Description		Price Each	Amount
1	10005368	SCOTT Regulator gasket		17.16	17.16
1	36713-00	SCOTT valve seat		9.43	9.43
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Pak 021 115S1246010088 - ALERT 240409 - Replaced damaged regulator gasket			
		Pak 071 115S1309004945 - ALERT 240115 - Inspected pak. regulator functioning and operational, within specifications.			
		Cylinder 162 OK486072 - ALERT 240117 - Damaged threads. Filed,tapped and chased threads. CGA fitting now is working.			
		Cyl 107 OK1028387 - ALERT 240591 - Cylinder hard to operate. Replaced worn seat and plug, filled and tested.			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$116.59	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
1/30/25	2028105

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	8865	
Quantity	Item Code	Description		Price Each	Amount
1	201134-01	SCOTT AV3000 HT lens		185.16	185.16
1	802919-01	SCOTT regulator body sub-assy		448.66	448.66
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Regulator Test ...	Flow Test of Regulator		25.00	25.00
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		ALERT 243099 Pak 039 115S1309004946 - No vibra alert, troubleshot pak found faulty vibra alert in regulator. Disassembled regulator, replaced regulator body, reassembled, adjusted interior components, reassembled regulator and flow tested.			
		ALERT 242734 - Face piece - 115S1943007220 - Lens damaged/scratches - Replaced lens			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$748.82	

119-131 Route 22 East
Green Brook, NJ 08812

Invoice

Date	Invoice #
7/16/25	2030168

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	10010	
Quantity	Item Code	Description	Price Each	Amount	
12	Hydro-test	Hydro-Test of SCBA Cylinder, Including New Authorized Scott Valve O-Ring, Recharge Cylinder with Breathing Air, & Delivery.	30.60	367.20	
Phone #		(732) 968-2121	Fax #	732-968-4724	Total \$367.20

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
7/30/25	2030335

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	10130	
Quantity	Item Code	Description		Price Each	Amount
1	200450-01 NJSC - Scott P...	SCOTT assy hose, HUD socket QD New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.		617.68	617.68
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		** ALERT 264876 ** Pak67 115R0000457507 - Torn LP QD Female. Disassembled, replaced. Tested.			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$707.68	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
2/11/25	2028240

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	8993	
Quantity	Item Code	Description		Price Each	Amount
2	37092-02	SCOTT Bonnet		29.12	58.24
3	36713-00	SCOTT valve seat		9.43	28.29
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Cylinder 008 IL1018145 - ALERT 246101 - Complaint: Cylinder hard to turn. Disassembled cylinder valve found cylinder bonnet shaft bent. Replaced bonnet and seat/plug assembly. Reassembled cylinder valve, filled and tested.			
		Cylinder 106 - IL1027070 - ALERT 245769 - Valve is difficult to open/close. Disassembled cylinder valve Seat was crushed and shaft bent. Replaced bonnet and seat assembly. Reassembled cylinder valve, filled and tested.			
		Cylinder 90 - IL1953406 - ALERT 246137 - Complaint Leaking from valve. Filled cylinder, unable to shut off cylinder. Disassembled cylinder valve. Found seat damaged from overtightening the hand wheel. Replaced seat and plug assembly. Reassembled cylinder valve, filled and tested.			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$176.53	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
4/1/25	2028890

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	9264	
Quantity	Item Code	Description		Price Each	Amount
1	200674-02	SCOTT 4.5 remote Gauge		181.31	181.31
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Pak 39 115s1309004946 - ALERT 249318 - Complaint: leak at regulator. Disassembled regulator and found leak at purge stem. Adjusted purge stem pressure and tested. Pak 28 115s1422007961 - ALERT 249257 - Complaint leak at gauge. Found leaking remote gauge. Replaced remote gauge and tested. Pak 002 115S1422012651 - ALERT 250248 - Complaint leak at regulator. Tightened lock plate and lock pad retaining screw.			
Phone #		(732) 968-2121	Fax #	732-968-4724	Total \$271.31

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
4/3/25	2028941

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	9325	
Quantity	Item Code	Description		Price Each	Amount
1	Hydro-test	Hydro-Test of SCBA Cylinder, Including New Authorized Scott Valve O-Ring, Recharge Cylinder with Breathing Air, & Delivery.		30.60	30.60
		OK462353			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$30.60	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
4/29/25	74790

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County	
25-00341		Net 30	RWZ	Delivered		
Quantity	Item Code	Description		Price Each	Amount	
1	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570.			0.00	
6	201215-22	SCOTT AV3000 HT w/ Kevlar 4 strap harness (medium)		430.11	2,580.66	
Phone #		(732) 968-2121	Fax #	732-968-4724	Total	
						\$2,580.66

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
6/3/25	2029674

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	9372 & 9846	
Quantity	Item Code	Description		Price Each	Amount
1	10007881	SCOTT Retaining ring - EZ-FLO diaphragm		9.79	9.79
1	802919-01	SCOTT regulator body sub-assy		448.66	448.66
1	200270-02	SCOTT gaugeline assy, NxG7		143.41	143.41
1	10012602	SCOTT Display visor		9.79	9.79
1	200674-02	SCOTT 4.5 remote Gauge		181.31	181.31
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
2	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	180.00
		ALERT# 250502 - 03/28/25 Customer states the regulator 115S1309004945 for pak 071 is leaking out of the regulator. Found a cracked retaining cover, and a leak in the regulator housing. Replaced retaining cover, and regulator body assy. Flow tested and passed.			
		Alert#258192 - 05/30/25 Customer states Pak#20 115S1308007459 has a torn HUD LED rubber cover. Inspected, found rubber display visor torn. Disassembled regulator, took off torn rubber display visor, replaced new one. Reassembled regulator.			
		Alert#258543 - 05/30/25 Customer states Pak#71 is leaking from gauge. Put Pak to air, heard air leak. Disassembled gauge, found air leaking from the gauge assembly, and the gauge line. Disassembled parts, replaced gauge, gauge line. Reassembled, Tested.			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$972.96	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
6/3/25	2029671

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	9801	
Quantity	Item Code	Description		Price Each	Amount
1	200803-01	F,5-ST KEV HH, AV-3000 SS/HT		219.29	219.29
1	200827-04	SCOTT Console top cover, 4.5 (good used part)		399.79	399.79
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Alert# 255916 Customer states that Pak#66 115S1246003693 is leaking from the gauge. Put Pak to air, air leaking from gauge. No LED lights on HUD. Disassembled gauge, Found air leaking from transducer and broken connection on transducer wire. Replaced with good used top cover. Tested, no leak found.			
		Alert#256672 Customer states Cylinder IL1953425 is leaking when under pressure. Disassembled Bumper and sight glass cover on gauge. Sprayed with Leak Detector. Submerged cylinder in water, No air leaks found. Reassembled sight glass cover and Bumper. Tested cylinder on Pak, No leak detected.			
		Customer states Facemask Straps are frayed and stretched. Inspected, found four straps frayed and stretched out. Disassembled AV3000 net and replaced with new AV3000 net.			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$709.08	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
6/17/25	2029866

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	9925	
Quantity	Item Code	Description		Price Each	Amount
1	200450-03 NJSC - Scott P...	SCOTT HUD hose QD 75 New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.		654.55	654.55
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Alert# 260111			
		Pak75 115S1309004968 - HUD not showing Green LED lights when pak is on and cylinder is full. Tested on HUD tester, and found Low Pressure QD hose is bad. Disassembled hose, replaced new hose. Tested.			
Phone #		(732) 968-2121	Fax #	732-968-4724	Total \$744.55

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
7/3/25	2030060

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	9997	
Quantity	Item Code	Description		Price Each	Amount
1	200237-04	3M™ Scott™ Pouch EBSS, Flap, LH, Kombat		250.97	250.97
1	804471-01	SCOTT Waist pad assy		396.42	396.42
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Alert# 260879 - Pak15 115S1309004986 Loud pitch sound when Pak is on. Put Pak to air, no loud pitch sound. Checked molded cable wires, loose connections. Tightened connections. Tested.			
		Alert# 260701 - Pak 1 115S1246010089 Ripped fabric on back harness, and EBSS pouch. Replaced with new parts.			
Phone #		(732) 968-2121	Fax #	732-968-4724	Total \$737.39

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
8/8/25	2030449

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	10173 & 10216	
Quantity	Item Code	Description		Price Each	Amount
1	200455-02 NJSC - Scott P...	SCOTT circuit board New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.		91.17	91.17
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools. Pak 009 1156r0000457909 - High pitched noise, No Hud. Troubleshoot and found defective PC board, replaced PC board, cleaned and tightened molded cable connections and tested electronics - all operational		90.00	90.00
2	Hydro-test	Hydro-Test of SCBA Cylinder, Including New Authorized Scott Valve O-Ring, Recharge Cylinder with Breathing Air, & Delivery.		30.60	61.20
Phone #		(732) 968-2121	Fax #	732-968-4724	Total \$242.37

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
8/26/25	2030668

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	10281 & 10263	
Quantity	Item Code	Description		Price Each	Amount
1	200450-03	SCOTT HUD hose QD 75		654.55	654.55
1	200098-01	SCOTT shoulder pad/strap assy		848.15	848.15
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Alert#267411 Pak 63 115S1309006040 -Swapped regulators with customer supplied regulator and regulator flow test.			
		Alert#267951 Pak 28 115S1422007961 HUD intermittently working. Inspected Pak and found that the pigtail was bad. Inspected the LP QD hose and found it is torn and showing HUD wires. Replaced LP QD hose. Tested.			
		Alert#259585 Pak#31 115S1246010086 has torn shoulder strap. Disassembled strap and replaced with new shoulder straps.			
2	Hydro-test	Hydro-Test of SCBA Cylinder, Including New Authorized Scott Valve O-Ring, Recharge Cylinder with Breathing Air, & Delivery.		30.60	61.20
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$1,653.90	

**New Jersey Fire Equipment Co.**

119-131 Route 22 East
Green Brook, NJ 08812

Invoice

Date	Invoice #
11/25/25	2030427

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
25-00662		Net 30	RWZ	10217	
Quantity	Item Code	Description		Price Each	Amount
78	Flow Test	Flow/POSI Test of Scott SCBA Unit, Including minor adjustments, batteries supplied and installed, custom SCBA test decal, & copy test record issued to end user. All work completed by NJFE/Scott Certified Technicians, utilizing all Scott Authorized Parts & Tools.		35.00	2,730.00
Phone #		(732) 968-2121	Fax #	732-968-4724	Total \$2,730.00

119-131 Route 22 East
Green Brook, NJ 08812

Invoice

Date	Invoice #
11/25/25	2031940

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	10217	
Quantity	Item Code	Description	Price Each	Amount	
		REPAIRS OUT OF WARRANTY DURING 2025			
		ANNUAL FLOW TEST			
10	200674-02	SCOTT 4.5 remote Gauge	181.31	1,813.10	
2	31002046	SCOTT Seat	40.00	80.00	
2	200923-010	SCOTT "O" ring	4.00	8.00	
2	200951-03	SCOTT Electrical connector kit for AP 75	68.63	137.26	
2	200449-01	SCOTT Regulator hose, GQ	489.64	979.28	
1	200923-013	SCOTT "O" ring	4.00	4.00	
1	802919-01	SCOTT regulator body sub-assy	448.66	448.66	
1	201140-02	SCOTT 2013 gauge 4.5	181.31	181.31	
1	200827-04	SCOTT Console top cover, 4.5	799.58	799.58	
1	31001150-02	SCOTT Molded cable assy, SE7	454.81	454.81	
2	Regulator Test ...	Flow Test of Regulator	25.00	50.00	
1	804110-03	SCOTT Regulator Cover - CBRN (WARRANTY)	0.00	0.00	
Phone #		(732) 968-2121	Fax #	732-968-4724	Total

**New Jersey Fire Equipment Co.**

119-131 Route 22 East
Green Brook, NJ 08812

Invoice

Date	Invoice #
11/25/25	2031940

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County	
		Net 30	RWZ	10217		
Quantity	Item Code	Description			Price Each	Amount
		Pak008 115S1246003646 - New gauge Pak023 115S1309000478 - New gauge Pak 027 115S1246010081 - New gauge Pak039 115S1309004946 - New gauge Pak 018 115S1309004943 - Pigtail Pak 007 115S1740015801 - Regulator cover (warranty) Pak 021 115S1246010088 - Leaking UAC O-Ring and Regulator cover Pak 070 115S1309004971 - New gauge Pak 058 115S1308007505 - New gauge Pak 025 115S1246003700 - New piigtail Pak 040 115S1740015797 - New gauge Pak 067 115R0000457507 - New gauge Pak 047 115S1246003659 - Secondary seat pak 015 115S1309004986 - Gauge Pak 013 115s1246010082 - LP Hose Pak 017 115S1737019647 - LP Hose Pak 024 115S1246010084 - Gauge Pak 030 115s0900 - Gauge / seat retainer oring Pak 059 115S1309004945 - Primary seat Pak 012 115s1246015044 - Top console/ molded cable shorted				
Phone #		(732) 968-2121	Fax #	732-968-4724	Total \$4,956.00	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
9/11/25	2030879

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	10419	
Quantity	Item Code	Description		Price Each	Amount
1	804176-03	BAND ASSY, NECK		29.86	29.86
1	804176-01	SCOTT Kevlar neck strap		31.24	31.24
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Alert#268344 Face piece straps are frayed. Disassembled old straps, replaced with new.			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$151.10	

**New Jersey Fire Equipment Co.**

119-131 Route 22 East
Green Brook, NJ 08812

Invoice

Date	Invoice #
9/24/25	2031035

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	10491	
Quantity	Item Code	Description		Price Each	Amount
3	Hydro-test	Hydro-Test of SCBA Cylinder, Including New Authorized Scott Valve O-Ring, Recharge Cylinder with Breathing Air, & Delivery.		30.60	91.80
Phone #		(732) 968-2121	Fax #	732-968-4724	Total
					\$91.80

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
12/18/25	2032273

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	11112 & 11195	
Quantity	Item Code	Description		Price Each	Amount
1	802919-01 NJSC - Scott P...	PACK REPAIR 12/16/25 SCOTT regulator body sub-assy New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.		448.66	448.66
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools. Alert#279651 Pak 042115S1246003664 Customer states the VibraAlert was not working with low pressure air. Put Pak to air and no VibraAlert activation when Pak was turned on. Performed regulator flow test and no VibraAlert activated during flow test. Disassembled regulator and all internal components and replaced with new regulator body. Performed regulator flow test and passed. VibraAlert is working.		90.00	90.00
3	Hydro-test	Hydro - 12/10/25 Hydro-Test of SCBA Cylinder, Including New Authorized Scott Valve O-Ring, Recharge Cylinder with Breathing Air, & Delivery.		30.60	91.80
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$630.46	

119-131 Route 22 East
Green Brook, NJ 08812

Invoice

Date	Invoice #
12/18/25	2032272

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	11068 & 11125	
Quantity	Item Code	Description	Price Each	Amount	
2	10010666	SCOTT bearing (EZFLO purge body)	4.10	8.20	
3	10010667	SCOTT "O" ring (EZFLO purge body)	4.10	12.30	
2	10012602	SCOTT Display visor	9.79	19.58	
1	802919-01	SCOTT regulator body sub-assy	448.66	448.66	
2	201134-01	SCOTT AV3000 HT lens	185.16	370.32	
2	Regulator Test ...	Flow Test of Regulator	0.00	0.00	
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
2	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.	90.00	180.00	
Phone #		(732) 968-2121	Fax #	732-968-4724	Total

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
12/18/25	2032272

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County	
		Net 30	RWZ	11068 & 11125		
Quantity	Item Code	Description			Price Each	Amount
		115S1309004972 - Replaced defective purge valve body orings and hud cover 115S 1246003664 - Replaced defective hud cover Alert#279477 Pak 029 has a regulator that is leaking air. Put the regulator to air and it has air leaking. Tried to tighten the set screw and found the hole is stripped. Needs new regulator body. Disassembled regulator and rebuilt new regulator body. Performed Regulator flow test. Aler#279128 Pak 17 115S1737019647 customer states Pak is leaking where regulator and LP hose meet. Put Pak to air and heard air leaking. Tightened set screw to regulator and hose and air leak stopped. Tested. Alert#278891 Mask 115S154F979987 mask was scratched and made visibility difficult. Disassembled old mask lense and replaced with new. Reassembled. Alert#279135 Mask 115S1938002992 has a gouge in the mask. Disassembled bad lense and replaced with new. Reassembled mask seal and mouth piece.				
Phone #		(732) 968-2121	Fax #	732-968-4724	Total \$1,039.06	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
11/19/25	2031872

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	10934 & 10987	
Quantity	Item Code	Description		Price Each	Amount
2	36713-00	CYLINDER REPAIR - 11/10/25			
1	37093-02	SCOTT valve seat		9.43	18.86
	NJSC - Scott P...	SCOTT Stem, Valve KB		22.13	22.13
		New Jersey State Contract 24-FLEET-61850			
		Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		Cyl 23 IL1017929 - ALERT 275174 - Valve difficult to turn, disassembled valve found valve stem bent, replaced post and seat/plug assy. Reassembled valve, filled and tested.			
		Cyl OK455385 - ALERT 274089 - Will not fill. Disassembled valve and found seat crushed from overtightening the hand wheel. Replaced seat and plug assy. Reassembled valve, filled and tested.			
1	802919-01	PAK REPAIR - 11/17/25			
1	10008734	SCOTT regulator body sub-assy		448.66	448.66
2	10010666	SCOTT Purge body		59.41	59.41
3	10010667	SCOTT bearing (EZFLO purge body)		4.10	8.20
	NJSC - Scott P...	SCOTT "O" ring (EZFLO purge body)		4.10	12.30
		New Jersey State Contract 24-FLEET-61850			
		Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
Phone #		(732) 968-2121	Fax #	732-968-4724	Total

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
11/19/25	2031872

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	10934 & 10987	
Quantity	Item Code	Description		Price Each	Amount
		Pak 012 115S1309004969 - ALERT 276653 - Complaint: Leak at regulator. Disassembled regulator and found an extensive leak inside the demand piston. Replaced the regulator body, cleaned demand piston and rebuilt the purge body, packing and orings. reassembled regulator and flow tested regulator. Pak 069 115S1309000477 - ALERT 276035 - Complaint, Air saver switch opens when the regulator is hit. Checked regulator- operational. Normal operation for regulator to open when popped on the pre 2013 regulator.			
Phone #		(732) 968-2121	Fax #	732-968-4724	Total
					\$749.56

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
1/14/26	2032541

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	11308	
Quantity	Item Code	Description		Price Each	Amount
		PAK REPAIR - 01/07/26			
1	31002046	SCOTT Seat		40.00	40.00
1	200923-010	SCOTT "O" ring		4.00	4.00
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Flow Test	Flow/POSI Test of Scott SCBA Unit, Including minor adjustments, batteries supplied and installed, custom SCBA test decal, & copy test record issued to end user. All work completed by NJFE/Scott Certified Technicians, utilizing all Scott Authorized Parts & Tools.		35.00	35.00
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools. Alert# 282242 Pak 070 115S1309004971 Customer states regulator has no Vibra Alert. Put Pak to air and vibra alert activated. Performed a Breathing test on the Pak and found that it needed a new Primary seat. Replaced seat and performed Flow test.		90.00	90.00
2	Hydro-test	Hydro-Test of SCBA Cylinder, Including New Authorized Scott Valve O-Ring, Recharge Cylinder with Breathing Air, & Delivery. Alert# 281547 Alert# 281546		30.60	61.20
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$230.20	

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
1/22/26	2032644

Bill To
Lakewood Fire District #1 733 Cedar Bridge Avenue Lakewood, NJ 08701

Ship To
Lakewood Fire Department Fire Headquarters 733 Cedar Bridge Avenue Lakewood, NJ 08701

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RWZ	11381	
Quantity	Item Code	Description		Price Each	Amount
1	37092-02	SCOTT Bonnet		29.12	29.12
1	37093-02	SCOTT Stem, Valve KB		22.13	22.13
1	36713-00	SCOTT valve seat		9.72	9.72
	NJSC - Scott P...	New Jersey State Contract 24-FLEET-61850 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		95.00	95.00
		Cylinder IL1953400 customer states valve will not turn open. Disassembled hand wheel valve and bonnet. Found crushed seat due to over tightening valve, bent stem. Replaced bonnet, stem and seat. Reassembled hand wheel, filled cylinder, and tested.			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$155.97	



66 Firemens way
Poughkeepsie NY 12603
United States

Invoice

Page 1 of 2

Date 03/12/2020

Invoice # IN1436632

Terms Net 30

Due Date 04/11/2020

Customer # C40356

PO #

Sales Rep Sexton, Robert P

Order Sales Order #SO1350816

Bill To

LAKEWOOD FIRE DISTRICT #1
316 RIVER AVENUE
Lakewood NJ 08701

Ship To

C40356 LAKEWOOD FIRE DISTRICT #1
316 RIVER AVENUE
Lakewood NJ 08701
United States

Item	Description	QTY	Units	Back Ordered	Unit Price	Amount
SCBA Repair	SCBA Repair	1		0	0.00	0.00
EN91-AA	ENERGIZER INDUSTRIAL ALK AA (sold by each)	6		0	0.58	3.48
31001277	POST, BATTERY HOUSING, 2007	1		0	6.70	6.70
Electronics Repair	Electronics Repair	1		0	85.00	85.00
200455-02	BATTERY PCB ASSY, 2007 SENSOR	1		0	76.20	76.20
31001539	BATTERY SEPARATOR,SENSOR 2007	1		0	9.30	9.30
SCBA Repair	SCBA Repair	1		0	0.00	0.00
Regulator Repair - Minor	Minor Regulator Repair	1		0	42.50	42.50
200063-01	DIAPHRAGM & VALVE ASSY,EZ FLO+	1		0	251.00	251.00
SCBA Flow Test	SCBA Flow Test	1		0	36.00	36.00



IN1436632

	Subtotal	510.18
Shipping Cost (MES Delivery)	0.00	
	Total	510.18
	Amount Due	\$510.18

IN1436632



MUNICIPAL EMERGENCY SERVICES

66 Firemens way
Poughkeepsie NY 12603
United States

Invoice

Date 04/17/2020
Invoice # IN1448525
Terms Net 30
Due Date 05/17/2020
Customer # C40356
PO #
Sales Rep Sexton, Robert P
Order Sales Order #SO1362434

Bill To
LAKEWOOD FIRE DISTRICT #1
316 RIVER AVENUE
Lakewood NJ 08701

Ship To
C40356 LAKEWOOD FIRE DISTRICT #1
316 RIVER AVENUE
Lakewood NJ 08701
United States

Item	Description	QTY	Units	Back Ordered	Unit Price	Amount
SCBA Repair	SCBA Repair	1		0	0.00	0.00
Cylinder Valve Repair	Cylinder Valve Repair	1		0	42.50	42.50
804098-01	VALVE ASSY, CYLINDER 4.5	1		0	501.00	501.00
CO5125	THREAD SAVERS RED	1		0	4.50	4.50
33324-041	SCREW PAN HD .164 X .250	1		0	2.30	2.30

Subtotal 550.30
Shipping Cost (MES Delivery) 0.00
Total 550.30
Amount Due \$550.30

Repairs made to cylinder with damaged threads. Per Steve Mulhalend

All returns must be processed within 30 days of receipt and require a return authorization number and are subject to a restocking fee.

All payments must be clearly marked with the Customer and Invoice numbers. Payments not marked will be applied to the oldest invoice first.

Wire/ ACH:
Routing#: 121000248
Acct#: 2000030294606
Bank Name: Wells Fargo Bank, N.A.

Wire/ ACH Remittance Advice: AR@MESFIRE.COM
Please include Customer# and Invoice#

Please call us for invoice questions:
1-877-MES-FIRE (1-877-637-3473)

Remittance Slip

Customer C40356 LAKEWOOD FIRE DIST...
Invoice # IN1448525
Amount Due \$550.30
Amount Paid

Make Checks Payable To
Municipal Emergency Services Depository Account
75 Remittance Drive
Suite 3135
Chicago, IL 60675



IN1448525



66 Firemens way
Poughkeepsie NY 12603
United States

Invoice

Date 09/16/2020
Invoice # IN1498611
Terms Net 30
Due Date 10/16/2020
Customer # C40356
PO # 20-0447
Sales Rep Watson, Frank
Order Sales Order #SO1386454

Bill To
LAKEWOOD FIRE DISTRICT #1
316 RIVER AVENUE
Lakewood NJ 08701

Ship To
Yehuda Beer
LAKEWOOD FIRE DISTRICT #1
316 RIVER AVE
Lakewood NJ 08701
United States

Item	Description	QTY	Units	Back Ordered	Unit Price	Amount
201215-02	AV-3000 HT (M), KVL R	5		0	309.33	1,546.65

SCOTT Contract #: 17-FLEET-00819

Thank You

Subtotal 1,546.65
Shipping Cost (FedEx Ground) 0.00
Total 1,546.65
Amount Due \$1,546.65

All returns must be processed within 30 days of receipt and require a return authorization number and are subject to a restocking fee.

All payments must be clearly marked with the Customer and Invoice numbers. Payments not marked will be applied to the oldest invoice first.

Wire/ ACH:
Routing#: 121000248
Acct#: 2000030294606
Bank Name: Wells Fargo Bank, N.A.

Wire/ ACH Remittance Advice: AR@MESFIRE.COM
Please include Customer# and Invoice#

Please call us for invoice questions:
1-877-MES-FIRE (1-877-637-3473)

Remittance Slip

Customer C40356 LAKEWOOD FIRE DIST..
Invoice # IN1498611
Amount Due \$1,546.65
Amount Paid _____

Make Checks Payable To
Municipal Emergency Services Depository Account
75 Remittance Drive
Suite 3135
Chicago, IL 60675



IN1498611



Order Date	07/15/2020
Order #	SO1386454
Acct. No.	C40356
Ship Date	09/16/2020
Tracking #	
Ship Via	FedEx Ground
PO #	20-0447
Shipment #	IF1656919
Customer	LAKEWOOD FIRE DIS...
Vendor's RMA Number	
Notes	

Yehuda Beer
LAKEWOOD FIRE DISTRICT #1
316 RIVER AVE
Lakewood NJ 08701
United States

SCOTT Contract #: 17-FLEET-00819

