

**New Jersey Fire Equipment Co.**119-131 Route 22 East
Green Brook, NJ 08812**Invoice**

Date	Invoice #
5/1/23	2020431

Bill ToTinton Falls Fire District #2
PO Box 443
695 Tinton Avenue
Tinton Falls, NJ 07753**Ship To**Tinton Falls Fire Company #1
695 Tinton Avenue
Tinton Falls, NJ 07753

Customer P.O.		Terms	Rep	F.O.B.	County
		Net 30	RZ	5396	
Quantity	Item Code	Description		Price Each	Amount
1	200449-02	SCOTT HUD hose std, AP 75		560.90	560.90
	NJSC - Scott P...	New Jersey State Contract 17-FLEET-00819 Vendor ID# 00000570. All SCOTT parts are in compliance with NJSC pricing.			
1	Labor Rate	Repairs completed by NJFE Scott Certified Technicians, utilizing Scott Authorized Parts & Tools.		90.00	90.00
		115S1247008153 pak#1-07 Found HUD housing damaged / broken off bracket on Low Pressure Hose . Also found Low Pressure hose cracked with exposed HUD wires at reduced end. - Replaced LP Hose, reassembled regulator and tested functionality			
Phone #		(732) 968-2121	Fax #	732-968-4724	
Total				\$650.90	