



Wall Township, NJ 07753

Bill To: OAKLA-01-017
OAKLAND PUBLIC SCHOOLS
315 RAMAPO VALLEY ROAD
OAKLAND, NJ. 07436-1896

Ship To: 33084
Oakland BOE - Valley School
71 Oak Street
Oakland, NJ. 07436

Invoice Date	Customer PO	Payment Terms	Reference #	Workorder #
05/27/2020	20-01418	Due Upon Receipt	OAKLA-01-017	3672009

Item ID	Description	Service Date	Hrs/Qty	Unit Price	Ext. Price
	Quoted Work Order	05/26/2020	1.00	610.00	610.00

Summary of Work Performed

Job Scope

Programming/Replacing a heat detector, additionally checking the batteries to investigate the trouble that appeared on the panel regarding low battery. Location of the heat detector is in the boys locker room shower

Work Summary

5/26/2020. BC

Arrived and found panel showing trouble for "Boys locker room Shower" (internal trouble).

Located heat detector and replaced device.

Downloaded to panel after replacing and tested, ok. Heat detector reported to FACP correctly.

System normal upon Departure.

Oakland Board of Ed

JUN 09 2020

Business Office

[Handwritten signature]
6-12-20

Sales Total	\$610.00
Tax Total	\$0.00
Net Amount	\$610.00

A FINANCE CHARGE WILL BE ADDED TO PAST DUE ACCOUNTS AT THE RATE OF ONE AND ONE-HALF PERCENT (1.5%) PER MONTH, OR AT THE HIGHEST LEGAL RATE, WHICHEVER IS LESS.

Remit To: PO Box 530212, Atlanta, GA 30353-0212

Phone: 877-387-0180 Fax: 713-353-3311

Wall Township, NJ 07753


Bill To: OAKLA-01-017
OAKLAND PUBLIC SCHOOLS
315 RAMAPO VALLEY ROAD
OAKLAND, NJ. 07436-1896

Ship To: 33083
Oakland BOE - Manito School
111 Manito Avenue
Oakland, NJ. 07436

Invoice Date	Customer PO	Payment Terms	Reference #	Workorder #
06/03/2020	20-01430	Due Upon Receipt	OAKLA-01-017	3674089

Item ID	Description	Service Date	Hrs/Qty	Unit Price	Ext. Price
	Quoted Work Order	06/01/2020	1.00	660.00	660.00

Summary of Work Performed	
Job Scope	Replacing a combo(Smoke/Heat) detector by the first floor library
Oakland Board of Ed JUN 09 2020 Business Office	
Work Summary	6/2/20 MK I arrived on site and found that the hallway device at address 1:3:43 by the library had an internal trouble. I replaced the SIGA-IPHS device with a newer model SIGA-PHD and changed its type in the database. While programming, the exit 4 device at address 1:3:57 came up as a unconfigured, I corrected it and tested it after programming and it functioned as expected. I also tested the new device at address 1:3:43 and it also functioned as expected. Left system normal upon departure. No customer signature available due to preventive measures for the COVID- 19.



Sales Total	\$660.00
Tax Total	\$0.00
Net Amount	\$660.00

A FINANCE CHARGE WILL BE ADDED TO PAST DUE ACCOUNTS AT THE RATE OF ONE AND ONE-HALF PERCENT (1.5%) PER MONTH, OR AT THE HIGHEST LEGAL RATE, WHICHEVER IS LESS.

Remit To: PO Box 530212, Atlanta, GA 30353-0212

Phone: 877-387-0180 Fax: 713-353-3311