

Invoice 202301400

FAST Fire and Security Technologies

217 Halls Mill Road Lebanon NJ 08833
Phone: (908) 823-4367 / Fax: (866) 844-3086
Email: Sales@fireandsecuritytech.com
Lic: NJ# 34BX00023300
NJ# P01207

DATE:	07/22/2023
Purchase Order #:	24-00414
TERMS:	NET 60
Due Date:	09/20/2023

Oakland Board of Ed

JUL 24 2023
Business Office
(S.W.)

BILL TO
Oakland School District 315 Ramapo Valley Road Oakland, NJ, 07436

SERVICE LOCATION
Oakland School District 315 Ramapo Valley Road Oakland, NJ, 07436

Job Number: 231355 Job Category: NFPA 10

CO-OPS - Fire Alarm, Fire Extinguisher, Kitchen Hood (Inspection and Service) MCCPC #13A / EdData Bid 9994-15A / EdData Bid 9995-15B / ESCNJ 20/21-23

Customer Request: NFPA 10 Fire Extinguisher Inspections

Completion Notes:
NFPA 10 FE Inspections

Description	Qty	Rate	Tax	Total
 NFPA 10 TAG ALL - Dogwood School Price to inspect and tag all fire extinguishers. This price includes all services to meet current code including (as needed) recharging, internal inspections and hydro testing. This price does not include any replacement fire extinguishers for units that fail.	1.00	\$325.00	\$0.000	\$325.00
NFPA 10 TAG ALL - Manito School Price to inspect and tag all fire extinguishers. This price includes all services to meet current code including (as needed) recharging, internal inspections and hydro testing. This price does not include any replacement fire extinguishers for units that fail.	1.00	\$225.00	\$0.000	\$225.00
NFPA 10 TAG ALL - Admin Building Price to inspect and tag all fire extinguishers. This price includes all services to meet current code including (as needed) recharging, internal inspections and hydro testing. This price does not include any replacement fire extinguishers for units that fail.	1.00	\$525.00	\$0.000	\$525.00
NFPA 10 TAG ALL - Heights School	1.00	\$525.00	\$0.000	\$525.00

services to meet current code including (as needed) recharging, internal inspections and hydro testing. This price does not include any replacement fire extinguishers for units that fail.

NFPA 10 TAG ALL - Valley Middle School

Price to inspect and tag all fire extinguishers. This price includes all services to meet current code including (as needed) recharging, internal inspections and hydro testing. This price does not include any replacement fire extinguishers for units that fail.

1.00 \$775.00 \$0.00 \$775.00

CUSTOMER MESSAGE

Invoice Total:	\$2,375.00
Sales Tax:	\$0.00
Payments (-):	\$0.00
Total Due:	\$2,375.00