

25-00443 ✓

Invoice **202401505**



217 Halls Mill Road Lebanon NJ 08833
Phone: (908) 823-4367 / Fax: (866) 844-3086
Email: Sales@fireandsecuritytech.com
Lic: NJ# 34BX00023300
NJ# P01207

DATE:	07/15/2024
Purchase Order #:	25-00443
TERMS:	NET 60
Due Date:	09/13/2024

BILL TO	SERVICE LOCATION
Oakland School District 315 Ramapo Valley Road Oakland, NJ, 07436	Oakland School District 315 Ramapo Valley Road Oakland, NJ, 07436

Job Number: 241261	Job Category: NFPA 10 (S.W.)	CO-OPS Fire Extinguishers - MCCPC #13A / EdData #15A / ESCNJ 20/21-23 Fire Alarms - 57-CCCPS / Ed Data #14
--------------------	------------------------------	--

Customer Request: NFPA 10 Fire Extinguisher Inspections

Completion Notes:
NFPA 10 inspections

Description	Qty	Rate	Tax	Total
NFPA 10 TAG ALL - Dogwood School Price to inspect and tag all fire extinguishers. This price includes all services to meet current code including (as needed) recharging, internal inspections and hydro testing. This price does not include any replacement fire extinguishers for units that fail.	1.00	\$325.00	\$0.000	\$325.00
NFPA 10 TAG ALL - Manito School Price to inspect and tag all fire extinguishers. This price includes all services to meet current code including (as needed) recharging, internal inspections and hydro testing. This price does not include any replacement fire extinguishers for units that fail.	1.00	\$225.00	\$0.000	\$225.00
NFPA 10 TAG ALL - Admin Building Price to inspect and tag all fire extinguishers. This price includes all services to meet current code including (as needed) recharging, internal inspections and hydro testing. This price does not include any replacement fire extinguishers for units that fail.	1.00	\$525.00	\$0.000	\$525.00
NFPA 10 TAG ALL - Heights School Price to inspect and tag all fire	1.00	\$525.00	\$0.000	\$525.00

(as needed) recharging, internal inspections and hydro testing. This price does not include any replacement fire extinguishers for units that fail.

NFPA 10 TAG ALL - Valley Middle School

1.00

\$775.00

\$0.000

\$775.00

Price to inspect and tag all fire extinguishers. This price includes all services to meet current code including (as needed) recharging, internal inspections and hydro testing. This price does not include any replacement fire extinguishers for units that fail.

CUSTOMER MESSAGE

Invoice Total:

\$2,375.00

Sales Tax:

\$0.00

Payments (-):

\$0.00

Total Due:

\$2,375.00