



181 US Hwy 46
Mine Hill, NJ 07803
(908) 654-8068
(800) 783-0567
Fax 908-654-8069

LEAD IN DRINKING WATER REPORT

Performed At:

15 Facilities
New Brunswick, NJ

Performed For:

New Brunswick Board of Education
Frank LoDolce
268 Baldwin Street
New Brunswick, NJ 08901

Prepared By:

LEW Corporation
181 US Hwy 46
Mine Hill, NJ 07803

Phone (908) 654-8068
Fax (908) 654-8069
Website <http://www.LEWCorp.com>

Inspection Date: 6/28/19, 7/02/19
7/11/19, 7/16/19 & 8/1/19
Project Number: 190652 & 190808

Table of Contents

Contact Information.....	3
Introduction	4
Sampling Methodology	4
Drinking Water Results	5
Recommendations	6
Additional Recommendations	7

Appendices

Appendix A	Exceedances
Appendix B	Recommendations
Appendix C	All results
Appendix D	Floor Plan(S)
Appendix E	Laboratory Data

Contact Information

Agency

Client Contact:	Frank LoDolce
Client Name:	New Brunswick Board of Education
Street Address	268 Baldwin Street New Brunswick, NJ 08901
Phone Number:	See Client Information

Risk Assessor

Site Assessor(s):	Alex Salvador	Mark Franz
License:	NJDOH # 022779	NJDOH #003265
Signature		
Date:	August 9, 2018	August 20, 2019
E-Mail	xxxxxxxxx@xxxxxxxx.xxx	xxxxxxx@xxxxxxxx.xxx

Firm

Organization:	LEW Corporation
Certification #:	NJDCA 00015 E
Street:	181 US Hwy 46
City, State & Zip:	Mine Hill, NJ 07803
Phone Number:	908-654-8068
Web Address:	http://www.lewcorp.com

Laboratory

Organization:	Environmental Hazard Services, LLC
Street:	7469 Whitepine Road
City, State & Zip:	Richmond, VA 23237
NJDEP Certification #	VA008
Phone Number:	800-347-4010

Introduction

LEW Corporation was contracted by New Brunswick Board of Education to test for the presence of lead in drinking water in fifteen facilities in the district.

Sampling Methodology

LEW Corporation followed the July 13, 2016 amendments to NJAC 6A:26. Full details on sampling practices can be found in Districts Sampling Plan.

All samples were collected in 250mL wide mouth plastic containers that was prepackaged by the analytical laboratory. The sample containers may contain nitric acid, if expedited analysis is required. If not, nitric acid will be added to each sample upon arrival at the laboratory. At each sample location, the first draw sample was taken after it was determined that the water had been standing in the plumbing system for greater than eight hours but less than forty-eight hours. If second draw samples were collected, they were collecting following a flushing protocol outlined in the District's Sampling Plan.

Drinking Water Results

On June 28, 2019 & July 2, 2019, July 11, 2019, July 16, 2019 & August 1, 2019, LEW Corporation collected the following number of water samples:

Adult Learning Center – 268 Baldwin Street

- 8 first draw samples collected + 1 quality control sample collected
- 0 samples above the 15ppb action level

Chester Redshaw School – 216 Livingston Street

- 32 first draw samples collected + 1 quality control sample collected
- 0 samples above the 15ppb action level

Livingston Elementary School – 206 Delevan Street

- 11 first draw samples collected + 1 quality control sample collected
- 1 sample above the 15ppb action level

Lord Stirling Community School – 101 Redmond Street

- 19 first draw samples collected + 1 quality control sample collected
- 0 samples above the 15ppb action level

Woodrow Wilson Elementary School – 133 Tunison Road

- 15 first draw samples collected + 1 quality control sample collected
- 1 sample above the 15ppb action level

Roosevelt Elementary School – 83 Livingston Avenue

- 17 first draw samples collected + 1 quality control sample collected
- 0 samples above the 15ppb action level

Lincoln Elementary School – 66 Bartlett Street

- 14 first draw samples collected + 1 quality control sample collected
- 0 samples above the 15ppb action level

Lincoln Annex School – 165 Somerset Street

- 10 first draw samples collected + 1 quality control sample collected
- 0 samples above the 15ppb action level

McKinley Kindergarten School – 21 Van Dyke Avenue

- 18 first draw samples collected + 1 quality control sample collected
- 0 samples above the 15ppb action level

McKinley School – 15 Van Dyke Avenue

- 43 first draw samples collected + 1 quality control sample collected
- 0 samples above the 15ppb action level

Health Science Technology High School – 165 Bayard Street

- 6 first draw samples collected + 1 quality control sample collected
- 0 samples above the 15ppb action level

40 Van Dyke Avenue School

- 13 first draw samples collected + 1 quality control sample collected
- 0 samples above the 15ppb action level

Paul Robeson 199 Commercial Avenue School

- 48 first draw samples collected + 1 quality control sample collected
- 4 samples above the 15ppb action level

New Brunswick Middle School – 1125 Livingston Avenue

- 30 first draw samples collected + 1 quality control sample collected
- 0 samples above the 15ppb action level

New Brunswick High School 100 Somerset Street

- 49 first draw samples collected + 1 quality control sample collected
- 2 sample above the 15ppb action level

The complete list of samples that exceeded the 15ppb limit can be found in Appendix A. The complete list of all sample results can be found in Appendix C. The laboratory results can be found in Appendix E.

Certain outlets could not or were not tested due to various reasons. The following table lists those locations and the reason why samples were not collected.

School	Sample location	Reason for not testing
Paul Robeson School	199 – 14 - BB	Outlet removed
New Brunswick Middle School	1125 – 13 - FP	Outlet removed
Roosevelt Elementary School	83-2-WC	Outlet out of Service

Recommendations

Those outlets where the first draw sample tested below 15ppb are not considered to be elevated and no mitigation is necessary.

For those outlets where the first draw sample exceeds 15ppb the following steps are recommended:

- 1) Immediately discontinue use of the outlets.
- 2) Conduct second draw (flush) samples on these outlets to further delineate source of contamination.

A complete list of recommendations per outlet can be found in Appendix B.

Additional Recommendations

- 1) Follow-up samples should be collected after any remediation efforts in order to determine the efficacy of the work.
- 2) Any of the inoperable/non-functioning outlets listed above that are brought back into service should be sample.
- 3) Comply with all requirements set forth in NJAC 6A:26.

Appendix A Exceedances

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
1 st Draw Samples					
Roosevelt Elementary School					
Roosevelt Elementary	07/11/2019	07/19/2019	B3-16	Trailer 1	32.6
Paul Robeson School					
Paul Robeson	07/02/2019	07/09/2019	199-3	Kitchen Kettle Sink	18.0
Paul Robeson	07/02/2019	07/09/2019	199-20	Room 105	81.5
Paul Robeson	07/02/2019	07/09/2019	199-35	Room 211	15.5
Paul Robeson	07/02/2019	07/09/2019	199-44	Room 202	18.2
Woodrow Wilson Elementary School					
Woodrow Wilson Elementary	7/11/2019	7/17/2019	133-1	Hall by Room 207	15.7
Livingston Elementary School					
Livingston Elementary School	7/11/2019	7/17/2019	206-3	Room 5	53.8
New Brunswick High School					
New Brunswick High School	07/16/2019	7/22/2019	NBHS-26	Room H154	31.2
New Brunswick High School	07/16/2019	7/22/2019	NBHS-42	Room 119D Coffee Machine	39.4

Appendix B Recommendations

Building	Sample ID	Location	Remediation Recommendation
Roosevelt Elementary	B3-16	Trailer 1	Immediately discontinue use of the outlet. Conduct second draw (flush) sample on this outlet to further delineate the source of contamination.
Paul Robeson	199-3	Kitchen Kettle Sink	Immediately discontinue use of the outlet. Conduct second draw (flush) sample on this outlet to further delineate the source of contamination.
Paul Robeson	199-20	Room 105	Immediately discontinue use of the outlet. Conduct second draw (flush) sample on this outlet to further delineate the source of contamination.
Paul Robeson	199-35	Room 211	Immediately discontinue use of the outlet. Conduct second draw (flush) sample on this outlet to further delineate the source of contamination.
Paul Robeson	199-44	Room 202	Immediately discontinue use of the outlet. Conduct second draw (flush) sample on this outlet to further delineate the source of contamination.
Woodrow Wilson Elementary	133-1	Hall by Room 207	Immediately discontinue use of the outlet. Conduct second draw (flush) sample on this outlet to further delineate the source of contamination.
Livingston Elementary School	206-3	Room 5	Immediately discontinue use of the outlet. Conduct second draw (flush) sample on this outlet to further delineate the source of contamination.
New Brunswick High School	NBHS-26	Room H154	Immediately discontinue use of the outlet. Conduct second draw (flush) sample on this outlet to further delineate the source of contamination.
New Brunswick High School	NBHS-42	Room 119D Coffee Machine	Immediately discontinue use of the outlet. Conduct second draw (flush) sample on this outlet to further delineate the source of contamination.

Appendix C All Results

2019 - Water Testing Report Summary

Adult Learning Center

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Adult Learning Center – 268 Baldwin Street					
Adult Learning Center	06/28/2019	07/03/2019	268-1-WC	SECURITY HALL FOUNTAIN RIGHT	<1.00
Adult Learning Center	06/28/2019	07/03/2019	268-2-S	KITCHEN 1	<1.00
Adult Learning Center	06/28/2019	07/03/2019	268-3-S	NURSE OFFICE	<1.00
Adult Learning Center	06/28/2019	07/03/2019	268-4-WC	HALL BY CUSTODIAN LEFT	<1.00
Adult Learning Center	06/28/2019	07/03/2019	268-5-S	TEACHERS LOUNGE	<1.00
Adult Learning Center	06/28/2019	07/03/2019	268-6-WC	HALLWAY BY RM 214 RIGHT	<1.00
Adult Learning Center	06/28/2019	07/03/2019	268-7-WC	HALLWAY BY GIRLS RM 3RD FL RIGHT	<1.00
Adult Learning Center	06/28/2019	07/03/2019	268-8-S	STAFF LOUNGE	<1.00
Adult Learning Center	06/28/2019	07/03/2019	268-9-S	STORAGE RM – QA/QC	<1.00

2019 - Water Testing Report Summary

Redshaw

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Chester Redshaw School – 216 Livingston Street					
Chester Redshaw School	07/11/2019	07/17/2019	216-1-BB	RM 102	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-2-BB	RM 104	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-3-BB	RM 105	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-4-BB	RM 106	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-5-BB	RM 107	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-6-S	MAIN OFFICE	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-7-S	NURSES OFFICE	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-8-BB	RM 1 20 BB	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-9-BB	RM 122	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-10-BB	RM 113	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-11-BB	RM 115	1.12
Chester Redshaw School	07/11/2019	07/17/2019	216-12-BB	RM 117	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-13-BB	RM 124	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-14-BB	RM 126	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-15-WC	HALL BY 127 RIGHT	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-16-WC	PLAY GROUND RIGHT	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-17-WC	HALL BY RM 154 RIGHT	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-18-WC	HALLWAY BY ELEVATOR #31 RIGHT	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-19-IM	KITCHEN ICE MACHINE #29	<1.00

2019 - Water Testing Report Summary

Redshaw cont.

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Chester Redshaw School – 216 Livingston Street					
Chester Redshaw School	07/11/2019	07/17/2019	216-20-FP	KITCHEN #17	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-21-SK	KIT #28	2.69
Chester Redshaw School	07/11/2019	07/17/2019	216-22-SK	KIT #30	11.5
Chester Redshaw School	07/11/2019	07/17/2019	216-23-FP	KIT #18	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-24-WC	HALLWAY BY RM 253 RIGHT	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-25-WC	HALLWAY BY RM 231 RIGHT	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-26-WC	HALLWAY BY RM 315 RIGHT	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-27-WC	HALLWAY BY MEDIA CENTER RIGHT	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-28-BB	RM 206	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-29-BB	RM 207	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-30-BB	RM 204	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-31-BB	RM 202	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-32-BB	RM 205	<1.00
Chester Redshaw School	07/11/2019	07/17/2019	216-33-S	STORAGE RM QA-QC	<1.00

2019 - Water Testing Report Summary

Livingston

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Livingston Elementary School – 206 Delevan Street					
Livingston Elementary School	07/11/2019	07/17/2019	206-1-WC	BASEMENT LEFT HALLWAY	<1.00
Livingston Elementary School	07/11/2019	07/17/2019	206-2-WC	BASEMENT RIGHT HALLWAY	1.56
Livingston Elementary School	07/11/2019	07/17/2019	206-3-BB	ROOM 5 BB	53.8
Livingston Elementary School	07/11/2019	07/17/2019	206-4-S	ROOM 6 SINK	1.69
Livingston Elementary School	07/11/2019	07/17/2019	206-5-S	KITCHEN #4	1.30
Livingston Elementary School	07/11/2019	07/17/2019	206-6-WC	1ST FLOOR HALLWAY	<1.00
Livingston Elementary School	07/11/2019	07/17/2019	206-7-WC	2ND FL HALL LIBRARY	<1.00
Livingston Elementary School	07/16/2019	07/22/2019	206-8-WC	TRAILER 1	<1.00
Livingston Elementary School	07/11/2019	07/17/2019	206-9-WC	TRAILER 2	<1.00
Livingston Elementary School	07/11/2019	07/17/2019	206-10-WC	TRAILER 3	<1.00
Livingston Elementary School	07/11/2019	07/17/2019	206-11-WC	TRAILER 4	<1.00
Livingston Elementary School	07/11/2019	07/17/2019	206-12-S	STORAGE ROOM – QA.QC	<1.00

2019 - Water Testing Report Summary

Stirling

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Lord Stirling Community School – 101 Redmond Street					
Lord Stirling Community School	07/02/2019	07/08/2019	101-1-WC	#2 CAFETERIA LEFT	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-2-FP	#4 KITCHEN KETTLE	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-3-S	KITCHEN SINK	1.27
Lord Stirling Community School	07/02/2019	07/08/2019	101-4-S	MAIN OFFICE WORK RM	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-5-S	NURSE OFFICE	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-6-WC	HALL BY RM 210 LEFT	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-7-S	RM 206	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-8-S	RM 232	2.28
Lord Stirling Community School	07/02/2019	07/08/2019	101-9-S	FACULTY LOUNGE	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-10-WC	BOYS LOCKER RM #17 LEFT	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-11-WC	GIRLS LOCKER RM LEFT	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-12-WC	HALLWAY BY GYM LEFT	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-13-BB	RM 124	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-14-BB	RM 123	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-15-BB	RM 122	1.11
Lord Stirling Community School	07/02/2019	07/08/2019	101-16-BB	RM 120	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-17-BB	RM 119	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-18-S	RM 106	6.26
Lord Stirling Community School	07/02/2019	07/08/2019	101-19-WC	HALL BY RM 118 LEFT	<1.00
Lord Stirling Community School	07/02/2019	07/08/2019	101-20-S	STORAGE RM – QA/QC	<1.00

2019 - Water Testing Report Summary

Woodrow Wilson

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Woodrow Wilson Elementary School – 133 Tunison Road					
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-1 WC	HALL BY RM 27 (#5)	15.7
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-2-S	NURSE OFFICE (#6)	6.70
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-3-WC	HALLY BY RM 25 (#7)	6.08
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-4-WC	HALL BY RM 22 (#8)	1.17
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-5-WC	HALL BY CUSTODIAN CLOSET (#4) RIGHT	<1.00
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-6-WC	HALL BY MAIN OFFICE (#3) RIGHT	<1.00
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-7-S	KITCHEN (#1)	4.03
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-8-WC	TRAILER 2 (#10)	1.04
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-9-WC	TRAILER 3 (#12)	<1.00
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-10-WC	TRAILER 1 (#9)	<1.00
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-11-WC	TRAILER 4 (#11)	<1.00
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-12-WC	TRAILER 5 (#13)	<1.00
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-13-WC	TRAILER 8 (#15)	<1.00
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-14-WC	TRAILER 7 (#16)	<1.00
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-15-WC	TRAILER 6 (#14)	<1.00
Woodrow Wilson Elementary	07/11/2019	07/17/2019	133-16-S	STORAGE RM –QA/QC	<1.00

2019 - Water Testing Report Summary

Roosevelt

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Roosevelt Elementary School – 83 Livingston Avenue					
Roosevelt Elementary School	7/11/2019	7/17/2019	83-1-WC	HALLWAY BY CUST CLOSET	<1.00
Roosevelt Elementary School	7/11/2019	7/17/2019	83-2-WC	CAFETERIA LEFT	Out of service
Roosevelt Elementary School	7/11/2019	7/17/2019	83-3-WC	CAFETERIA RIGHT	<1.00
Roosevelt Elementary School	7/11/2019	7/17/2019	83-4-FP	KITCHEN #13	3.01
Roosevelt Elementary School	7/11/2019	7/17/2019	83-5-FP	KITCHEN KETTLE #18	2.14
Roosevelt Elementary School	7/11/2019	7/17/2019	83-6-WC	HALLWAY BY RM 20 LEFT	1.94
Roosevelt Elementary School	7/11/2019	7/17/2019	83-7-WC	HALLWAY BY RM 121 LEFT	3.41
Roosevelt Elementary School	7/11/2019	7/17/2019	83-8-WC	HALLWAY BY NURSES OFFICE LEFT	11.0
Roosevelt Elementary School	7/11/2019	7/17/2019	83-9-S	NURSES OFFICE #9	2.10
Roosevelt Elementary School	7/11/2019	7/17/2019	83-10-WC	HALLWAY BY RM 114	3.68
Roosevelt Elementary School	7/11/2019	7/17/2019	83-11-WC	HALLWAY BY RM 114 LEFT	<1.00
Roosevelt Elementary School	7/11/2019	7/17/2019	83-12-WC	HALLWAY BY RM 215 LEFT	<1.00
Roosevelt Elementary School	7/11/2019	7/17/2019	83-13-WC	HALLWAY BY RM 224 LEFT	1.52
Roosevelt Elementary School	7/11/2019	7/17/2019	83-14-WC	HALLWAY BY 321 LEFT	9.61
Roosevelt Elementary School	7/11/2019	7/17/2019	83-15-WC	HALLWAY BY RM 315 LEFT	2.38
Roosevelt Elementary School	7/11/2019	7/17/2019	83-16-WC	TRAILER #1	32.8
Roosevelt Elementary School	7/11/2019	7/17/2019	83-17-WC	TRAILER #2	8.73
Roosevelt Elementary School	7/11/2019	7/17/2019	83-18-S	STORAGE RM – QA/QC	<1.00

2019 - Water Testing Report Summary

Lincoln

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Lincoln Elementary School – 66 Bartlett Street					
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-1-WC	HALL BY FACULTY RESTROOM RIGHT	<1.00
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-2-FP	BASEMENT KITCHEN	1.38
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-3-WC	HALL BY RM 205 #12	<1.00
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-4-WC	HALL BY RM 211 LEFT #13	<1.00
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-5-S	FACULTY RM LEFT #14	1.20
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-6-S	NURSES OFFICE	<1.00
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-7-WC	HALLWAY BY RM 111 RIGHT	2.96
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-8-S	ROOM 108 #4	1.77
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-9-S	ROOM 104 #3	<1.00
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-10-WC	TRAILER 601 #7	<1.00
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-11-WC	TRAILER 602 #8	<1.00
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-12-WC	TRAILER 603 #9	<1.00
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-13-WC	TRAILER 604 #10	<1.00
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-14-WC	TRAILER 605 #11	<1.00
Lincoln Elementary School	07/02/2019	07/09/2019	LINCOLN-66-15-S	STORAGE RM – QA/QC	<1.00

2019 - Water Testing Report Summary

Lincoln Annex

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Lincoln Annex School – 165 Somerset Street					
Lincoln Annex School	07/02/2019	07/08/2019	ANNEX-165-1-WC	HALL BY RM 144 RIGHT	<1.00
Lincoln Annex School	07/02/2019	07/08/2019	ANNEX-165-2-WC	#7 HALL BY RM 237 RIGHT	<1.00
Lincoln Annex School	07/02/2019	07/08/2019	ANNEX-165-3-WC	#9 HALL BY RM 319 RIGHT	<1.00
Lincoln Annex School	07/02/2019	07/08/2019	ANNEX-165-4-WC	#8 HALL BY RM 204	<1.00
Lincoln Annex School	07/02/2019	07/08/2019	ANNEX-165-5-S	#2 NURSE OFFICE	1.21
Lincoln Annex School	07/02/2019	07/08/2019	ANNEX-165-6-WC	#3 HALL BY RM 104	<1.00
Lincoln Annex School	07/02/2019	07/08/2019	ANNEX-165-7-WC	#6 HALL BY RM 005 RIGHT	<1.00
Lincoln Annex School	07/02/2019	07/08/2019	ANNEX-165-8-FP	#10 KITCHEN KETTLE	1.51
Lincoln Annex School	07/02/2019	07/08/2019	ANNEX-165-9-FP	#4 KITCHEN SINK	<1.00
Lincoln Annex School	07/02/2019	07/08/2019	ANNEX-165-10-FP	#5 KITCHEN SINK	1.81
Lincoln Annex School	07/02/2019	07/08/2019	ANNEX-165-11-S	STORAGE RM QC	<1.00

2019 – Water Testing Report Summary

McKinley Kindergarten School

Bui ldin g	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
McKinley Kindergarten School – 21 Van Dyke Avenue					
McKinley Kindergarten	06/28/2019	07/03/2019	MCKINLEY PRE K-21-1	RM 100 A #7	1.81
McKinley Kindergarten	06/28/2019	07/03/2019	MCKINLEY PRE K-21-2	RM 103 A #6	<1.00
McKinley Kindergarten	06/28/2019	07/03/2019	MCKINLEY PRE K-21-3	RM 106 A #5	1.08
McKinley Kindergarten	06/28/2019	07/03/2019	MCKINLEY PRE K-21-4	RM 145 A #11	1.20
McKinley Kindergarten	06/28/2019	07/03/2019	MCKINLEY PRE K-21-5	RM 109 A #4	<1.00
McKinley Kindergarten	06/28/2019	07/03/2019	MCKINLEY PRE K-21-6	NURSES OFFICE #17	1.32
McKinley Kindergarten	06/28/2019	07/03/2019	MCKINLEY PRE K-21-7	RM 112 A #3	1.24
McKinley Kindergarten	06/28/2019	07/03/2019	MCKINLEY PRE K-21-8	HALL BY RM 126 A #2	<1.00
McKinley Kindergarten	06/28/2019	07/03/2019	MCKINLEY PRE K-21-9	RM 128 A #1	<1.00
McKinley Kindergarten	06/28/2019	07/03/2019	MCKINLEY PRE K-21-10	HALL BY RM A 212 #10	<1.00
McKinley Kindergarten	06/28/2019	07/05/2019	MCKINLEY PRE K-21-11	RM 219 A #8	<1.00
McKinley Kindergarten	06/28/2019	07/05/2019	MCKINLEY PRE K-21-12	RM 220 A #9	<1.00
McKinley Kindergarten	06/28/2019	07/05/2019	MCKINLEY PRE K-21-13	RM 212 A #12	<1.00
McKinley Kindergarten	06/28/2019	07/05/2019	MCKINLEY PRE K-21-14	RM 209 A # 13	<1.00
McKinley Kindergarten	06/28/2019	07/05/2019	MCKINLEY PRE K-21-15	RM 229 #18	5.94
McKinley Kindergarten	06/28/2019	07/05/2019	MCKINLEY PRE K-21-16	RM 206 #14	<1.00
McKinley Kindergarten	06/28/2019	07/05/2019	MCKINLEY PRE K-21-17	RM 203 #16	1.61
McKinley Kindergarten	06/28/2019	07/05/2019	MCKINLEY PRE K-21-18	RM 200 #15	2.21
McKinley Kindergarten	06/28/2019	07/05/2019	MCKINLEY PRE K-21-19	STORAGE RM + QA/QC	<1.00

2019 - Water Testing Report Summary

McKinley / McKinley PK

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
McKinley School – 15 Van Dike Avenue					
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY-15-1-S	LIBRARY OFFICE 109 A #1	2.04
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY-15-2-BB	ROOM 110	1.31
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY-15-3-BB-2	RM 111 #4	3.60
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY-15-4-BB	RM 119 #5	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY-15-5-BB	RM 112 #6	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY-15-6-BB	RM 118 #7	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY-15-7-BB	RM 113 #8	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY-15-8-BB	RM 117 #9	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY-15-9-BB	RM 114 #3	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY-15-10-BB	RM 115 #34	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY-15-11-BB	STORAGE RM – QA/QC	<1.00
McKinley School	08/1/2019	08/07/2019	MCKINLEY COMMUNITY- 15-11-WC	HALL BY RM 116 (10)	4.18
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-12-WC	HALL BY RM 305 (11)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-13-WC	HALL BY MAINTENANCE CLOSET RIGHT	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-14-S	NURSES OFFICE (13)	2.10
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-16-BB	RM 105 (15)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-15-BB	RM 106 (14)	1.12
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-17-BB	RM 104 (16)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-18-BB	RM 103 (17)	7.29

2019 - Water Testing Report Summary

McKinley / McKinley PK

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
McKinley School – 15 Van Dyke Avenue					
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-19-BB	RM 102 (18)	1.06
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-20-BB	RM 101 (19)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-21-S-2	MAIN OFFICE (21)	1.52
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-22-WC	HALL BY RM 328D (33)	1.21
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-23-WC	HALL BY RM 316 (20) RIGHT	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-24-WC	HALL BY RM 320 (22) RIGHT	1.10
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-25-WC	HALL BY AUDITORIUM (23) LEFT	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-26-WC	COMMUNITY ROOM RIGHT (24)	1.25
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-27-S	COMMUNITY ROOM KITCHEN (25)	3.23
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-28-WC	GYM (26)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-29-S	FACULTY DINING (27)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-30-FP	KITCHEN KETTLE (32)	1.46
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-31-S	KITCHEN (28)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-32-S	KITCHEN (29)	3.79
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-33-S	TEACHERS LOUNGE (30) RM 200	2.91
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-34-BB-2	RM 201 (35)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-35-BB-2	RM 202 (36)	
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-36-BB	RM 209 (37)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-37-BB-2	RM 210 (38)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-38-BB-2	RM 203 (39)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-39-BB-2	RM 204 (40)	<1.00

2019 - Water Testing Report Summary

McKinley / McKinley PK

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
McKinley School – 15 Van Dyke Avenue					
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-40-BB-2	RM 208 (41)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-41-BB-2	RM 207 (42)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-42-BB	RM 205 (43)	<1.00
McKinley School	06/28/2019	07/05/2019	MCKINLEY COMMUNITY- 15-43-BB-2	RM 206 (44)	<1.00

2019 - Water Testing Report Summary

Building 40 – P-Tech

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
40 Van Dyke Avenue School					
40 Van Dyke School	6/28/2019	07/03/2019	40-1-S	NURSES OFFICE	2.00
40 Van Dyke School	6/28/2019	07/03/2019	40-2-BB	RM 152	<1.00
40 Van Dyke School	6/28/2019	07/03/2019	40-3-BB	RM 154	<1.00
40 Van Dyke School	6/28/2019	07/03/2019	40-4-BB	RM 155	<1.00
40 Van Dyke School	6/28/2019	07/03/2019	40-5-BB	RM 169	<1.00
40 Van Dyke School	6/28/2019	07/03/2019	40-6-BB	RM 170	1.16
40 Van Dyke School	6/28/2019	07/03/2019	40-7-BB	RM 173	<1.00
40 Van Dyke School	6/28/2019	07/03/2019	40-8-WC	HALLWAY BY RM 108 RIGHT	<1.00
40 Van Dyke School	6/28/2019	07/03/2019	40-9-WC	HALLWAY BY GIRLS 134 & BOYS RIGHT	<1.00
40 Van Dyke School	6/28/2019	07/03/2019	40-10-WC	HALLWAY BY GIRLS RM & BOYS RIGHT	<1.00
40 Van Dyke School	6/28/2019	07/03/2019	40-11-WC	HALLWAY BY CAFE 163	<1.00
40 Van Dyke School	6/28/2019	07/03/2019	40-12-S	KITCHEN 01	<1.00
40 Van Dyke School	6/28/2019	07/03/2019	40-13-S	KITCHEN 01	2.85
40 Van Dyke School	6/28/2019	07/03/2019	40-14-S	STORAGE RM QA-QC	2.43

2019 - Water Testing Report Summary

New Brunswick Heath Sciences Tech HS

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
Health Science Technology High School – 165 Bayard Street					
Health Science Technology High School	07/02/2019	07/08/2019	HSTHS-1S	CAFETERIA	<1.00
Health Science Technology High School	07/02/2019	07/08/2019	HSTHS-2-S	HALL BY RM 109 RIGHT	<1.00
Health Science Technology High School	07/02/2019	07/08/2019	HSTHS-3-S	NURSES OFFICE	1.11
Health Science Technology High School	07/02/2019	07/08/2019	HSTHS-4-S	TEACHERS LOUNGE	<1.00
Health Science Technology High School	07/02/2019	07/08/2019	HSTHS-5-WC	HALL BY TEACHERS LOUNGE	<1.00
Health Science Technology High School	07/02/2019	07/08/2019	HSTHS-6-WC	HALL BY RM 307	<1.00
Health Science Technology High School	07/02/2019	07/08/2019	HSTHS-7-S	STORAGE RM – QA/QC	<1.00

2019 - Water Testing Report Summary

Paul Robeson

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
199 Commercial Avenue School					
199 Commercial School	07/02/2019	07/09/2019	199-1-FP	KITCHEN SINK	2.65
199 Commercial School	07/02/2019	07/09/2019	199-2-FP	KITCHEN KETTLE SINK	<1.00
199 Commercial School	07/02/2019	07/09/2019	199-3-FP	KITCHEN KETTLE SINK	18
199 Commercial School	07/02/2019	07/09/2019	199-4-BB	RM 156	<1.00
199 Commercial School	07/02/2019	07/09/2019	199-5-BB	RM 154 #6	1.46
199 Commercial School	07/02/2019	07/09/2019	199-6-BB	RM 157 #5	1.14
199 Commercial School	07/02/2019	07/09/2019	199-7-BB	RM 158 #8	<1.00
199 Commercial School	07/02/2019	07/09/2019	199-8-BB	RM 153 # 7	<1.00
199 Commercial School	07/02/2019	07/09/2019	199-9-BB	RM 152 # 9	<1.00
199 Commercial School	07/02/2019	07/09/2019	199-10-BB	RM 151 #10	1.83
199 Commercial School	07/02/2019	07/09/2019	199-11-BB	RM 150 #11	1.83
199 Commercial School	07/02/2019	07/09/2019	199-12-BB	RM 149 #12	1.67
199 Commercial School	07/02/2019	07/09/2019	199-13-BB	RM 148 #13	<1.00
199 Commercial School	07/02/2019	07/09/2019	199-14-BB	RM 147	Outlet Removed
199 Commercial School	07/02/2019	07/09/2019	199-15-WC	HALLWAY BY RM 142 RIGHT	<1.00
199 Commercial School	07/02/2019	07/09/2019	199-16-S	RM 141	2.09
199 Commercial School	07/02/2019	07/09/2019	199-17-WC	HALL BY RM 128	<1.00
199 Commercial School	07/02/2019	07/09/2019	199-18-BB	RM 109 #19	1.24
199 Commercial School	07/02/2019	07/09/2019	199-19-BB	RM 110 #20	1.05
199 Commercial School	07/02/2019	07/09/2019	199-20-S-2	RM 105 #21	81.5
199 Commercial School	07/02/2019	07/09/2019	199-21-WC	HALLWAY BY RM 102 RIGHT	<1.00
199 Commercial School	07/02/2019	07/09/2019	199-22-S	NURSE OFFICE 23	<1.00
199 Commercial School	07/02/2019	07/09/2019	199-23-S	NURSE OFFICE 24	1.19
199 Commercial School	07/02/2019	07/09/2019	199-24-BB	RM 241 #25	1.28
199 Commercial School	07/02/2019	07/09/2019	199-25-BB	RM 238 #27	1.18
199 Commercial School	07/02/2019	07/09/2019	199-26-BB	RM 237 #28	1.58
199 Commercial School	07/02/2019	07/09/2019	199-27-BB	RM 236 # 29	<1.00
199 Commercial School	07/02/2019	07/09/2019	199-28-BB	RM 242 (#26)	1.21
199 Commercial School	07/02/2019	07/09/2019	199-29-BB	RM 243 #30	<1.00
199 Commercial School	07/02/2019	07/09/2019	199-30-BB	RM 232 (#3)	1.62
199 Commercial School	07/02/2019	07/09/2019	199-31-S	RM 230 #32	<1.00

2019 - Water Testing Report Summary

Paul Robeson

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
199 Commercial Avenue School					
199 Commercial School	07/02/2019	07/09/2019	199-32-WC	HALLWAY BY RM 244 #33 LEFT	<1.00
199 Commercial School	07/02/2019	07/09/2019	199-33-S-2	RM 210 #34	4.45
199 Commercial School	07/02/2019	07/09/2019	199-34-S-2	RM 208 #35	7.43
199 Commercial School	07/02/2019	07/09/2019	199-35-S-2	RM 211 #37	15.5
199 Commercial School	07/02/2019	07/09/2019	199-36-S-2	RM 207 #36	3.30
199 Commercial School	07/02/2019	07/10/2019	199-37-S-2	RM 206 #39	8.02
199 Commercial School	07/02/2019	07/10/2019	199-38-S-2	RM 212 #38	2.88
199 Commercial School	07/02/2019	07/10/2019	199-39-S-2	RM 213 (#41)	5.09
199 Commercial School	07/02/2019	07/10/2019	199-40-WC	HALLWAY BY RM 213 #40 RIGHT	<1.00
199 Commercial School	07/02/2019	07/10/2019	199-41-S-2	RM 205 #42	4.19
199 Commercial School	07/02/2019	07/10/2019	199-42-S-3	RM 204 #43	9.05
199 Commercial School	07/02/2019	07/10/2019	199-43-S-2	RM 203 #44	3.72
199 Commercial School	07/02/2019	07/10/2019	199-44-S-2	RM 202 #45	18.2
199 Commercial School	07/02/2019	07/10/2019	199-45-S-2	RM 201 #47	4.45
199 Commercial School	07/02/2019	07/10/2019	199-46-S-2	RM 217 #46	6.33
199 Commercial School	07/02/2019	07/10/2019	199-47-S-2	RM 218 #50	3.51
199 Commercial School	07/02/2019	07/10/2019	199-48-WC	HALL BY RM 303 #49 RIGHT	<1.00
199 Commercial School	07/02/2019	07/10/2019	199-49-WC	HALL BY T=RM 312 #48 RIGHT	<1.00
199 Commercial School	07/02/2019	07/10/2019	199-50-S	STORAGE RM – QA/QC	<1.00

2019 - Water Testing Report Summary

New Brunswick High School

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
New Brunswick High School					
New Brunswick High School	07/16/2019	07/22/2019	NBHS-1 -BB	RM 124 A	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-2 -S	RM 118 B	1.78
New Brunswick High School	07/16/2019	07/22/2019	NBHS-3 -S	RM 114 C	1.89
New Brunswick High School	07/16/2019	07/22/2019	NBHS-4 -S	RM 119 S	3.11
New Brunswick High School	07/16/2019	07/22/2019	NBHS-5 -S	RM 119 S	3.64
New Brunswick High School	07/16/2019	07/22/2019	NBHS-6 -BB	RM 106 D	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-7 -BB	RM 108 D	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-8 -WC	HALL BY RM 111F RIGHT	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-9 -WC	CAFE J100 RIGHT	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-10 -S	KITCHEN	2.73
New Brunswick High School	07/16/2019	07/22/2019	NBHS-11 -S	KITCHEN	1.02
New Brunswick High School	08/01/2019	08/07/2019	NBHS-12 -S	KITCHEN	4.46
New Brunswick High School	07/16/2019	07/22/2019	NBHS-13 -BB	RM J 126	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-14 -BB	RM J 128	2.07
New Brunswick High School	08/01/2019	08/07/2019	NBHS-15 -WC	RM L 127 RIGHT	1.87
New Brunswick High School	07/16/2019	07/22/2019	NBHS-16 -WC	RM L 125 RIGHT	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-17 -BB	WEIGHT RM	1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-18 -WC	RM L 110 RIGHT	<1.00
New Brunswick High School	08/01/2019	08/07/2019	NBHS-18 -WC	RM L 110 RIGHT	1.82
New Brunswick High School	08/01/2019	08/07/2019	NBHS-19 -WC	RM L 100 RIGHT	10.4
New Brunswick High School	07/16/2019	07/22/2019	NBHS-21 -BB	NURSE OFFICE	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-22 -WC	GYM LEFT	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-23 -S	RM H 133	2.44
New Brunswick High School	07/16/2019	07/22/2019	NBHS-24 -S	RM H 104	1.48
New Brunswick High School	07/16/2019	07/22/2019	NBHS-25 -S	RM H 127 IN H 125	2.21
New Brunswick High School	07/16/2019	07/22/2019	NBHS-26 -S	RM H 154	31.2
New Brunswick High School	07/16/2019	07/22/2019	NBHS-27-S	ROOM 240 PREP RM	1.21
New Brunswick High School	07/16/2019	07/22/2019	NBHS-28 -BB	RM 212 C	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-29 -BB	RM 213 C	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-30 -S	RM 219 C	4.19

New Brunswick High School	07/16/2019	07/22/2019	NBHS-31 -WC	RM H 207 RIGHT	<1.00
---------------------------	------------	------------	-------------	----------------	-------

2019 - Water Testing Report Summary

New Brunswick High School

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
New Brunswick High School					
New Brunswick High School	07/16/2019	07/22/2019	NBHS-32 -S	RM 214 D	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-33 -WC	HALL BY RM 219 D RIGHT	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-34 -BB	RM A 211	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-35 -BB	RM 315 B	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-36 -S	RM 315 C	1.28
New Brunswick High School	07/16/2019	07/22/2019	NBHS-37 -S	RM 312 D	4.22
New Brunswick High School	07/16/2019	07/22/2019	NBHS-38 -S	RM 306 G	1.12
New Brunswick High School	07/16/2019	07/22/2019	NBHS-39 -WC	HALL BY RM 320 D RIGHT	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-40 -	FIELD HOUSE	3.43
New Brunswick High School	07/16/2019	07/22/2019	NBHS-41 -1M	RM 119 D 1M	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-42 -FP	RM 119 D COFFEE MACHINE	39.4
New Brunswick High School	07/16/2019	07/22/2019	NBHS-43 -FP	KITCHEN KETTLE	<1.00
New Brunswick High School	08/01/2019	08/07/2019	NBHS-44 -FP-2	KITCHEN POT FILLER	10.7
New Brunswick High School	07/16/2019	07/22/2019	NBHS-45 -FP	KITCHEN POT FILLER	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-46 -FP	KITCHEN ICE MACHINE	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-47 -FP	KITCHEN SINK	3.72
New Brunswick High School	07/16/2019	07/22/2019	NBHS-48 -FP	RM J 114 COFFEE	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-49 -S	RM L 112	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-50 -IM	RM L 112	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-52 - STORAGE RM	STORAGE RM QA-QC	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-53-	Room 122 B	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-54-	Room C108	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-55-	Hall by H137	<1.00
New Brunswick High School	07/16/2019	07/22/2019	NBHS-56-	Room D 319	<1.00

2019 - Water Testing Report Summary

Middle School

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
New Brunswick Middle School – 1125 Livingston Avenue					
New Brunswick Middle School	07/16/2019	07/24/2019	1125-1-WF	HALLWAY BY RM 120	<1.0 0
New Brunswick Middle School	07/16/2019	07/24/2019	1125-2-WF	HALLWAY BY RM 107	<1.0 0
New Brunswick Middle School	07/16/2019	07/24/2019	1125-3-S	MAIN OFFICE SINK	2.54
New Brunswick Middle School	07/16/2019	07/24/2019	1125-4-WF-2	HALLWAY BY RM 102	1.51
New Brunswick Middle School	07/16/2019	07/24/2019	1125-5-S	NURSE OFFICE SINK	1.29
New Brunswick Middle School	07/16/2019	07/24/2019	1125-6-WF	HALLWAY BY NURSE	<1.0 0
New Brunswick Middle School	07/16/2019	07/24/2019	1125-7-WF	HALLWAY BY SECURITY	<1.0 0
New Brunswick Middle School	07/16/2019	07/24/2019	1125-8-WF	GIRLS LOCKER ROOM	3.94
New Brunswick Middle School	07/16/2019	07/24/2019	1125-9-WF	BOYS LOCKER ROOM	2.99
New Brunswick Middle School	07/16/2019	07/24/2019	1125-10-WF	HALL BY GYM	<1.0 0
New Brunswick Middle School	07/16/2019	07/24/2019	1125-11-FP-3	KITCHEN KETTLE -1	<1.0 0
New Brunswick Middle School	07/16/2019	07/24/2019	1125-12-S	KITCHEN #14 S	4.60
New Brunswick Middle School	07/16/2019	07/24/2019	1125-13-FP-2	KITCHEN KETTLE -33-2	Outlet removed
New Brunswick Middle School	07/16/2019	07/24/2019	1125-14-FP	KITCHEN SINK #15	2.44
New Brunswick Middle School	07/16/2019	07/24/2019	1125-15-WC	CAFE WATER FOUNTAIN #12	<1.0 0
New Brunswick Middle School	07/16/2019	07/24/2019	1125-16-WC	CAFE WATER FOUNTAIN #13	<1.0 0
New Brunswick Middle School	07/16/2019	07/24/2019	1125-17-WC	HALLWAY BY AUDITORIUM RIGHT	8.73
New Brunswick Middle School	07/16/2019	07/24/2019	1125-18-WC	OUTSIDE AUDITORIUM BY ENTRANCE	4.67

2019 - Water Testing Report Summary

Middle School

Building	Date Collected	Analysis Date	Sample ID	Sample Description	Concentration (ug/L) Or ppb
New Brunswick Middle School – 1125 Livingston Avenue					
New Brunswick Middle School	07/16/2019	07/24/2019	1125-19-WC	#23 BY RM 203	1.23
New Brunswick Middle School	07/16/2019	07/24/2019	1125-20-WC	#22 BY RM 233	2.03
New Brunswick Middle School	07/16/2019	07/24/2019	1125-21-WC	HALLWAY BY BIOLOGY	<1.00
New Brunswick Middle School	07/16/2019	07/24/2019	1125-22-WC	HALLWAY BY RM 221	10.6
New Brunswick Middle School	07/16/2019	07/24/2019	1125-23-WC	TRAILER 8 #25	<1.00
New Brunswick Middle School	07/16/2019	07/24/2019	1125-24-WC	TRAILER 6 #27	<1.00
New Brunswick Middle School	07/16/2019	07/24/2019	1125-25-WC	TRAILER #4 (#29)	1.86
New Brunswick Middle School	07/16/2019	07/24/2019	1125-26-WC	TRAILER 2 #31	1.89
New Brunswick Middle School	07/16/2019	07/24/2019	1125-27-WC	TRAILER #1 (#30)	1.13
New Brunswick Middle School	07/16/2019	07/24/2019	1125-28-WC	TRAILER 3 #28	<1.00
New Brunswick Middle School	07/16/2019	07/24/2019	1125-29-WC	TRAILER 5 #26	<1.00
New Brunswick Middle School	07/16/2019	07/24/2019	1125-30-WC	TRAILER #7 (#24)	<1.00
New Brunswick Middle School	07/16/2019	07/24/2019	1125-31-S	STORAGE RM QC	<1.00
New Brunswick Middle School	07/16/2019	07/24/2019	1125-32-S	TRAINERS ROOM	1.61

Appendix D Floor Plan(s)

Appendix E Laboratory Data



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-08-00682

Received Date: 08/05/2019
Reported Date: 08/09/2019
Sampled By: Mark Franz
Tech Certification #: 003265

Project/Test Address: 190808; New Brunswick High School; New Brunswick, NJ 08901

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-08-00682-001	12	08/01/2019	KITCHEN SINK	4.46	08/07/2019	
19-08-00682-002	15	08/01/2019	RM 127 RT WC	1.87	08/07/2019	
19-08-00682-003	19	08/01/2019	RM L 100 RT WC	10.4	08/07/2019	
19-08-00682-004	44	08/01/2019	KITCHEN POT FILLER	10.7	08/07/2019	
19-08-00682-005	18	08/01/2019	RM L 100 WC	1.82	08/07/2019	

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion




WaterSmart® Pro

LEAD ONLY

EHS Laboratories™
Environmental Hazards Services, LLC
www.leadlab.com
(800) 347-4010
(804) 275-4907 (fax)

7469 Whitepine Rd
Richmond, VA 23237

Chain-of-Custody
Analysis by National Testing Laboratories



19-U8-00682

Due Date:
08/12/2019
(Monday)
AE

Company Name:

LEU Corporation

Address:

1090 Bristol Rd.

City/State/Zip:

LEU Corporation

Phone: (908) 654-8068

Fax: (908) 654-8069

E-mail:

LEUresults@leucorp.com

Acct. Number:

201329

Project Name / Collection Address:

New Brunswick High School

City/State (Required):

NJ 08901

Collected by:

Mark Franz

Certification #:

003265

Well Tag # (if applicable):

8/1/19 open

Purchase Order Number:

19 0808

Relinquished by:

Mark Franz

Date:

8/1/19 open

ALL SAMPLES BELOW SHOULD BE ANALYZED FOR

LEAD

IN DRINKING WATER

Turn-around Time Required:

5 days

PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

No.	Client Sample ID APT. NUMBER	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters			LAB USE
						Field PH:	Field Chlorine:	Temperature at Time of Collection:	
1	12	Kitchen Sink	8/1/19	8 AM/PM	Pb				
2	15	Rm 127 Rt, wc		AM/PM					
3	19	Rm L100 Rt, wc		AM/PM					
4	44	Kitchen Pot Filler		AM/PM					
5	18	Rm L110, wc		9 AM/PM					
6				AM/PM					
7				AM/PM					
8				AM/PM					
9				AM/PM					
10				AM/PM					
Received by: <u>T. Walsh</u>						Date: <u>8/5/19</u>	Time: <u>1p</u>	AM/PM	
Tracking Number:						NTL Lab ID Number			



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-08-00694

Received Date: 08/05/2019
Reported Date: 08/09/2019
Sampled By: Mark Franz
Tech Certification #: 003265

Project/Test Address: 190808; 15 Van Dyke Ave; New Brunswick, NJ 08901

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-08-00694-001	15-11	08/01/2019	HALL BY RM 116 WC	4.18	08/07/2019	

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-03066

Received Date: 07/18/2019

Reported Date: 07/24/2019

Sampled By: Alex Salvador

Tech Certification #:

Project/Test Address: 190652; New Brunswick Middle School; 1125 Livingston Avenue; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-03066-001	1125-1	07/16/2019	HALLWAY BY ROOM 120	<1.00	07/24/2019	
19-07-03066-002	1125-2	07/16/2019	HALLWAY BY ROOM 107	<1.00	07/24/2019	
19-07-03066-003	1125-3	07/16/2019	MAIN OFFICE SINK	2.54	07/24/2019	
19-07-03066-004	1125-4	07/16/2019	HALLWAY BY ROOM 102	1.51	07/24/2019	
19-07-03066-005	1125-5	07/16/2019	NURSE OFFICE SINK	1.29	07/24/2019	
19-07-03066-006	1125-6	07/16/2019	HALLWAY BY NURSE	<1.00	07/24/2019	
19-07-03066-007	1125-7	07/16/2019	HALLWAY BY SECURITY	<1.00	07/24/2019	
19-07-03066-008	1125-8	07/16/2019	GIRLS LOCKER ROOM	3.94	07/24/2019	
19-07-03066-009	1125-9	07/16/2019	BOYS LOCKER ROOM	2.99	07/24/2019	
19-07-03066-010	1125-10	07/16/2019	HALL BY GYM	<1.00	07/24/2019	
19-07-03066-011	1125-11	07/16/2019	KITCHEN KETTLE 1	<1.00	07/24/2019	
19-07-03066-012	1125-12	07/16/2019	KITCHEN S	4.60	07/24/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-03066

Project/Test Address: 190652; New Brunswick Middle School; 1125 Livingston Avenue; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-03066-013	1125-14	07/16/2019	KITCHEN SINK	2.44	07/24/2019	
19-07-03066-014	1125-15	07/16/2019	CAFE WATER FOUNTAIN	<1.00	07/24/2019	
19-07-03066-015	1125-16	07/16/2019	CAFE WATER FOUNTAIN	<1.00	07/24/2019	
19-07-03066-016	1125-17	07/16/2019	HALLWAY BY AUDITORIUM RIGHT	8.73	07/24/2019	
19-07-03066-017	1125-18	07/16/2019	OUTSIDE AUDITORIUM BY ENTRANCE	4.67	07/24/2019	
19-07-03066-018	1125-19	07/16/2019	BY ROOM 203	1.23	07/24/2019	
19-07-03066-019	1125-20	07/16/2019	BY ROOM 233	2.03	07/24/2019	
19-07-03066-020	1125-21	07/16/2019	HALLWAY BY BIOLOGY	<1.00	07/24/2019	
19-07-03066-021	1125-22	07/16/2019	HALLWAY BY ROOM 221	10.6	07/24/2019	
19-07-03066-022	1125-23	07/16/2019	TRAILER 8	<1.00	07/24/2019	
19-07-03066-023	1125-24	07/16/2019	TRAILER 6	<1.00	07/24/2019	
19-07-03066-024	1125-25	07/16/2019	TRAILER 4	1.86	07/24/2019	
19-07-03066-025	1125-26	07/16/2019	TRAILER 2	1.89	07/24/2019	
19-07-03066-026	1125-27	07/16/2019	TRAILER 1	1.13	07/24/2019	
19-07-03066-027	1125-28	07/16/2019	TRAILER 3	<1.00	07/24/2019	
19-07-03066-028	1125-29	07/16/2019	TRAILER 5	<1.00	07/24/2019	
19-07-03066-029	1125-30	07/16/2019	TRAILER 7	<1.00	07/24/2019	
19-07-03066-030	1125-31	07/16/2019	STORAGE ROOM	<1.00	07/24/2019	
19-07-03066-031	1125-32	07/16/2019	TRAINERS ROOM	1.61	07/24/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-03066

Project/Test Address: 190652; New Brunswick Middle School; 1125 Livingston Avenue; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
-------------------	------------------	-----------------	---------------------	--------------------------	---------------	--------------

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.


The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com



19-07-03066

Due Date:
07/25/2019
(Thursday)
AE



Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address:

New Brunswick-Middle School 1125 Livingston Avenue
City/State/Zip: New Brunswick NJ

Project #: 196652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	1125-1	Hallway by Rm 126	7/16/19	8:10	AM/PM					
2	2	Hallway by Rm 107		11	AM/PM					
3	3	Main office Sink		12	AM/PM					
4	4	Hallway by Rm 162		13	AM/PM					
5	5	Nurse office Sink		14	AM/PM					
6	6	Hallway by Nurse		15	AM/PM					
7	7	Hallway by Security		16	AM/PM					
8	8	girls lockers Room		17	AM/PM					
9	9	Boys lockers Room		18	AM/PM					
10	10	Hall by gym		19	AM/PM					

Released by: Alex Salvador
Signature: [Signature]
Date/Time: 7/16/19

Received by: E. Glade
Signature: [Signature]
Date/Time: 7-18-19 @ 12:14pm



EHS
Laboratories™
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: New Brunswick Middle School 1125 Livingston Avenue
City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead	Metals			Field Parameters			LAB USE	
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	Temp at Time of Receipt:		
No.	Client Sample ID	Collection Location (Eic: Kitchen Sink)	Collection Date	Collection Time								
1	1125-11	Kitchen Kettle-1	7/16/19	8:21 AM / PM								
2	12	Kitchen S		22 AM / PM								
3	14	Kitchen Sink		24 AM / PM								
4	15	Cafe water Fountain		25 AM / PM								
5	16	Cafe water Fountain		26 AM / PM								
6	17	Hallway by Audition Right		27 AM / PM								
7	18	Outside Audition by entrance		28 AM / PM								
8	19	By Rm 203		29 AM / PM								
9	20	By Rm 233		31 AM / PM								
10	21	Hallway by Biology		32 AM / PM								
Released by: Alex Salvador		Signature:		Date/Time: 7/16/19								
Released by:		Signature:		Date/Time: 7-18-19 01:24 pm								



EHS
Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: New Brunswick Middle School 1125 Livingston Avenue
City/State/Zip: New Brunswick NJ

Project #: 190652 Sampled By: Alex Salvador License # (If Required):

Water Source: (Check One) Public ☒ Well ☐ Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround - Call Ahead
---	------------------	------------------	------------------	-------------------------------

No.	Client Sample ID	Collection Location (Exc: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	1125-22	Hallway by Rm 221	7/16/14	8:33	AM / PM					
2	23	Trailers		34	AM / PM					
3	24			35	AM / PM					
4	25			36	AM / PM					
5	26			38	AM / PM					
6	27			46	AM / PM					
7	28			41	AM / PM					
8	29			44	AM / PM					
9	30			46	AM / PM					
10	31	Storage Rm		48	AM / PM					

Released by: Alex Salvador Signature: [Signature] Date/Time: 7/16/14

Released by: E.H. Signature: [Signature] Date/Time: 7-18-14 2:44pm



ENVIRONMENTAL HAZARDS SERVICES, LLC

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237

Phone: (800) 347-4010 FAX: (804) 275-4907

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908) 654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: New Brunswick Middle School 125 Livingston Avenue

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One)

Public ☒

Well ☐

Well Tag # (If Applicable):

☒ 5 Day Turnaround

☐ 3 Day Turnaround

☐ 2 Day Turnaround

☐ 1 Day Turnaround - Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE Temp at Time of Receipt:
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	1125-32	Trainers Rm	7/14/19	8:50	AM/PM	☒				
2					AM/PM					
3					AM/PM					
4					AM/PM					
5					AM/PM					
6					AM/PM					
7					AM/PM					
8					AM/PM					
9					AM/PM					
10					AM/PM					

Released by: <u>Alex Salvador</u>	Signature: <u>[Signature]</u>	Date/Time: <u>7/14/19</u>
Released by: <u>EG</u>	Signature: <u>[Signature]</u>	Date/Time: <u>7-18-19 01:14pm</u>



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-00202

Received Date: 07/01/2019
Reported Date: 07/05/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; Building 40-P-Tech; 40 Van Dyke Avenue; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00202-001	40-1	06/28/2019	NURSES OFFICE 1	2.00	07/03/2019	
19-07-00202-002	40-2	06/28/2019	ROOM 152 2	<1.00	07/03/2019	
19-07-00202-003	40-3	06/28/2019	ROOM 154 3	<1.00	07/03/2019	
19-07-00202-004	40-4	06/28/2019	ROOM 155 4	<1.00	07/03/2019	
19-07-00202-005	40-5	06/28/2019	ROOM 169 5	<1.00	07/03/2019	
19-07-00202-006	40-6	06/28/2019	ROOM 170 6	1.16	07/03/2019	
19-07-00202-007	40-7	06/28/2019	ROOM 173 7	<1.00	07/03/2019	
19-07-00202-008	40-8	06/28/2019	HALL BY RM 108 RIGHT 8	<1.00	07/03/2019	
19-07-00202-009	40-9	06/28/2019	HALLWAY BY 134 RIGHT 9	<1.00	07/03/2019	
19-07-00202-010	40-10	06/28/2019	HALLWAY BY GIRLS RM RIGHT 10	<1.00	07/03/2019	
19-07-00202-011	40-11	06/28/2019	HALLWAY BY CAFE 163 11	<1.00	07/03/2019	
19-07-00202-012	40-12	06/28/2019	KITCHEN 01 12	<1.00	07/03/2019	
19-07-00202-013	40-13	06/28/2019	KITCHEN 01 13	2.85	07/03/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-00202

Project/Test Address: 190652; Building 40-P-Tech; 40 Van Dyke Avenue; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00202-014	40-14	06/28/2019	STORAGE ROOM 14	2.43	07/03/2019	

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.


The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com



19-07-00202

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

gt

Due Date:
07/09/2019
(Tuesday)
AE



Project Name / Collection Address: (Required)

Building 40-P-Tech 40 Van Dyke Avenue

City/State/Zip: (Required)

New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X 5 Day Turnaround

3 Day Turnaround

2 Day Turnaround

1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Exc: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE	
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:		Temp at Time of Receipt:
1	40-1	Nurses office	#1	6/28/19	10:30	AM/PM					
2	2	Room 152	#2			AM/PM					
3	3	154	#3			AM/PM					
4	4	155	#4			AM/PM					
5	5	169	#5			AM/PM					
6	6	170	#6			AM/PM					
7	7	173	#7			AM/PM					
8	8	Hallway from 108 Right	#8			AM/PM					
9	9	Hallway by 134 Right	#9			AM/PM					
10	10	Hallway by girls room Right	#10			AM/PM					
Released by: Alex Salvador		Signature: [Signature]		Date/Time: 6/28/19		Date/Time:		Date/Time:			



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

19-07-00262
~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address:

Building 40 P-Tech 40 Van Dyke Avenue

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time						
1	40-11	Hallway by cafe 163 #11	6/28/19	10:30 AM / PM						
2	12	Kitchen 01 #12		AM / PM						
3	13	Kitchen 01 #13		AM / PM						
4	14	Storage Room #14		AM / PM						
5				AM / PM						
6				AM / PM						
7				AM / PM						
8				AM / PM						
9				AM / PM						
10				AM / PM						
Released by: Alex Salvador		Signature: [Signature]		Date/Time: 6/28/19						
Released by: [Signature]		Signature: [Signature]		Date/Time: 6/28/19						



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-00203

Received Date: 07/01/2019
Reported Date: 07/05/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; Adult Learning Center; 268 Baldwin St; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00203-001	ALC-1	06/28/2019	SECURITY HALL FOUNTAIN RIGHT 1	<1.00	07/03/2019	
19-07-00203-002	ALC-2	06/28/2019	KITCHEN 2	<1.00	07/03/2019	
19-07-00203-003	ALC-3	06/28/2019	NURSE OFFICE 3	<1.00	07/03/2019	
19-07-00203-004	ALC-4	06/28/2019	HALL BY CUSTODIAN LEFT 4	<1.00	07/03/2019	
19-07-00203-005	ALC-5	06/28/2019	TEACHERS LOUNGE 5	<1.00	07/03/2019	
19-07-00203-006	ALC-6	06/28/2019	HALL BY ROOM 214 RIGHT 6	<1.00	07/03/2019	
19-07-00203-007	ALC-7	06/28/2019	HALLWAY BY GIRLS RM LEFT 7	<1.00	07/03/2019	
19-07-00203-008	ALC-8	06/28/2019	STAFF LOUNGE 8	<1.00	07/03/2019	
19-07-00203-009	ALC-9	06/28/2019	STORAGE ROOM 9	<1.00	07/03/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-00203

Project/Test Address: 190652; Adult Learning Center; 268 Baldwin St; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
-------------------	------------------	-----------------	---------------------	--------------------------	---------------	--------------

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

19-07-00203



Due Date:
07/09/2019
(Tuesday)
AE

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Adult Learning Center 268 Baldwin St

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
No.	Client Sample ID	Collection Location (Exc: Kitchen Sink)	Collection Date	Collection Time						
1	ALC-1	Security Hall Fountain #1	6/28/19	11:00 AM						
2	2	kitchen								
3	3	Nurse office								
4	4	Hall by Custodian left								
5	5	Teacher's lounge								
6	6	Hall by Room 219 right								
7	7	Hallway by girls Rn left								
8	8	Staff lounge								
9	9	Storage Room								
10										

Released by: Alex Salvador Signature: [Signature] Date/Time: 6/28/19

Released by: Green Signature: [Signature] Date/Time: 7/1/19 1:35



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-00204

Received Date: 07/01/2019
Reported Date: 07/05/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; McKinley Kindergarten; 21 Van Dyke Ave; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00204-001	MS-21-7	06/28/2019	ROOM 100A 7	1.81	07/03/2019	
19-07-00204-002	MS-21-6	06/28/2019	ROOM 103A 6	<1.00	07/03/2019	
19-07-00204-003	MS-21-5	06/28/2019	ROOM 106A 5	1.08	07/03/2019	
19-07-00204-004	MS-21-11	06/28/2019	ROOM 145A 11	1.20	07/03/2019	
19-07-00204-005	MS-21-4	06/28/2019	ROOM 109A 4	<1.00	07/03/2019	
19-07-00204-006	MS-21-17	06/28/2019	NURSES OFFICE 17	1.32	07/03/2019	
19-07-00204-007	MS-21-3	06/28/2019	ROOM 112A 3	1.24	07/03/2019	
19-07-00204-008	MS-21-2	06/28/2019	HALL BY ROOM 126 2	<1.00	07/03/2019	
19-07-00204-009	MS-21-1	06/28/2019	ROOM 128A 1	<1.00	07/03/2019	
19-07-00204-010	MS-21-10	06/28/2019	HALL BY ROOM A 212 10	<1.00	07/03/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-00204

Project/Test Address: 190652; McKinley Kindergarten; 21 Van Dyke Ave; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
-------------------	------------------	-----------------	---------------------	--------------------------	---------------	--------------

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



EHS Laboratories™
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com



19-07-00204

Due Date:
07/08/2019
(Monday)

AE

(Handwritten: TRUE)

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: McKinley Kindergarten 21 Van Dyke Ave

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

☒ 5 Day Turnaround

☐ 3 Day Turnaround

☐ 2 Day Turnaround

☐ 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	MS-21-7	Room 100A #7	6/28/19	10:15						
2		103A #6								
3		106A #5								
4		145A #11								
5		109A #4								
6		Nurses Office #17								
7		Room 112A #3								
8		Hall by Room 126 #2								
9		Room 128A #1								
10		Hall by Room A 212 #10								

Released by: Alex Salvador

Signature: *(Handwritten Signature)*

Date/Time: 6/28/19



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-00216

Received Date: 07/01/2019
Reported Date: 07/05/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; McKinley Kindergarten; 21 Van Dyke Ave; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00216-001	MS-21-8	06/28/2019	ROOM 219A 8	<1.00	07/05/2019	
19-07-00216-002	MS-21-9	06/28/2019	ROOM 220A 9	<1.00	07/05/2019	
19-07-00216-003	MS-21-12	06/28/2019	ROOM 212A 12	<1.00	07/05/2019	
19-07-00216-004	MS-21-13	06/28/2019	ROOM 209A 13	<1.00	07/05/2019	
19-07-00216-005	MS-21-18	06/28/2019	ROOM 229 18	5.94	07/05/2019	
19-07-00216-006	MS-21-14	06/28/2019	ROOM 206 14	<1.00	07/05/2019	
19-07-00216-007	MS-21-16	06/28/2019	ROOM 203 16	1.61	07/05/2019	
19-07-00216-008	MS-21-15	06/28/2019	ROOM 200 15	2.21	07/05/2019	
19-07-00216-009	MS-21-00	06/28/2019	STORAGE ROOM 00	<1.00	07/05/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-00216

Project/Test Address: 190652; McKinley Kindergarten; 21 Van Dyke Ave; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
-------------------	------------------	-----------------	---------------------	--------------------------	---------------	--------------

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com



19-07-00216

Due Date:
07/09/2019
(Tuesday)
AE



Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: McKenley Kindergarten 21 Van Dyke Av

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salgado

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time						
1	MS-21-8	Room 219 A #8	6/28/19	10:45	AM/PM					
2	9	220 A #9			AM/PM					
3	12	212 A #12			AM/PM					
4	13	209 A #13			AM/PM					
5	18	229 #18			AM/PM					
6	14	206 #14			AM/PM					
7	16	203 #16			AM/PM					
8	15	200 #15			AM/PM					
9	↓ -00	↓ Storage Room 00	↓	↓	AM/PM					
10					AM/PM					

Released by: Alex Salgado Signature: [Signature] Date/Time: 6/28/19

Released by: [Signature] Signature: [Signature] Date/Time: 6/28/19



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-00221

Received Date: 07/01/2019
Reported Date: 07/05/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; McKinley; McKinley PK; 15 Van Dyke Ave; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00221-001	MS-15-1	06/28/2019	LIBRARY OFFICE 109A 1	2.04	07/05/2019	
19-07-00221-002	MS-15-2	06/28/2019	ROOM 110 2	1.31	07/05/2019	
19-07-00221-003	MS-15-4	06/28/2019	ROOM 111 4	3.60	07/05/2019	
19-07-00221-004	MS-15-5	06/28/2019	ROOM 119 5	<1.00	07/05/2019	
19-07-00221-005	MS-15-6	06/28/2019	ROOM 112 6	<1.00	07/05/2019	
19-07-00221-006	MS-15-7	06/28/2019	ROOM 118 7	<1.00	07/05/2019	
19-07-00221-007	MS-15-8	06/28/2019	ROOM 113 8	<1.00	07/05/2019	
19-07-00221-008	MS-15-9	06/28/2019	ROOM 117 9	<1.00	07/05/2019	
19-07-00221-009	MS-15-3	06/28/2019	ROOM 114 3	<1.00	07/05/2019	
19-07-00221-010	MS-15-34	06/28/2019	ROOM 115 34	<1.00	07/05/2019	
19-07-00221-011	MS-15-00	06/28/2019	STORAGE ROOM	<1.00	07/05/2019	
19-07-00221-012	MS-15-11	06/28/2019	HALL BY RM 305 11	<1.00	07/05/2019	
19-07-00221-013	MS-15-12	06/28/2019	HALL BY MAINTENANCE CLOSET RIGHT 12	<1.00	07/05/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-00221

Project/Test Address: 190652; McKinley; McKinley PK; 15 Van Dyke Ave; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00221-014	MS-15-13	06/28/2019	NURSES OFFICE 13	2.10	07/05/2019	
19-07-00221-015	MS-15-15	06/28/2019	ROOM 105 15	<1.00	07/05/2019	
19-07-00221-016	MS-15-14	06/28/2019	ROOM 106 14	1.12	07/05/2019	
19-07-00221-017	MS-15-16	06/28/2019	ROOM 104 16	<1.00	07/05/2019	
19-07-00221-018	MS-15-17	06/28/2019	ROOM 103 17	7.29	07/05/2019	
19-07-00221-019	MS-15-18	06/28/2019	ROOM 102 18	1.06	07/05/2019	
19-07-00221-020	MS-15-19	06/28/2019	ROOM 101 19	<1.00	07/05/2019	
19-07-00221-021	MS-15-21	06/28/2019	MAIN OFFICE 21	1.52	07/05/2019	
19-07-00221-022	MS-15-33	06/28/2019	HALL BY RM 328D 33	1.21	07/05/2019	
19-07-00221-023	MS-15-20	06/28/2019	HALL BY RM 316 RIGHT 20	<1.00	07/05/2019	
19-07-00221-024	MS-15-22	06/28/2019	HALL BY RM 320 RIGHT 22	1.10	07/05/2019	
19-07-00221-025	MS-15-23	06/28/2019	HALL BY AUDITORIUM LEFT 23	<1.00	07/05/2019	
19-07-00221-026	MS-15-24	06/28/2019	COMMUNITY RM RIGHT 24	1.25	07/05/2019	
19-07-00221-027	MS-15-25	06/28/2019	COMMUNITY RM KITCHEN 25	3.23	07/05/2019	
19-07-00221-028	MS-15-26	06/28/2019	GYM 26	<1.00	07/05/2019	
19-07-00221-029	MS-15-27	06/28/2019	FACULTY DINING 27	<1.00	07/05/2019	
19-07-00221-030	MS-15-32	06/28/2019	KITCHEN KETTLE 32	1.46	07/05/2019	
19-07-00221-031	MS-15-28	06/28/2019	KITCHEN 28	<1.00	07/05/2019	
19-07-00221-032	MS-15-29	06/28/2019	KITCHEN 29	3.79	07/05/2019	
19-07-00221-033	MS-15-30	06/28/2019	TEACHERS LOUNGE 30	2.91	07/05/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-00221

Project/Test Address: 190652; McKinley; McKinley PK; 15 Van Dyke Ave; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00221-034	MS-15-35	06/28/2019	ROOM 201 35	<1.00	07/05/2019	
19-07-00221-035	MS-15-36	06/28/2019	ROOM 202 36	<1.00	07/05/2019	
19-07-00221-036	MS-15-37	06/28/2019	ROOM 209 37	<1.00	07/05/2019	
19-07-00221-037	MS-15-38	06/28/2019	ROOM 210 38	<1.00	07/05/2019	
19-07-00221-038	MS-15-39	06/28/2019	ROOM 203 39	<1.00	07/05/2019	
19-07-00221-039	MS-15-40	06/28/2019	ROOM 204 40	<1.00	07/05/2019	
19-07-00221-040	MS-15-41	06/28/2019	ROOM 208 41	<1.00	07/05/2019	
19-07-00221-041	MS-15-42	06/28/2019	ROOM 207 42	<1.00	07/05/2019	
19-07-00221-042	MS-15-43	06/28/2019	ROOM 205 43	<1.00	07/05/2019	
19-07-00221-043	MS-15-44	06/28/2019	ROOM 206 44	<1.00	07/05/2019	

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory: 

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com



19-07-00221

Due Date:
07/09/2019
(Tuesday)
AE

ant

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: McKinley McKinley PK 15 Van Dyke Ave

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

No.	Client Sample ID	Collection Location (Eic Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters			LAB USE	
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	Temp at Time of Receipt:		
1	MS-15-1	Library office 109 A #1	6/28/19	8:00	AM/PM							
2	2	Room 110			AM/PM							
3	4	111	#4	2	AM/PM							
4	5	119	5	3	AM/PM							
5	6	112	4	4	AM/PM							
6	7	118	7	5	AM/PM							
7	8	113	8	4	AM/PM							
8	9	117	9	1	AM/PM							
9	3	114	3	8	AM/PM							
10	34	115	34	9	AM/PM							

Released by: Alex Salvador
Signature: [Signature]
Date/Time: 6/28/19

Released by: [Signature]
Signature: [Signature]
Date/Time: 6/28/19

1 Day Turnaround * Call Ahead



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

19-07-6621
~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068)

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: McKinley/McKinley PK 15 Van Dyke Ave

City/State/Zip: (Required)

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

No.	Client Sample ID	Collection Location (Exc Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters			LAB USE	
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	Temp at Time of Receipt:		
11	MS-15-00	Storage Room	6/28/19	8:10	AM/PM							
12		Hall by Ln 305 #11		11	AM/PM							
13		Hall by Maintenance Light #12		12	AM/PM							
14		Nurses Office		13	AM/PM							
15		Room 105		14	AM/PM							
16				15	AM/PM							
17				16	AM/PM							
18				17	AM/PM							
19				18	AM/PM							
20				19	AM/PM							

Released by: Alex Salvador
Signature: [Signature]
Date/Time: 6/28/19

Released by: [Signature]
Signature: [Signature]
Date/Time: 6/28/19

Water Source: (Check One) Public ☒ Well ☐
Well Tag # (If Applicable):
1 Day Turnaround * Call Ahead



ENVIRONMENTAL HAZARDS SERVICES, LLC

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237

Phone: (800) 347-4010 FAX: (804) 275-4907

19-07-06221
~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908) 654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: McKinley McKingley PK 15 Van Dyke Av

City/State/Zip: (Required)

New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One)

Public ☒

Well ☐

Well Tag # (If Applicable):

X 5 Day Turnaround

3 Day Turnaround

2 Day Turnaround

1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
21	MS-15-21	Main Office # 21	6/28/19	9:30	AM / PM					
22	33	Hall by Rm 328D #33		31	AM / PM					
23	26	316 Right / 26		32	AM / PM					
24	22	320 Right / 22		33	AM / PM					
25	23	Hall by Auditorium left		34	AM / PM					
26	24	Community Rm Right		35	AM / PM					
27	25	Community Rm Kitchen		36	AM / PM					
28	26	Gym		37	AM / PM					
29	27	Faculty Dining		38	AM / PM					
30	32	Kitchen Kettle		39	AM / PM					

Released by: Alex Salvador
Signature: [Signature]
Date/Time: 6/28/19

Released by: Alex Salvador
Signature: [Signature]
Date/Time: 6/28/19



ENVIRONMENTAL HAZARDS SERVICES, LLC

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237

Phone: (800) 347-4010 FAX: (804) 275-4907

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address:

McKenney / McKenney PK 15 Van Dyke Av

City/State/Zip:

New Brunswick NJ

Project #: 190652

Sampled By: Alex Salceda

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

Well Tag # (If Applicable):

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
31	MS-15-28	Kitchen #28	6/28/19	10:00	AM/PM					
32	-29	Kitchen #29			AM/PM					
33	30	Backyard #30			AM/PM					
34	35	Room 209			AM/PM					
35	36	202			AM/PM					
36	37	209			AM/PM					
37	38	210			AM/PM					
38	39	203			AM/PM					
39	40	204			AM/PM					
40	41	208			AM/PM					
Released by: Alex Salceda		Signature: [Signature]		Date/Time: 6/28/19		Date/Time: 6/28/19				
Released by: Gary [Signature]		Signature: [Signature]		Date/Time: 6/28/19		Date/Time: 6/28/19				

19-07-00221



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~
K-07-00221

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: (Required)

McKenley/McKenley PK 15 Van Dyke Ave

City/State/Zip: (Required)

New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvadei

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround - Call Ahead			
				Lead	Copper	Other	
No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Field Parameters	LAB USE	
					Field pH at time of Collection:	Temp. at time of Collection:	Temp at Time of Receipt:
1	MS-15-42	Room 207 #42	6/28/19	10:20	AM/PM		
2	43	205 #43		21	AM/PM		
3	44	206 #44		22	AM/PM		
4				23	AM/PM		
5					AM/PM		
6					AM/PM		
7					AM/PM		
8					AM/PM		
9					AM/PM		
10					AM/PM		

Released by: Alex Salvadei
Signature: [Signature]
Date/Time: 6/28/19

Released by: [Signature]
Signature: [Signature]
Date/Time: 6/28/19



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-00928

Received Date: 07/05/2019
Reported Date: 07/11/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; Paul Robeson School; 199 Commercial Ave; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00928-001	199-1	07/02/2019	KITCHEN SINK	2.65	07/09/2019	
19-07-00928-002	199-2	07/02/2019	KITCHEN KETTLE SINK	<1.00	07/09/2019	
19-07-00928-003	199-3	07/02/2019	KITCHEN KETTLE SINK	18.0	07/09/2019	
19-07-00928-004	199-4	07/02/2019	ROOM 156	<1.00	07/09/2019	
19-07-00928-005	199-5	07/02/2019	ROOM 154	1.46	07/09/2019	
19-07-00928-006	199-6	07/02/2019	ROOM 157	1.14	07/09/2019	
19-07-00928-007	199-7	07/02/2019	ROOM 158	<1.00	07/09/2019	
19-07-00928-008	199-8	07/02/2019	ROOM 153	<1.00	07/09/2019	
19-07-00928-009	199-9	07/02/2019	ROOM 152	<1.00	07/09/2019	
19-07-00928-010	199-10	07/02/2019	ROOM 151	1.83	07/09/2019	
19-07-00928-011	199-11	07/02/2019	ROOM 150	1.83	07/09/2019	
19-07-00928-012	199-12	07/02/2019	ROOM 149	1.67	07/09/2019	
19-07-00928-013	199-13	07/02/2019	ROOM 148	<1.00	07/09/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-00928

Project/Test Address: 190652; Paul Robeson School; 199 Commercial Ave;
New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00928-014	199-15	07/02/2019	HALL BY ROOM 142 RIGHT	<1.00	07/09/2019	
19-07-00928-015	199-16	07/02/2019	ROOM 141	2.09	07/09/2019	
19-07-00928-016	199-17	07/02/2019	HALL BY ROOM 128	<1.00	07/09/2019	
19-07-00928-017	199-18	07/02/2019	ROOM 109	1.24	07/09/2019	
19-07-00928-018	199-19	07/02/2019	ROOM 110	1.05	07/09/2019	
19-07-00928-019	199-20	07/02/2019	ROOM 105	81.5	07/09/2019	
19-07-00928-020	199-21	07/02/2019	HALLWAY BY ROOM 102 RIGHT	<1.00	07/09/2019	
19-07-00928-021	199-22	07/02/2019	NURSE OFFICE	<1.00	07/09/2019	
19-07-00928-022	199-23	07/02/2019	NURSE OFFICE	1.19	07/09/2019	
19-07-00928-023	199-24	07/02/2019	ROOM 241	1.28	07/09/2019	
19-07-00928-024	199-25	07/02/2019	ROOM 238	1.18	07/09/2019	
19-07-00928-025	199-26	07/02/2019	ROOM 237	1.58	07/09/2019	
19-07-00928-026	199-27	07/02/2019	ROOM 236	<1.00	07/09/2019	
19-07-00928-027	199-28	07/02/2019	ROOM 242	1.21	07/09/2019	
19-07-00928-028	199-29	07/02/2019	ROOM 243	<1.00	07/09/2019	
19-07-00928-029	199-30	07/02/2019	ROOM 232	1.62	07/09/2019	
19-07-00928-030	199-31	07/02/2019	ROOM 230	<1.00	07/09/2019	
19-07-00928-031	199-32	07/02/2019	HALL BY ROOM 244 LEFT	<1.00	07/09/2019	
19-07-00928-032	199-33	07/02/2019	ROOM 210	4.45	07/09/2019	
19-07-00928-033	199-34	07/02/2019	ROOM 208	7.43	07/09/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-00928

Project/Test Address: 190652; Paul Robeson School; 199 Commercial Ave;
New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00928-034	199-35	07/02/2019	ROOM 211	15.5	07/09/2019	
19-07-00928-035	199-36	07/02/2019	ROOM 207	3.30	07/09/2019	
19-07-00928-036	199-37	07/02/2019	ROOM 206	8.02	07/10/2019	
19-07-00928-037	199-38	07/02/2019	ROOM 212	2.88	07/10/2019	
19-07-00928-038	199-39	07/02/2019	ROOM 213	5.09	07/10/2019	
19-07-00928-039	199-40	07/02/2019	HALLWAY BY ROOM 213 RIGHT	<1.00	07/10/2019	
19-07-00928-040	199-41	07/02/2019	ROOM 205	4.19	07/10/2019	
19-07-00928-041	199-42	07/02/2019	ROOM 204	9.05	07/10/2019	
19-07-00928-042	199-43	07/02/2019	ROOM 203	3.72	07/10/2019	
19-07-00928-043	199-44	07/02/2019	ROOM 202	18.2	07/10/2019	
19-07-00928-044	199-45	07/02/2019	ROOM 201	4.45	07/10/2019	
19-07-00928-045	199-46	07/02/2019	ROOM 217	6.33	07/10/2019	
19-07-00928-046	199-47	07/02/2019	ROOM 218	3.51	07/10/2019	
19-07-00928-047	199-48	07/02/2019	HALL BY ROOM 303 RIGHT	<1.00	07/10/2019	
19-07-00928-048	199-49	07/02/2019	HALL BY ROOM 312 RIGHT	<1.00	07/10/2019	
19-07-00928-049	199-50	07/02/2019	STORAGE ROOM	<1.00	07/10/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-00928

Project/Test Address: 190652; Paul Robeson School; 199 Commercial Ave;
New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
----------------------	---------------------	--------------------	---------------------	-----------------------------	------------------	-----------------

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

19-07-00928



Due Date:
07/12/2019
(Friday)
AE

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: (Required)

Paul Robeson School 199 Commercial Ave

City/State/Zip: (Required)

New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time						
1	199-1	kitchen sink	7/2/19	11:01	AM/PM					
2	2	kitchen kettle sink		2	AM/PM					
3	3	kitchen kettle sink		3	AM/PM					
4	4	Room 156		4	AM/PM					
5	5	Room 154		5	AM/PM					
6	6	157		6	AM/PM					
7	7	158		7	AM/PM					
8	8	153		8	AM/PM					
9	9	152		9	AM/PM					
10	10	151		10	AM/PM					

Released by: Alex Salvador
Signature: [Signature]
Date/Time: 7/2/19

Released by: [Signature]
Date/Time: 7/2/19



EHS Laboratories

ENVIRONMENTAL HAZARDS SERVICES, LLC

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237

Phone: (800) 347-4010 FAX: (804) 275-4907

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908) 654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Paul Robeson School 199 Commercial Avenue

City/State/Zip: New Brunswick NJ

Project #: 190652 Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time						
1	199-11	Room 150	7/2/19	11:11	AM/PM					
2	12	148		12	AM/PM					
3	13	148		13	AM/PM					
4	14	N/A		14	AM/PM					
5	15	Hall by Room 142 Right		15	AM/PM					
6	16	Room 141		16	AM/PM					
7	17	Hall by Room 128		17	AM/PM					
8	18	Room 109		18	AM/PM					
9	19	Room 110		19	AM/PM					
10	20	Room 105		20	AM/PM					
Released by: Alex Salvador		Signature: [Signature]		Date/Time: 7/2/19						

Green 7/5/19 12:30



EHS Laboratories™

ENVIRONMENTAL HAZARDS SERVICES, LLC

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237

Phone: (800) 347-4010 FAX: (804) 275-4907

19-67-00928
~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908) 654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Paul Robeson School 199 Commercial Avenue

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time						
1	199-21	Hallway by Room 102	7/2/19	11:21	AM/PM					
2	22	Nurse office		23	AM/PM					
3	23	Nurse office		24	AM/PM					
4	24	Room 241		25	AM/PM					
5	25			26	AM/PM					
6	26			27	AM/PM					
7	27			28	AM/PM					
8	28			29	AM/PM					
9	29			30	AM/PM					
10	30			31	AM/PM					
Released by: Alex Salvador					Signature: [Signature]			Date/Time: 7/2/19		
Released by:					Signature:			Date/Time:		

CEU 7/2 7/5/19 12:30



TELEPHONE: (800) 577-7010 FAX: (804) 213-4501

SHIP TR: 7469 Whitening Rd Richmond VA 22227

Phone: (800) 347-4010 FAX: (800) 275-1907

19-07-08928

For Lab Use Only

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Law Nelson School 199 Commercial Avenue

City/State/Zip: New Brunswick NJ

City/State

Project #: 190652

Sampled By: Alex Salgado

License # (If Required):

Water Source: (Check One) Public X
(Required)

X

ell

Well Tag # (If Applicable):

X		5 Day Turnaround		3 Day Turnaround		2 Day Turnaround		1 Day Turnaround * Call Ahead		
No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE Temp at Time of Receipt:
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	199-31	Room 230	7/2/19	11:32						
2	32	Hall by Room 244 left		33	AM / PM					
3	33	Room 210		34	AM / PM					
4	34			35	AM / PM					
5	35			36	AM / PM					
6	36			37	AM / PM					
7	37			38	AM / PM					
8	38			39	AM / PM					
9	39			40	AM / PM					
10	40	Hallway by Room 213 right		41	AM / PM					
Released by: Alex Salvador		Signature: [Signature]		Date/Time: 7/2/19						



ENVIRONMENTAL HAZARDS SERVICES, LLC

Company Name: LEW CORP

Address: 181 US Highway 46

Phone: (908-654-8068)

Email: labresults@lewcorp.com

Fax: 908-654-8069

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237

Phone: (800) 347-4010 FAX: (804) 275-4907

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

Project Name / Collection Address (Required)

Sampled By:

License # (If Required):

Paul Robeson School 199 Commercial Avenue

City/State/Zip: New Brunswick NJ

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead	Metals			Field Parameters		LAB USE	
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:		Temp at Time of Receipt:
No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time							
1	199-41	Room 205	7/2/19	11:43	AM/PM						
2	42	204		44	AM/PM						
3	43	203		45	AM/PM						
4	44	202		46	AM/PM						
5	45	201		47	AM/PM						
6	46	217		48	AM/PM						
7	47	218		49	AM/PM						
8	48	Hall by Room 303 right		50	AM/PM						
9	49	Hall by Room 312 right		51	AM/PM						
10	50	Storage Room		52	AM/PM						
Released by: Alex Salvador					Signature: [Signature]					Date/Time: 7/2/19	
Released by: Alex Salvador					Signature: [Signature]					Date/Time: 7/2/19	

Collected 7/2/19 12:30



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-00942

Received Date: 07/05/2019
Reported Date: 07/09/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; Health Science Tech HS; 165 Bayard St.; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00942-001	HSTHS-1	07/02/2019	CAFETERIA	<1.00	07/08/2019	
19-07-00942-002	HSTHS-2	07/02/2019	HALL BY ROOM 109 RIGHT	<1.00	07/08/2019	
19-07-00942-003	HSTHS-3	07/02/2019	NURSES OFFICE	1.11	07/08/2019	
19-07-00942-004	HSTHS-4	07/02/2019	TEACHERS LOUNGE	<1.00	07/08/2019	
19-07-00942-005	HSTHS-5	07/02/2019	HALL BY TEACHERS LOUNGE	<1.00	07/08/2019	
19-07-00942-006	HSTHS-6	07/02/2019	HALL BY ROOM307	<1.00	07/08/2019	
19-07-00942-007	HSTHS-7	07/02/2019	STORAGE ROOM	<1.00	07/08/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-00942

Project/Test Address: 190652; Health Science Tech HS; 165 Bayard St.; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
-------------------	------------------	-----------------	---------------------	--------------------------	---------------	--------------

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:



Tasha Eaddy

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



ENVIRONMENTAL HAZARDS SERVICES, LLC

Company Name: LEW CORP

Address: 181 US Highway 46

Phone: (908-654-8068

Email: labresults@lewcorp.com

Project Name / Collection Address: Health Science Tech HS 165 Bayand St

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237

Phone: (800) 347-4010 FAX: (804) 275-4907


ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

Account #: 201327

City/State/Zip: Mine Hill, NJ 07803

Fax: 908-654-8069

City/State/Zip: New Brunswick NJ



19-07-00942

Due Date:

07/12/2019

(Friday)

AE

☒ 5 Day Turnaround	☐ 3 Day Turnaround	☐ 2 Day Turnaround	☐ 1 Day Turnaround * Call Ahead
--	---	---	--

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	HSTHS-1	cafeteria	7/2/19	10:01	AM/PM					
2	2	Hall by Room 109 Right		3	AM/PM					
3	3	Nurses Office		4	AM/PM					
4	4	Teachers lounge		5	AM/PM					
5	5	Hall by Teachers lounge		6	AM/PM					
6	6	Hall by Room 307		7	AM/PM					
7	7	Storage Room		9	AM/PM					
8					AM/PM					
9					AM/PM					
10					AM/PM					

Released by: Alex Salvador

Signature:

Date/Time:

7/2/19

Released by:

Signature:

Date/Time:

Alex Salvador 7/5/19 12:14



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-00945

Received Date: 07/05/2019
Reported Date: 07/09/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; Lord Stirling Community School; 101 Redmond St.; New Brunswick,
NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00945-001	101-1	07/02/2019	CAFETERIA LEFT	<1.00	07/08/2019	
19-07-00945-002	101-2	07/02/2019	KITCHEN KETTLE	<1.00	07/08/2019	
19-07-00945-003	101-3	07/02/2019	KITCHEN SINK	1.27	07/08/2019	
19-07-00945-004	101-4	07/02/2019	MAIN OFFICE WORK ROOM	<1.00	07/08/2019	
19-07-00945-005	101-5	07/02/2019	NURSE OFFICE	<1.00	07/08/2019	
19-07-00945-006	101-6	07/02/2019	HALL BY ROOM 210 LEFT	<1.00	07/08/2019	
19-07-00945-007	101-7	07/02/2019	ROOM 206	<1.00	07/08/2019	
19-07-00945-008	101-8	07/02/2019	ROOM 232	2.28	07/08/2019	
19-07-00945-009	101-9	07/02/2019	FACULTY LOUNGE	<1.00	07/08/2019	
19-07-00945-010	101-10	07/02/2019	BOYS LOCKER ROOM LEFT	<1.00	07/08/2019	
19-07-00945-011	101-11	07/02/2019	GIRLS LOCKER ROOM LEFT	<1.00	07/08/2019	
19-07-00945-012	101-12	07/02/2019	HALLWAY BY GYM LEFT	<1.00	07/08/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-00945

Project/Test Address: 190652; Lord Stirling Community School; 101 Redmond St.; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00945-013	101-13	07/02/2019	ROOM 124	<1.00	07/08/2019	
19-07-00945-014	101-14	07/02/2019	ROOM 123	<1.00	07/08/2019	
19-07-00945-015	101-15	07/02/2019	ROOM 122	1.11	07/08/2019	
19-07-00945-016	101-16	07/02/2019	ROOM 120	<1.00	07/08/2019	
19-07-00945-017	101-17	07/02/2019	ROOM 119	<1.00	07/08/2019	
19-07-00945-018	101-18	07/02/2019	ROOM 106	6.26	07/08/2019	
19-07-00945-019	101-19	07/02/2019	HALL BY ROOM 118 LEFT	<1.00	07/08/2019	
19-07-00945-020	101-20	07/02/2019	STORAGE ROOM	<1.00	07/08/2019	

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:



Tasha Eaddy

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com



Due Date:
07/12/2019
(Friday)
AE

Company Name: LEW CORP Account #: 201327

Address: 181 US Highway 46 City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: Lord Shering Community School 101 Redmond St City/State/Zip: New Brunswick NJ
(Required)

Project #: 190652 Sampled By: Alex Salvador License # (If Required): _____

Water Source: (Check One) Public ☒ Well _____ Well Tag # (If Applicable): _____
(Required)

☒ 5 Day Turnaround	☐ 3 Day Turnaround	☐ 2 Day Turnaround	☐ 1 Day Turnaround * Call Ahead
--	---	---	--

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	101-1	Cabotonia Left	7/2/19	10:30	AM/PM					
2	2	kitchen kettle		31	AM/PM					
3	3	kitchen sink		32	AM/PM					
4	4	Main office work Room		33	AM/PM					
5	5	Nurse office		34	AM/PM					
6	6	Hall by Room 210 Left		35	AM/PM					
7	7	Room 206		36	AM/PM					
8	8	Room 232		37	AM/PM					
9	9	Faculty Lounge		38	AM/PM					
10	10	Boys locker Room Left		39	AM/PM					
Released by: Alex Salvador		Signature:		Date/Time: 7/2/19		Date/Time: _____				

Green 7/2-7/5/19 12:45



ENVIRONMENTAL HAZARDS SERVICES, LLC

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907

~ FR

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908) 654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Lord Stirling Community School 101 Redmond St

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

☒ 5 Day Turnaround

☐ 3 Day Turnaround

☐ 2 Day Turnaround

☐ 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	101-11	girls locker room left	7/2/19	10:40	AM/PM					
2	12	hallway by gym left		41	AM/PM					
3	13	Room 124		42	AM/PM					
4	14			43	AM/PM					
5	15			44	AM/PM					
6	16			45	AM/PM					
7	17			46	AM/PM					
8	18			47	AM/PM					
9	19	hall by Room 118 left		48	AM/PM					
10	20	Storage Room		49	AM/PM					
Released by: <u>Alex Salvador</u>		Signature: <u>[Signature]</u>		Date/Time: <u>7/2/19</u>						
Released by: <u>[Signature]</u>		Signature: <u>[Signature]</u>		Date/Time: <u>7/2/19</u>						

SPEN 3/13 7/5/19 12:45

19-07-00945



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-00948

Received Date: 07/05/2019
Reported Date: 07/11/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; Lincoln Elementary School; 66 Barlett St; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00948-001	LINCOLN-66-1	07/02/2019	HALL BY FACULTY REST RM RIGHT	<1.00	07/09/2019	
19-07-00948-002	LINCOLN-66-2	07/02/2019	BASEMENT KITCHEN	1.38	07/09/2019	
19-07-00948-003	LINCOLN-66-3	07/02/2019	HALL BY ROOM 205	<1.00	07/09/2019	
19-07-00948-004	LINCOLN-66-4	07/02/2019	HALL BY ROOM 211 LEFT	<1.00	07/09/2019	
19-07-00948-005	LINCOLN-66-5	07/02/2019	FACULTY ROOM LEFT	1.20	07/09/2019	
19-07-00948-006	LINCOLN-66-6	07/02/2019	NURSES OFFICE	<1.00	07/09/2019	
19-07-00948-007	LINCOLN-66-7	07/02/2019	HALLWAY BY ROOM 111 RIGHT	2.96	07/09/2019	
19-07-00948-008	LINCOLN-66-8	07/02/2019	ROOM 108	1.77	07/09/2019	
19-07-00948-009	LINCOLN-66-9	07/02/2019	ROOM 104	<1.00	07/09/2019	
19-07-00948-010	LINCOLN-66-10	07/02/2019	TRAILER 601	<1.00	07/09/2019	
19-07-00948-011	LINCOLN-66-11	07/02/2019	TRAILER 602	<1.00	07/09/2019	
19-07-00948-012	LINCOLN-66-12	07/02/2019	TRAILER 603	<1.00	07/09/2019	
19-07-00948-013	LINCOLN-66-13	07/02/2019	TRAILER 604	<1.00	07/09/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-00948

Project/Test Address: 190652; Lincoln Elementary School; 66 Barlett St; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00948-014	LINCOLN-66-14	07/02/2019	TRAILER 605	<1.00	07/09/2019	
19-07-00948-015	LINCOLN-66-15	07/02/2019	STORAGE ROOM	<1.00	07/09/2019	

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



ENVIRONMENTAL HAZARDS SERVICES, LLC

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237

Phone: (800) 347-4010 FAX: (804) 275-4907

City/State/Zip: Mine Hill, NJ 07803

Due Date:
07/12/2019
(Friday)
AE

Account #: 201327

Company Name: LEW CORP

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908) 654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Lincoln Elementary School 600 600 St

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead	Metals			Field Parameters		LAB USE	
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:		Temp at Time of Receipt:
1	Lincoln-60-1	Hall by Faculty Resting Right	7/2/19	9:01	AM / PM						
2		Basement Kitchen		2	AM / PM						
3		Hall by Room 205		3	AM / PM						
4		Hall by Room 211 Left		4	AM / PM						
5		Faculty Room Left		5	AM / PM						
6		Nurses office		6	AM / PM						
7		Hallway by Room 111 Right		7	AM / PM						
8		Room 108		8	AM / PM						
9		Room 104		9	AM / PM						
10		Trailer 601		10	AM / PM						
Released by: <u>Alex Salvador</u>					Signature: <u>[Signature]</u>		Date/Time: <u>7/2/19</u>				
Released by: <u>[Signature]</u>					Signature: <u>[Signature]</u>		Date/Time: <u>7/2/19</u>				

Base 7/5/19 12:45



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

19-07-00948

~ For Lab Use Only ~

Company Name: LEW CORP Account #: 201327

Address: 181 US Highway 46 City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: Lincoln Elementary School 66 Bartlett St City/State/Zip: New Brunswick NJ

Project #: 190652 Sampled By: Alex Salvador License # (If Required):

Water Source: (Check One) Public ☒ Well ☐ Well Tag # (If Applicable):

X 5 Day Turnaround 3 Day Turnaround 2 Day Turnaround 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	Lincoln-66-11	Trailer 602	7/2/19	9:11	PM					
2		12		12	AM / PM					
3		13		13	AM / PM					
4		14		14	AM / PM					
5		15 Storage Room		15	AM / PM					
6				16	AM / PM					
7				17	AM / PM					
8				18	AM / PM					
9				19	AM / PM					
10				20	AM / PM					

Released by: Alex Salvador Signature: Date/Time: 7/2/19

CEH 7/5/19 12:45



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-00956

Received Date: 07/05/2019
Reported Date: 07/09/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; Lincoln Annex School; 165 Somerset St.; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-00956-001	ANNEX-165-1	07/02/2019	HALL BY ROOM 144 RIGHT	<1.00	07/08/2019	
19-07-00956-002	ANNEX-165-2	07/02/2019	HALL BY ROOM 237 RIGHT	<1.00	07/08/2019	
19-07-00956-003	ANNEX-165-3	07/02/2019	HALL BY ROOM 319 RIGHT	<1.00	07/08/2019	
19-07-00956-004	ANNEX-165-4	07/02/2019	HALL BY ROOM 204	<1.00	07/08/2019	
19-07-00956-005	ANNEX-165-5	07/02/2019	NURSE OFFICE	1.21	07/08/2019	
19-07-00956-006	ANNEX-165-6	07/02/2019	HALL BY ROOM 104	<1.00	07/08/2019	
19-07-00956-007	ANNEX-165-7	07/02/2019	HALL BY ROOM 005 RIGHT	<1.00	07/08/2019	
19-07-00956-008	ANNEX-165-8	07/02/2019	KITCHEN KETTLE	1.51	07/08/2019	
19-07-00956-009	ANNEX-165-9	07/02/2019	KITCHEN SINK	<1.00	07/08/2019	
19-07-00956-010	ANNEX-165-10	07/02/2019	KITCHEN SINK	1.18	07/08/2019	
19-07-00956-011	ANNEX-154-11	07/02/2019	STORAGE ROOM	<1.00	07/08/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-00956

Project/Test Address: 190652; Lincoln Annex School; 165 Somerset St.; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
-------------------	------------------	-----------------	---------------------	--------------------------	---------------	--------------

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:



Tasha Eaddy

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



EHS Laboratories™

ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

19-07-00956



Due Date:
07/12/2019
(Friday)

AE

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address:

Lindu Annex School 165 Somerset St

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One)

Public ☒

Well ☐

Well Tag # (If Applicable):

X 5 Day Turnaround

3 Day Turnaround

2 Day Turnaround

1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	Annex-165-1	Hall by Room 144 Right	7/2/19	10:50	AM/PM					
2		Hall by Room 237 Right		52	AM/PM					
3		Hall by Room 319 Right		53	AM/PM					
4		Hall by Room 204		54	AM/PM					
5		Nurse office		55	AM/PM					
6		Hall by Room 104		56	AM/PM					
7		Hall by Room 005 Right		57	AM/PM					
8		Kitchen Kettle		58	AM/PM					
9		Kitchen Sink		59	AM/PM					
10		Kitchen Sink		60	AM/PM					
Released by: Alex Salvador		Signature: [Signature]		Date/Time: 7/2/19						

GRN 7/2/19 1:10



EHS Laboratories™

ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237

Phone: (800) 347-4010 FAX: (804) 275-4907

ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Lincoln Annex School 165 Somerset St

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

☒ 5 Day Turnaround

☐ 3 Day Turnaround

☐ 2 Day Turnaround

☐ 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	Annex-165-11	Storage Room	7/2/19	11:00	AM/PM					
2					AM/PM					
3					AM/PM					
4					AM/PM					
5					AM/PM					
6					AM/PM					
7					AM/PM					
8					AM/PM					
9					AM/PM					
10					AM/PM					
Released by: <u>Alex Salvador</u>					Signature: <u>[Signature]</u>			Date/Time: <u>7/2/19</u>		
Released by: <u>GRE</u>					Signature: <u>[Signature]</u>			Date/Time: <u>7/2/19</u>		



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-02386

Received Date: 07/15/2019
Reported Date: 07/18/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; Woodrow Wilson Elementary School; 133 Tunison Rd; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-02386-001	133-1	07/11/2019	HALL BY ROOM 207	15.7	07/17/2019	
19-07-02386-002	133-2	07/11/2019	NURSE OFFICE	6.70	07/17/2019	
19-07-02386-003	133-3	07/11/2019	HALL BY ROOM 25	6.08	07/17/2019	
19-07-02386-004	133-4	07/11/2019	HALL BY ROOM 22	1.17	07/17/2019	
19-07-02386-005	133-5	07/11/2019	HALL BY CUSTODIAN CLOSET RIGHT	<1.00	07/17/2019	
19-07-02386-006	133-6	07/11/2019	HALL BY MAIN OFFICE RIGHT	<1.00	07/17/2019	
19-07-02386-007	133-7	07/11/2019	KITCHEN	4.03	07/17/2019	
19-07-02386-008	133-8	07/11/2019	TRAILER 2	1.40	07/17/2019	
19-07-02386-009	133-9	07/11/2019	TRAILER 3	<1.00	07/17/2019	
19-07-02386-010	133-10	07/11/2019	TRAILER 1	<1.00	07/17/2019	
19-07-02386-011	133-11	07/11/2019	TRAILER 4	<1.00	07/17/2019	
19-07-02386-012	133-12	07/11/2019	TRAILER 5	<1.00	07/17/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-02386

Project/Test Address: 190652; Woodrow Wilson Elementary School; 133
Tunison Rd; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-02386-013	133-13	07/11/2019	TRAILER 8	<1.00	07/17/2019	
19-07-02386-014	133-14	07/11/2019	TRAILER 7	<1.00	07/17/2019	
19-07-02386-015	133-15	07/11/2019	TRAILER 6	<1.00	07/17/2019	
19-07-02386-016	133-16	07/11/2019	STORAGE ROOM	<1.00	07/17/2019	

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:



Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com



19-07-02386

Due Date:

07/22/2019

(Monday)

AE

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Woodrow Wilson Elementary School 133 Tunisian Rd

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

☒ 5 Day Turnaround

☐ 3 Day Turnaround

☐ 2 Day Turnaround

☐ 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	133-1	Hall by Room 207	7/11/19	8:00	AM/PM					
2	2	Nurse office		1	AM/PM					
3	3	Hall by Room 25		2	AM/PM					
4	4	Hall by Room 22		3	AM/PM					
5	5	Hall by Custodian closet right		5	AM/PM					
6	6	Hall by main office right		8	AM/PM					
7	7	Kitchen		9	AM/PM					
8	8	Trailer 2		10	AM/PM					
9	9			11	AM/PM					
10	10			12	AM/PM					
Released by: <u>Alex Salvador</u>					Signature: <u>[Signature]</u>		Date/Time: <u>7/11/19</u>			
Released by: <u>Received by: [Signature]</u>					Signature: <u>[Signature]</u>		Date/Time: <u>7/15/19 @ 12:54 pm</u>			



EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP Account #: 201327

Address: 181 US Highway 46 City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068) Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: Woodrow Wilson Elementary School 133 Tunison Rd City/State/Zip: New Brunswick NJ

Project #: 190652 Sampled By: Alex Salvador License # (if Required):

Water Source: (Check One) Public ☒ Well ☐ Well Tag # (if Applicable):

X 5 Day Turnaround 3 Day Turnaround 2 Day Turnaround 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	133-11	Trailer 4	7/11/19	8:13	AM / PM					
2	12	5		14	AM / PM					
3	13	8		15	AM / PM					
4	14	7		16	AM / PM					
5	15	4		17	AM / PM					
6	16	Storage Room		18	AM / PM					
7					AM / PM					
8					AM / PM					
9					AM / PM					
10					AM / PM					
Released by: Alex Salvador			Signature: [Signature]		Date/Time: 7/11/19					
Released by: ECB By: E.G.			Signature: [Signature]		Date/Time: 7-15-19 0125pm					



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-02426

Received Date: 07/15/2019
Reported Date: 07/18/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; Livingston Elementary School; 206 Delavan St; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-02426-001	206-1	07/11/2019	BASEMENT LEFT HALLWAY	<1.00	07/17/2019	
19-07-02426-002	206-2	07/11/2019	BASEMENT RIGHT HALLWAY	1.56	07/17/2019	
19-07-02426-003	206-3	07/11/2019	ROOM 5	53.8	07/17/2019	
19-07-02426-004	206-4	07/11/2019	ROOM 6	1.69	07/17/2019	
19-07-02426-005	206-5	07/11/2019	KITCHEN	1.30	07/17/2019	
19-07-02426-006	206-6	07/11/2019	1ST FLOOR HALLWAY	<1.00	07/17/2019	
19-07-02426-007	206-7	07/11/2019	2ND FLOOR HALL LIBRARY	<1.00	07/17/2019	
19-07-02426-008	206-9	07/11/2019	TRAILER 2	<1.00	07/17/2019	
19-07-02426-009	206-10	07/11/2019	TRAILER 3	<1.00	07/17/2019	
19-07-02426-010	206-11	07/11/2019	TRAILER 4	<1.00	07/17/2019	
19-07-02426-011	206-12	07/11/2019	STORAGE ROOM	<1.00	07/17/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-02426

Project/Test Address: 190652; Livingston Elementary School; 206 Delavan St;
New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
----------------------	---------------------	--------------------	---------------------	-----------------------------	------------------	-----------------

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

19-07-02426



Due Date:

07/22/2019
(Monday)

AE

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

ST



Project Name / Collection Address: Livingston Elementary School 206 Delavan St
City/State/Zip: New Brunswick NJ
(Required)
Project #: 190652 Sampled By: Alex Salvador
License # (If Required):

Water Source: (Check One) Public ☒ Well ☐ Well Tag # (If Applicable):

X ☒ 5 Day Turnaround ☐ 3 Day Turnaround ☐ 2 Day Turnaround ☐ 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE	
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:		Temp at Time of Receipt:
1	206-1	Basement Left Hallway	7/11/19	10:01	AM/PM						
2	2	Basement Right Hallway		2	AM/PM						
3	3	Room 5		3	AM/PM						
4	4	Room 6		4	AM/PM						
5	5	Kitchen		5	AM/PM						
6	6	1st Floor Hallway		6	AM/PM						
7	7	2nd Floor Hall Library		7	AM/PM						
8	8	9		8	AM/PM						
9	9	10		9	AM/PM						
10	10	11		10	AM/PM						
Released by: Alex Salvador					Signature: [Signature]					Date/Time: 7/11/19	
Released by: [Signature]					Signature: [Signature]					Date/Time: 7-15-19 @ 2pm	



EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Livingston Elementary School 206 Delaware St

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

☒ 5 Day Turnaround

☐ 3 Day Turnaround

☐ 2 Day Turnaround

☐ 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	206-12	Storage Room	7/11/19	10:11	AM / PM	☒				
2					AM / PM					
3					AM / PM					
4					AM / PM					
5					AM / PM					
6					AM / PM					
7					AM / PM					
8					AM / PM					
9					AM / PM					
10					AM / PM					

Released by: <u>Alex Salvador</u>	Signature: <u>[Signature]</u>	Date/Time: <u>7/11/19</u>
Released by: <u>[Signature]</u>	Signature: <u>[Signature]</u>	Date/Time: <u>7-15-19 @ 2pm</u>



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-02451

Received Date: 07/15/2019
Reported Date: 07/18/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; Chester Ridshaw School; 216 Livingston Street; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-02451-001	216-1	07/11/2019	ROOM 102	<1.00	07/17/2019	
19-07-02451-002	216-2	07/11/2019	ROOM 104	<1.00	07/17/2019	
19-07-02451-003	216-3	07/11/2019	ROOM 105	<1.00	07/17/2019	
19-07-02451-004	216-4	07/11/2019	ROOM 106	<1.00	07/17/2019	
19-07-02451-005	216-5	07/11/2019	ROOM 107	<1.00	07/17/2019	
19-07-02451-006	216-6	07/11/2019	MAIN OFFICE	<1.00	07/17/2019	
19-07-02451-007	216-7	07/11/2019	NURSES OFFICE	<1.00	07/17/2019	
19-07-02451-008	216-8	07/11/2019	ROOM 120	<1.00	07/17/2019	
19-07-02451-009	216-9	07/11/2019	ROOM 122	<1.00	07/17/2019	
19-07-02451-010	216-10	07/11/2019	ROOM 113	<1.00	07/17/2019	
19-07-02451-011	216-11	07/11/2019	ROOM 115	1.12	07/17/2019	
19-07-02451-012	216-12	07/11/2019	ROOM 117	<1.00	07/17/2019	
19-07-02451-013	216-13	07/11/2019	ROOM 124	<1.00	07/17/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-02451

Project/Test Address: 190652; Chester Ridshaw School; 216 Livingston Street; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-02451-014	216-14	07/11/2019	ROOM 126	<1.00	07/17/2019	
19-07-02451-015	216-15	07/11/2019	HALL BY 127 RIGHT	<1.00	07/17/2019	
19-07-02451-016	216-16	07/11/2019	PLAYGROUND RIGHT	<1.00	07/17/2019	
19-07-02451-017	216-17	07/11/2019	HALL BY ROOM 154 RIGHT	<1.00	07/17/2019	
19-07-02451-018	216-18	07/11/2019	HALLWAY BY ELEVATOR RIGHT	<1.00	07/17/2019	
19-07-02451-019	216-19	07/11/2019	KITCHEN ICE MACHINE	<1.00	07/17/2019	
19-07-02451-020	216-20	07/11/2019	KITCHEN	<1.00	07/17/2019	
19-07-02451-021	216-21	07/11/2019	KITCHEN	2.69	07/17/2019	
19-07-02451-022	216-22	07/11/2019	KITCHEN	11.5	07/17/2019	
19-07-02451-023	216-23	07/11/2019	KITCHEN	<1.00	07/17/2019	
19-07-02451-024	216-24	07/11/2019	HALLWAY BY ROOM 253 RIGHT	<1.00	07/17/2019	
19-07-02451-025	216-25	07/11/2019	HALLWAY BY ROOM 231 RIGHT	<1.00	07/17/2019	
19-07-02451-026	216-26	07/11/2019	HALLWAY BY ROOM 315 RIGHT	<1.00	07/17/2019	
19-07-02451-027	216-27	07/11/2019	HALLWAY BY MEDIA CENTER	<1.00	07/17/2019	
19-07-02451-028	216-28	07/11/2019	ROOM 206	<1.00	07/17/2019	
19-07-02451-029	216-29	07/11/2019	ROOM 207	<1.00	07/17/2019	
19-07-02451-030	216-30	07/11/2019	ROOM 204	1.36	07/17/2019	
19-07-02451-031	216-31	07/11/2019	ROOM 202	<1.00	07/17/2019	
19-07-02451-032	216-32	07/11/2019	ROOM 205	<1.00	07/17/2019	
19-07-02451-033	216-33	07/11/2019	STORAGE ROOM	<1.00	07/17/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-02451

Project/Test Address: 190652; Chester Ridshaw School; 216 Livingston Street; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
-------------------	------------------	-----------------	---------------------	--------------------------	---------------	--------------

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com



19-07-02451

Due Date:

07/22/2019

(Monday)

AE

ONE

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Chesler Redshaw School 216 Livingston Street

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (if Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (if Applicable):

☒ 5 Day Turnaround

☐ 3 Day Turnaround

☐ 2 Day Turnaround

☐ 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	alb-1	Room 102	7/11/19	10:45	AM/PM					
2		104		46	AM/PM					
3		105		47	AM/PM					
4		106		48	AM/PM					
5		107		49	AM/PM					
6		Main office		50	AM/PM					
7		Nurses office		51	AM/PM					
8		Room 120		52	AM/PM					
9		Room 122		53	AM/PM					
10		Room 113		54	AM/PM					
Released by: <u>Alex Salvador</u>					Signature: <u>[Signature]</u>			Date/Time: <u>7/11/19</u>		
Revised by: <u>Erin Glauke</u>					Signature: <u>[Signature]</u>			Date/Time: <u>7-15-19 @ 2:47pm</u>		



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Chesta Rudshaw School

City/State/Zip: 216 Livingston Street
New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One)

Public ☒

Well ☐

Well Tag # (If Applicable):

☒ 5 Day Turnaround

☐ 3 Day Turnaround

☐ 2 Day Turnaround

☐ 1 Day Turnaround ⁴ Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters			LAB USE	
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	Temp at Time of Receipt:		
1	ale-11	Room 115	7/11/19	10:56	AM/PM							
2		117		57	AM/PM							
3		124		58	AM/PM							
4		126		59	AM/PM							
5		Hall by 127 right		11:01	AM/PM							
6		Playground right		2	AM/PM							
7		Hall by Room 154 right		3	AM/PM							
8		Hallway by elevator right		4	AM/PM							
9		Kitchen free machine		5	AM/PM							
10		Kitchen		6	AM/PM							
Released by: <u>Alex Salvador</u>		Signature: <u>[Signature]</u>		Date/Time: <u>7/11/19</u>								
Released by: <u>[Signature]</u>		Signature: <u>[Signature]</u>		Date/Time: <u>7-15-19 @ 2:27pm</u>								



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP Account #: 201327

Address: 181 US Highway 46 City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: Chester Rudshaw School 216 Livingston Street
City/State/Zip: New Brunswick NJ

Project #: 190652 Sampled By: Alex Salvador License # (If Required):

Water Source: (Check One) Public ☒ Well ☐ Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
No.	Client Sample ID	Collection Location (Exc: Kitchen Sink)	Collection Date	Collection Time						
1	216-21	kitchen	7/11/19	11:07	AM/PM					
2	22	kitchen		8	AM/PM					
3	23	kitchen		9	AM/PM					
4	24	Hallway by Room 253 Right		10	AM/PM					
5	25	231 Right		11	AM/PM					
6	26	315 Right		12	AM/PM					
7	27	Hallway by media center		13	AM/PM					
8	28	Room 206		14	AM/PM					
9	29	207		15	AM/PM					
10	30	204		16	AM/PM					
Released by: Alex Salvador		Signature: [Signature]		Date/Time: 7/11/19						
Released by: E. G.		Signature: [Signature]		Date/Time: 7-15-19 @ 2:30pm						



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4030 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908) 654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Chastor Redman School

210 Livingston Street

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

☒ 5 Day Turnaround

☐ 3 Day Turnaround

☐ 2 Day Turnaround

☐ 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	210-31	Room 202	7/11/19	11:17	AM / PM					
2	38	Room 205		11:18	AM / PM					
3	33	Storage Room		11:19	AM / PM					
4					AM / PM					
5					AM / PM					
6					AM / PM					
7					AM / PM					
8					AM / PM					
9					AM / PM					
10					AM / PM					

Released by: Alex Salvador Signature: [Signature] Date/Time: 7/11/19

Released by: [Signature] Signature: [Signature] Date/Time: 7-15-19 02:30pm

31-38 (eg) * Did not receive / received sample blank (nothing written) eg 7/15/19



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-03024

Received Date: 07/18/2019
Reported Date: 07/22/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; Livingston Elementary School; 206 Delavan Street; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-03024-001	206-8	07/16/2019	TRAILER 1	<1.00	07/22/2019	

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



EHS Laboratories™
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com



19-07-03024

Due Date:
07/25/2019
(Thursday)
AE



Company Name: LEW CORP Account #: 201327

Address: 181 US Highway 46 City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068) Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: Livingston Elementary School 200 Delavan Street City/State/Zip: New Brunswick NJ
(Required)

Project #: 190652 Sampled By: Alex Salgado License # (If Required): _____

Water Source: (Check One) Public ☒ Well _____ Well Tag # (If Applicable): _____
(Required)

☒	5 Day Turnaround	☐	3 Day Turnaround	☐	2 Day Turnaround	☐	1 Day Turnaround - Call Ahead
-------------------------------------	-------------------------	--------------------------	-------------------------	--------------------------	-------------------------	--------------------------	--------------------------------------

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	206-8	Trailer 1	7/14/19	9:01 AM	☒					
2					AM / PM					
3					AM / PM					
4					AM / PM					
5					AM / PM					
6					AM / PM					
7					AM / PM					
8					AM / PM					
9					AM / PM					
10					AM / PM					

Released by: Alex Salgado Signature: _____ Date/Time: 7/14/19

Released by: Revised By: E. Mark Signature: _____ Date/Time: 7-18-19 @ 11:39am



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-03027

Received Date: 07/18/2019
Reported Date: 07/22/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; New Brunswick High School; 1000 Somerset Street; New Brunswick,
NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-03027-001	NBHS-1	07/16/2019	ROOM 124 A	<1.00	07/22/2019	
19-07-03027-002	NBHS-2	07/16/2019	ROOM 118 B	1.78	07/22/2019	
19-07-03027-003	NBHS-3	07/16/2019	ROOM 114 C	1.89	07/22/2019	
19-07-03027-004	NBHS-4	07/16/2019	ROOM 119 D	3.11	07/22/2019	
19-07-03027-005	NBHS-5	07/16/2019	ROOM 119 D	3.64	07/22/2019	
19-07-03027-006	NBHS-6	07/16/2019	ROOM 106 D	<1.00	07/22/2019	
19-07-03027-007	NBHS-7	07/16/2019	ROOM 106 D	<1.00	07/22/2019	
19-07-03027-008	NBHS-8	07/16/2019	HALL BY ROOM 111 F RIGHT	<1.00	07/22/2019	
19-07-03027-009	NBHS-9	07/16/2019	CAFE J 100 RIGHT	<1.00	07/22/2019	
19-07-03027-010	NBHS-10	07/16/2019	KITCHEN	2.73	07/22/2019	
19-07-03027-011	NBHS-11	07/16/2019	KITCHEN	1.02	07/22/2019	
19-07-03027-012	NBHS-13	07/16/2019	ROOM J 126	<1.00	07/22/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-03027

Project/Test Address: 190652; New Brunswick High School; 1000 Somerset Street; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-03027-013	NBHS-14	07/16/2019	ROOM J 128	2.07	07/22/2019	
19-07-03027-014	NBHS-16	07/16/2019	ROOM L 125 RIGHT	<1.00	07/22/2019	
19-07-03027-015	NBHS-17	07/16/2019	WEIGHT ROOM	1.00	07/22/2019	
19-07-03027-016	NBHS-18	07/16/2019	ROOM L 110 RIGHT	<1.00	07/22/2019	
19-07-03027-017	NBHS-21	07/16/2019	NURSE OFFICE	<1.00	07/22/2019	
19-07-03027-018	NBHS-22	07/16/2019	GYM LEFT	<1.00	07/22/2019	
19-07-03027-019	NBHS-23	07/16/2019	ROOM H 133	2.44	07/22/2019	
19-07-03027-020	NBHS-24	07/16/2019	ROOM H 104	1.48	07/22/2019	
19-07-03027-021	NBHS-25	07/16/2019	ROOM H 127	2.21	07/22/2019	
19-07-03027-022	NBHS-26	07/16/2019	ROOM H 154	31.2	07/22/2019	
19-07-03027-023	NBHS-27	07/16/2019	ROOM H 240 PREP ROOM	1.21	07/22/2019	
19-07-03027-024	NBHS-28	07/16/2019	ROOM 212 C	<1.00	07/22/2019	
19-07-03027-025	NBHS-29	07/16/2019	ROOM 213 C	<1.00	07/22/2019	
19-07-03027-026	NBHS-30	07/16/2019	ROOM 219 C	4.19	07/22/2019	
19-07-03027-027	NBHS-31	07/16/2019	ROOM H 207 RIGHT	<1.00	07/22/2019	
19-07-03027-028	NBHS-32	07/16/2019	ROOM 214 D	<1.00	07/22/2019	
19-07-03027-029	NBHS-33	07/16/2019	HALL BY ROOM 219 D RIGHT	<1.00	07/22/2019	
19-07-03027-030	NBHS-34	07/16/2019	ROOM A 211	<1.00	07/22/2019	
19-07-03027-031	NBHS-35	07/16/2019	ROOM 315 B	<1.00	07/22/2019	
19-07-03027-032	NBHS-36	07/16/2019	ROOM 315 C	1.28	07/22/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-03027

Project/Test Address: 190652; New Brunswick High School; 1000 Somerset Street; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-03027-033	NBHS-37	07/16/2019	ROOM 315 D	4.22	07/22/2019	
19-07-03027-034	NBHS-38	07/16/2019	ROOM 306 G	1.12	07/22/2019	
19-07-03027-035	NBHS-39	07/16/2019	HALL BY ROOM 320 D RIGHT	<1.00	07/22/2019	
19-07-03027-036	NBHS-40	07/16/2019	FIELD HOUSE	3.43	07/22/2019	
19-07-03027-037	NBHS-41	07/16/2019	ROOM 119 D IM	<1.00	07/22/2019	
19-07-03027-038	NBHS-42	07/16/2019	ROOM 119 D COFFEE MACHINE	39.4	07/22/2019	
19-07-03027-039	NBHS-43	07/16/2019	KITCHEN KETTLE	<1.00	07/22/2019	
19-07-03027-040	NBHS-45	07/16/2019	KITCHEN POT FILLER	<1.00	07/22/2019	
19-07-03027-041	NBHS-46	07/16/2019	KITCHEN ICE MACHINE	<1.00	07/22/2019	
19-07-03027-042	NBHS-47	07/16/2019	KITCHEN SINK	3.72	07/22/2019	
19-07-03027-043	NBHS-48	07/16/2019	ROOM J 114 COFFEE	<1.00	07/22/2019	
19-07-03027-044	NBHS-49	07/16/2019	ROOM L 112	<1.00	07/22/2019	
19-07-03027-045	NBHS-50	07/16/2019	ROOM L 112 IM	<1.00	07/22/2019	
19-07-03027-046	NBHS-52	07/16/2019	STORAGE ROOM	<1.00	07/22/2019	
19-07-03027-047	NBHS-53	07/16/2019	ROOM 122 B	<1.00	07/22/2019	
19-07-03027-048	NBHS-54	07/16/2019	ROOM C 108	<1.00	07/22/2019	
19-07-03027-049	NBHS-55	07/16/2019	HALL BY H 137	<1.00	07/22/2019	
19-07-03027-050	NBHS-56	07/16/2019	ROOM D 319	<1.00	07/22/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-03027

Project/Test Address: 190652; New Brunswick High School; 1000 Somerset Street; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
-------------------	------------------	-----------------	---------------------	--------------------------	---------------	--------------

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com



19-07-03027

Due Date:
07/25/2019
(Thursday)
AE



Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address:

New Brunswick High School 1000 Somerset Street

City/State/Zip:

New Brunswick NJ

Project #: 190652

Sampled By:

Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead					
				Lead	Copper	Other			
No.	Client Sample ID	Collection Location (Eg: Kitchen Sink)	Collection Date	Collection Time	Metals		Field Parameters	LAB USE	
1	NBHS-1	Room 124 A	7/16/19	9:30	AM/PM				
2	2	118 B		31	AM/PM				
3	3	114 C		32	AM/PM				
4	4	119 D		33	AM/PM				
5	5	119 D		34	AM/PM				
6	6	106 D		35	AM/PM				
7	7	108 D		36	AM/PM				
8	8	Hall by Room 111F Right		37	AM/PM				
9	9	Cafe J100 Right		38	AM/PM				
10	10	Kitchen		39	AM/PM				
Released by: Alex Salvador		Signature: [Signature]		Date/Time: 7/16/19		Date/Time: 7-18-19 @ 1145 AM			



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908) 654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: New Brunswick High School 1000 Sunset Street

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead							
				Lead	Copper	Other					
No.	Client Sample ID	Collection Location (Exc: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE	
1	NBHS-11	Kitchen	7/16/19	9:45	AM/PM				Field pH at time of Collection:	Temp. at time of Collection:	Temp at Time of Receipt:
2	13	Room J 126		46	AM/PM						
3	14	Room J 128		47	AM/PM						
4	15	Room L 125 right		49	AM/PM						
5	17	Weight Room		50	AM/PM						
6	18	Room L 110 right		51	AM/PM						
7	21	Nurse office		52	AM/PM						
8	22	Gym left		55	AM/PM						
9	23	Room H 133		57	AM/PM						
10	24	Room H 104		59	AM/PM						
Released by: Alex Salvador		Signature: [Signature]		Date/Time: 7/16/19		Date/Time: 7-18-19 @ 1145AM					



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP Account #: 201327

Address: 181 US Highway 46 City/State/Zip: Mine Hill, NJ 07803

Phone: (908) 654-8068 Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: New Brunswick High School 1000 Somerset street City/State/Zip: New Brunswick NJ

Project #: 190652 Sampled By: Alex Salvador License # (If Required):

Water Source: (Check One) Public ☒ Well ☐ Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
No.	Client Sample ID	Collection Location (Exc: Kitchen Sink)	Collection Date	Collection Time						
1	NBHS-25	Room H 127	7/16/19	10:00	AM/PM					
2	26	Rm H 154		2	AM/PM					
3	27	Room H 240 Prep Rm		4	AM/PM					
4	28	Rm a12c		6	AM/PM					
5	29	Rm a13C		8	AM/PM					
6	30	Rm a19C		10	AM/PM					
7	31	Rm H 207 Right		12	AM/PM					
8	32	Rm a14B		14	AM/PM					
9	33	Hall by Rm a19 D Right		16	AM/PM					
10	34	Rm A 211		18	AM/PM					
Released by: Alex Salvador		Signature:		Date/Time: 7/16/19		Date/Time: 7-18-19 @ 1145am				



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: New Brunswick High School 1000 Somerset Street
City/State/Zip: New Brunswick NJ

Project #: 190652 Sampled By: Alex Salvador License # (If Required):

Water Source: (Check One) Public ☒ Well ☐ Well Tag # (If Applicable):

No.	Client Sample ID	Collection Location (Exc: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE Temp at Time of Receipt
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	NBHS-35	Rm 315 B	7/16/19	10:20	AM/PM					
2	36	Rm 315 C		22	AM/PM					
3	37	Rm 312 D		25	AM/PM					
4	38	Rm 306 G		27	AM/PM					
5	39	Hall by Rm 320 D right		28	AM/PM					
6	40	Field House		29	AM/PM					
7	41	Rm 119 D IM		36	AM/PM					
8	42	Rm 119 D coffee machine		31	PM/PM					
9	43	Kitchen Kettle		34	AM/PM					
10	45	Kitchen Pot filler		36	AM/PM					
Released by: Alex Salvador		Signature:		Date/Time: 7/14/19		Date/Time: 7-18-19 @ 11:55am				



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: New Brunswick High School 1000 Sunset Street

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time						
1	NBHS-46	kitchen ice machine	7/16/19	10:41	AM/PM					
2	47	kitchen sink		43	AM/PM					
3	48	Room J114 coffee		45	AM/PM					
4	49	Rm L112		49	AM/PM					
5	50	Rm L112 IM		55	AM/PM					
6	52	storage room		11:00	AM/PM					
7	53	Rm Y22B		05	AM/PM					
8	54	Rm C108		10	AM/PM					
9	55	Hall by #137		15	AM/PM					
10	56	Rm D319		20	AM/PM					
Released by: Alex Salvador		Signature: [Signature]		Date/Time: 7/16/19		Date/Time: 7-18-19 @ 11:55am				



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-03066

Received Date: 07/18/2019
Reported Date: 07/24/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; New Brunswick Middle School; 1125 Livingston Avenue; New Brunswick, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-03066-001	1125-1	07/16/2019	HALLWAY BY ROOM 120	<1.00	07/24/2019	
19-07-03066-002	1125-2	07/16/2019	HALLWAY BY ROOM 107	<1.00	07/24/2019	
19-07-03066-003	1125-3	07/16/2019	MAIN OFFICE SINK	2.54	07/24/2019	
19-07-03066-004	1125-4	07/16/2019	HALLWAY BY ROOM 102	1.51	07/24/2019	
19-07-03066-005	1125-5	07/16/2019	NURSE OFFICE SINK	1.29	07/24/2019	
19-07-03066-006	1125-6	07/16/2019	HALLWAY BY NURSE	<1.00	07/24/2019	
19-07-03066-007	1125-7	07/16/2019	HALLWAY BY SECURITY	<1.00	07/24/2019	
19-07-03066-008	1125-8	07/16/2019	GIRLS LOCKER ROOM	3.94	07/24/2019	
19-07-03066-009	1125-9	07/16/2019	BOYS LOCKER ROOM	2.99	07/24/2019	
19-07-03066-010	1125-10	07/16/2019	HALL BY GYM	<1.00	07/24/2019	
19-07-03066-011	1125-11	07/16/2019	KITCHEN KETTLE 1	<1.00	07/24/2019	
19-07-03066-012	1125-12	07/16/2019	KITCHEN S	4.60	07/24/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-03066

Project/Test Address: 190652; New Brunswick Middle School; 1125 Livingston Avenue; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-03066-013	1125-14	07/16/2019	KITCHEN SINK	2.44	07/24/2019	
19-07-03066-014	1125-15	07/16/2019	CAFE WATER FOUNTAIN	<1.00	07/24/2019	
19-07-03066-015	1125-16	07/16/2019	CAFE WATER FOUNTAIN	<1.00	07/24/2019	
19-07-03066-016	1125-17	07/16/2019	HALLWAY BY AUDITORIUM RIGHT	8.73	07/24/2019	
19-07-03066-017	1125-18	07/16/2019	OUTSIDE AUDITORIUM BY ENTRANCE	4.67	07/24/2019	
19-07-03066-018	1125-19	07/16/2019	BY ROOM 203	1.23	07/24/2019	
19-07-03066-019	1125-20	07/16/2019	BY ROOM 233	2.03	07/24/2019	
19-07-03066-020	1125-21	07/16/2019	HALLWAY BY BIOLOGY	<1.00	07/24/2019	
19-07-03066-021	1125-22	07/16/2019	HALLWAY BY ROOM 221	10.6	07/24/2019	
19-07-03066-022	1125-23	07/16/2019	TRAILER 8	<1.00	07/24/2019	
19-07-03066-023	1125-24	07/16/2019	TRAILER 6	<1.00	07/24/2019	
19-07-03066-024	1125-25	07/16/2019	TRAILER 4	1.86	07/24/2019	
19-07-03066-025	1125-26	07/16/2019	TRAILER 2	1.89	07/24/2019	
19-07-03066-026	1125-27	07/16/2019	TRAILER 1	1.13	07/24/2019	
19-07-03066-027	1125-28	07/16/2019	TRAILER 3	<1.00	07/24/2019	
19-07-03066-028	1125-29	07/16/2019	TRAILER 5	<1.00	07/24/2019	
19-07-03066-029	1125-30	07/16/2019	TRAILER 7	<1.00	07/24/2019	
19-07-03066-030	1125-31	07/16/2019	STORAGE ROOM	<1.00	07/24/2019	
19-07-03066-031	1125-32	07/16/2019	TRAINERS ROOM	1.61	07/24/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-03066

Project/Test Address: 190652; New Brunswick Middle School; 1125 Livingston Avenue; New Brunswick, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
-------------------	------------------	-----------------	---------------------	--------------------------	---------------	--------------

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com



19-07-03066

Due Date:
07/25/2019
(Thursday)
AE



Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address:

New Brunswick-Middle School 1125 Livingston Avenue
City/State/Zip: New Brunswick NJ

Project #: 196652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time						
1	1125-1	Hallway by Rm 126	7/16/19	8:10	AM/PM					
2	2	Hallway by Rm 107		11	AM/PM					
3	3	Main office Sink		12	AM/PM					
4	4	Hallway by Rm 162		13	AM/PM					
5	5	Nurse office Sink		14	AM/PM					
6	6	Hallway by Nurse		15	AM/PM					
7	7	Hallway by Security		16	AM/PM					
8	8	girls-toilet Room		17	AM/PM					
9	9	Boys locker Room		18	AM/PM					
10	10	Hall by gym		19	AM/PM					
Released by: Alex Salvador		Signature: [Signature]		Date/Time: 7/16/19		Date/Time: 7-18-19 @ 12:14pm				

1-10



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address

New Brunswick Middle School 1125 Livingston Avenue New Brunswick NJ

Project #: 190652

Sampled By: Alex Salva

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	Temp at Time of Receipt:
No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time						
1	1125-11	Kitchen Kettle-1	7/16/19	8:21	AM/PM					
2	12	Kitchen S		23	AM/PM					
3	14	Kitchen Sink		24	AM/PM					
4	15	Cafe water Fountain		25	AM/PM					
5	16	Cafe water Fountain		26	AM/PM					
6	17	Hallway by Auditorium Right		27	AM/PM					
7	18	Outside Auditorium by entrance		28	AM/PM					
8	19	By Rm 203		29	AM/PM					
9	20	By Rm 233		31	AM/PM					
10	21	Hallway by Biology		32	AM/PM					
Released by: Alex Salva					Signature: [Signature]			Date/Time: 7/16/19		
Released by: [Signature]					Signature: [Signature]			Date/Time: 7-18-19 12:14pm		



ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP Account #: 201327

Address: 181 US Highway 46 City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068) Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: New Brunswick Middle School 1125 Livingston Avenue
City/State/Zip: New Brunswick NJ

Project #: 190652 Sampled By: Alex Salvada License # (If Required):

Water Source: (Check One) Public ☒ Well ☐ Well Tag # (If Applicable):

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
No.	Client Sample ID	Collection Location (Exc: Kitchen Sink)	Collection Date	Collection Time						
1	1125-22	Hallway by Km 221	7/16/19	8:33	AM/PM					
2	23	Trailers		34	AM/PM					
3	24			35	AM/PM					
4	25			36	AM/PM					
5	26			38	AM/PM					
6	27			46	AM/PM					
7	28			41	AM/PM					
8	29			44	AM/PM					
9	30			46	AM/PM					
10	31	Storage Rm		48	AM/PM					
Released by: Alex Salvada					Signature: [Signature]		Date/Time: 7/16/19			
Released by: E.H.					Signature: [Signature]		Date/Time: 7-18-19 2:44pm			



EHS Laboratories™
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP Account #: 201327

Address: 181 US Highway 46 City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068) Email: labresults@lewcorp.com Fax: 908-654-8069

Project Name / Collection Address: New Brunswick Middle School 1125 Livingston Avenue City/State/Zip: New Brunswick NJ

Project #: 190652 Sampled By: Alex Salvada License # (If Required): _____

Water Source: (Check One) Public X Well _____ Well Tag # (If Applicable): _____

(Required)

X	5 Day Turnaround	3 Day Turnaround	2 Day Turnaround	1 Day Turnaround * Call Ahead	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time						
1	1125-32	Trainers Rm	7/16/19	8:50 AM	X					
2										
3										
4										
5										
6										
7										
8										
9										
10										

Released by: Alex Salvada Signature: [Signature] Date/Time: 7/16/19

Released by: EG Signature: [Signature] Date/Time: 7-18-19 01:14pm



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-08-00682

Received Date: 08/05/2019
Reported Date: 08/09/2019
Sampled By: Mark Franz
Tech Certification #: 003265

Project/Test Address: 190808; New Brunswick High School; New Brunswick, NJ 08901

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-08-00682-001	12	08/01/2019	KITCHEN SINK	4.46	08/07/2019	
19-08-00682-002	15	08/01/2019	RM 127 RT WC	1.87	08/07/2019	
19-08-00682-003	19	08/01/2019	RM L 100 RT WC	10.4	08/07/2019	
19-08-00682-004	44	08/01/2019	KITCHEN POT FILLER	10.7	08/07/2019	
19-08-00682-005	18	08/01/2019	RM L 100 WC	1.82	08/07/2019	

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



WaterSmart® Pro


LEAD ONLY

EHS Laboratories™

Environmental Hazards Services, LLC
www.leadlab.com
(800) 347-4010
(804) 275-4907 (fax)

7469 Whitepine Rd
Richmond, VA 23237

Chain-of-Custody
Analysis by National Testing Laboratories



19-U8-U0682

Due Date:
08/12/2019
(Monday)
AE

Company Name:

LEU Corporation

Address:

1090 Bristol Rd.

City/State/Zip:

11111-1111

Phone:

(908) 654-8068

Fax:

(908) 654-8069

E-mail:

LEUresults@leucorp.com

Acct. Number:

201327

Project Name / Collection Address:

New Brunswick High School

City/State (Required):

New Brunswick NJ

Zip:

08901

Collected by:

Mark Franz

Certification #:

003265

Well Tag # (if applicable):

Purchase Order Number:

19 0808

Relinquished by:

Date:

8/11/19 Open

ALL SAMPLES BELOW SHOULD BE ANALYZED FOR

LEAD

IN DRINKING WATER

Turn-around Time Required:

5 days

PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

No.	Client Sample ID APT. NUMBER	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters			LAB USE
						Field PH:	Field Chlorine:	Temperature at Time of Collection:	
1	12	Kitchen, Sink	8/11/19	8 ~~AM~~ PM	Pb				
2	15	Rm 127 Rt, wc		AM / PM					
3	19	Rm L100 Rt, wc		AM / PM					
4	44	Kitchen, Pot Filler		AM / PM					
5	18	Rm L110, wc		9 ~~AM~~ PM					
6				AM / PM					
7				AM / PM					
8				AM / PM					
9				AM / PM					
10				AM / PM					
Received by: <u>T. W. H.</u>						Date: <u>8/5/19</u>		Time: <u>10</u> AM / PM	
Tracking Number:						NTL Lab ID Number			



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-08-00694

Received Date: 08/05/2019
Reported Date: 08/09/2019
Sampled By: Mark Franz
Tech Certification #: 003265

Project/Test Address: 190808; 15 Van Dyke Ave; New Brunswick, NJ 08901

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-08-00694-001	15-11	08/01/2019	HALL BY RM 116 WC	4.18	08/07/2019	

Method: SM 3113B-2010
Analyst: Jennalee Hertzler
Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



WaterSmart® Pro

LEAD ONLY

Chain-of-Custody

Analysis by National Testing Laboratories

EHS Laboratories™
Environmental Hazards Services, LLC
www.leadlab.com
(800) 347-4010
(804) 275-4907 (fax)

7469 Whitepine Rd
Richmond, VA 23237



19-UB-UB094

Due Date:

08/12/2019

(Monday)

AE

Company Name:

LEW Colocation

Address:

1090 Bristol Rd.

City/State/Zip:

Mountain View, NC 28111

Phone:

(908) 654-8068

Fax:

(908) 654-8069

E-mail:

LEWresults@lewcoc.com

Acct. Number:

2013019

Project Name / Collection Address:

15 Van Dyke Ave

City/State (Required):

New Brunswick NJ 08901

Age of Property:

Collected by:

Mark Franz

Certification #:

003265

Well Tag # (if applicable):

Purchase Order Number:

190808

Relinquished by:

MF

Date:

8/11/9 pm

ALL SAMPLES BELOW SHOULD BE ANALYZED FOR LEAD IN DRINKING WATER Turn-around Time Required: 5 Days

PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

No.	Client Sample ID APT. NUMBER	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters			LAB USE
						Field PH:	Field Chlorine:	Temperature at Time of Collection:	
1	15-11	Hellby Rm116, LLC	8/11/19 <i>dup</i>	9 <i>AM</i> / <i>PM</i>	Pb				
2				<i>AM</i> / <i>PM</i>					
3				<i>AM</i> / <i>PM</i>					
4				<i>AM</i> / <i>PM</i>					
5				<i>AM</i> / <i>PM</i>					
6				<i>AM</i> / <i>PM</i>					
7				<i>AM</i> / <i>PM</i>					
8				<i>AM</i> / <i>PM</i>					
9				<i>AM</i> / <i>PM</i>					
10				<i>AM</i> / <i>PM</i>					
Received by: <i>Thoburn</i>				Date: <i>8/5/19</i>		Time: <i>1:30p</i>	<i>AM</i> / <i>PM</i>		
Tracking Number:				Temperature:					
NTI Lab ID Number									

NTL Lab ID Number



Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: LEW Corp
181 US Hwy 46
Mine Hill, NJ 07803

Report Number: 19-07-02390

Received Date: 07/15/2019
Reported Date: 07/19/2019
Sampled By: Alex Salvador
Tech Certification #:

Project/Test Address: 190652; Roosevelt Elementary School; 83 Livingston Avenue; Newark, NJ

Client Number:
201327

Laboratory Results

Fax Number:
Ext 18 Melissa

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-02390-001	83-1	07/11/2019	HALLWAY BY CUST CLOSET	<1.00	07/17/2019	
19-07-02390-002	83-3	07/11/2019	CAFETERIA RIGHT	<1.00	07/17/2019	
19-07-02390-003	83-4	07/11/2019	KITCHEN	3.01	07/17/2019	
19-07-02390-004	83-5	07/11/2019	KITCHEN KETTLE	2.14	07/17/2019	
19-07-02390-005	83-6	07/11/2019	HALLWAY BY ROOM 20 LEFT	1.94	07/17/2019	
19-07-02390-006	83-7	07/11/2019	HALLWAY BY ROOM 121 LEFT	3.41	07/17/2019	
19-07-02390-007	83-8	07/11/2019	HALLWAY BY NURSES OFFICE LEFT	11.0	07/17/2019	
19-07-02390-008	83-9	07/11/2019	NURSES OFFICE	2.10	07/17/2019	
19-07-02390-009	83-10	07/11/2019	HALLWAY BY ROOM 114	3.68	07/17/2019	
19-07-02390-010	83-11	07/11/2019	HALLWAY BY ROOM 114 LEFT	<1.00	07/17/2019	
19-07-02390-011	83-12	07/11/2019	HALLWAY BY ROOM 215 LEFT	<1.00	07/17/2019	
19-07-02390-012	83-13	07/11/2019	HALLWAY BY ROOM 224 LEFT	1.52	07/17/2019	
19-07-02390-013	83-14	07/11/2019	HALLWAY BY 321 LEFT	9.61	07/17/2019	

Environmental Hazards Services, L.L.C

Client Number: 201327

Report Number: 19-07-02390

Project/Test Address: 190652; Roosevelt Elementary School; 83 Livingston Avenue; Newark, NJ

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
19-07-02390-014	83-15	07/11/2019	HALLWAY BY ROOM 315 LEFT	2.38	07/17/2019	
19-07-02390-015	83-16	07/11/2019	TRAILER 1	32.6	07/19/2019	
19-07-02390-016	83-17	07/11/2019	TRAILER 2	8.73	07/17/2019	
19-07-02390-017	83-18	07/11/2019	STORAGE ROOM	<1.00	07/17/2019	

Method: SM 3113B-2010

Analyst: Jennalee Hertzler

Accreditation #: NJ VA008

Reviewed By Authorized Signatory:

Melissa Kanode

Missy Kanode

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



EHS Laboratories
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form
SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com



19-07-02390

Due Date:

07/22/2019

(Monday)

AE

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068)

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Roosevelt Elementary School 83 Livingston Avenue Newark NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐

Well Tag # (If Applicable):

☒ 5 Day Turnaround

☐ 3 Day Turnaround

☐ 2 Day Turnaround

☐ 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	83-1	Hallway by cust closet	7/11/19	9:36	AM/PM					
2	3	Cafeteria Right		31	AM/PM					
3	4	Kitchen		32	AM/PM					
4	5	Kitchen Kettle		33	AM/PM					
5	6	Hallway by Room 20 Left		34	AM/PM					
6	7	Hallway by Room 121 Left		35	AM/PM					
7	8	Hallway by Nurses Office Left		36	AM/PM					
8	9	Nurses Office		37	AM/PM					
9	10	Hallway by Room 114 Left		38	AM/PM					
10	11	Hallway by Room 114 Left		39	AM/PM					
Released by: Alex Salgado					Signature: [Signature]		Date/Time: 7/11/19			
Released by: Received By: E. Gluck					Signature: [Signature]		Date/Time: 7-15-19 @ 1pm			



EHS Laboratories™
ENVIRONMENTAL HAZARDS SERVICES, LLC

Water Chain-of-Custody Form

SHIP TO: 7469 Whitepine Rd. Richmond, VA 23237
Phone: (800) 347-4010 FAX: (804) 275-4907
ONLINE CLIENT PORTAL AVAILABLE FOR ANALYSIS RESULTS AT: www.leadlab.com

~ For Lab Use Only ~

Company Name: LEW CORP

Account #: 201327

Address: 181 US Highway 46

City/State/Zip: Mine Hill, NJ 07803

Phone: (908-654-8068

Email: labresults@lewcorp.com

Fax: 908-654-8069

Project Name / Collection Address: Roosevelt Elementary School 83 Livingston Avenue

City/State/Zip: New Brunswick NJ

Project #: 190652

Sampled By: Alex Salvador

License # (If Required):

Water Source: (Check One) Public ☒ Well ☐ Well Tag # (If Applicable):

X ☒ 5 Day Turnaround ☐ 3 Day Turnaround ☐ 2 Day Turnaround ☐ 1 Day Turnaround * Call Ahead

No.	Client Sample ID	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Metals			Field Parameters		LAB USE
					Lead	Copper	Other	Field pH at time of Collection:	Temp. at time of Collection:	
1	83-12	Hallway by Room 215 left	7/11/19	9:46	AM/PM					
2	13	Hallway by Room 224 left		41	AM/PM					
3	14	Hallway by Room 321 left		42	AM/PM					
4	15	Hallway by Room 315 left		43	AM/PM					
5	16	Trailer 1		44	AM/PM					
6	17	Trailer 2		45	AM/PM					
7	18	Storage Room		46	AM/PM					
8					AM/PM					
9					AM/PM					
10					AM/PM					

Released by: Alex Salvador Signature: [Signature] Date/Time: 7/11/19

Released by: Alex Salvador Signature: [Signature] Date/Time: 7-15-19 2:00 pm



WaterSmart® Pro

LEAD ONLY

Chain-of-Custody

Analysis by National Testing Laboratories

Environmental Hazards Services, LLC
www.leadlab.com
(800) 347-4010
(804) 275-4907 (fax)

7469 Whitepine Rd
Richmond, VA 23237



19-UB-UB094

Due Date:

08/12/2019

(Monday)

AE

Company Name:

LEW Colocation

Address:

1090 Bristol Rd.

City/State/Zip:

Mountainview, NC 28111

Phone:

(908) 654-8068

Fax:

(908) 654-8069

E-mail:

LEWresults@lewcoc.com

Acct. Number:

2013019

Project Name / Collection Address:

15 Van Dyke Ave

City/State (Required):

New Brunswick NJ 08901

Age of Property:

Collected by:

Mark Franz

Certification #:

003265

Well Tag # (if applicable):

Purchase Order Number:

190808

Relinquished by:

MF

Date:

8/11/9 pm

ALL SAMPLES BELOW SHOULD BE ANALYZED FOR LEAD IN DRINKING WATER Turn-around Time Required: 5 Days

PLEASE PROVIDE A SINGLE REPORT FOR ALL SAMPLES INCLUDED ON THIS CHAIN OF CUSTODY.

No.	Client Sample ID APT. NUMBER	Collection Location (Ex: Kitchen Sink)	Collection Date	Collection Time	Analysis Requested	Field Parameters			LAB USE
						Field PH:	Field Chlorine:	Temperature at Time of Collection:	Temperature at Time of Receipt:
1	15-11	Hellby Rm116, WC	8/11/9	9 AM / PM	Pb				
2				AM / PM					
3				AM / PM					
4				AM / PM					
5				AM / PM					
6				AM / PM					
7				AM / PM					
8				AM / PM					
9				AM / PM					
10				AM / PM					
Received by: <u>Thoburn</u>				Date: <u>8/5/19</u>		Time: <u>1:30p</u>		AM / PM	
Tracking Number:				Temperature:					

NTL Lab ID Number