


New Jersey Police Crash Investigation Report NJTR-1 (Rev. 01/22)

E	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death

144. Crash Diagram



145. Crash Description/Narrative

Officer's Investigation: V1was traveling on US Highway North. Due to a down light laying across US Highway 9 North, V1 was unable to avoid the pole and struck it. The down light pole was unavoidable. There were no reported injuries. NJ DOT was advised of the down light pole.

Other Descriptions

Down light pole - Field 128
01 - Down Light Pole in roadway - Field 126a
01 - Down Light Pole in roadway - Field 126e
01 - Vantapro Specialty Insurance Company. Comapny#44768 - Field 25

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Alcott, Ryan	720	Bruno, Marco	602	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Woodbridge Police Department Code: 01

Station: _____ Case No: 24051299

144. Crash Diagram (NOT TO SCALE)

