



**Brigantine Fire
Department**

Station: **1**
Shifts Or Platoon: **A Platoon**

Location: 4801 Atlantic Brigantine BLVD # B Brigantine NJ 08203	Incident Type: 424 - Carbon monoxide incident
Lat/Long: N 39° 23' 24.87" W 74° 24' 46.99"	FDID: 01031 Incident #: 2019-947 Exposure ID: 40161841 Exposure #: 0 Incident Date: 05/19/2019 Dispatch Run #: FD-2019-01058
Zone: Ward 4 - Ward 4 Location Type: 1 - Street address	

Report Completed by:	HURTT, DANIEL W	ID: 98542	Date: 05/19/2019
Report Reviewed by:	HURTT, DANIEL W	ID: 98542	Date: 05/19/2019
Report Printed by:	MURRAY IV, JOHN J	ID: 98853	Date: 5/28/2019 Time: 10:46

Structure Type:	Property Use: 419 - 1 or 2 family dwelling		
Automatic Extinguishment System Present: ☐	Detectors Present: ☐	Cause of Ignition:	
Aid Given or Received: None	Primary action taken: 32 - Provide basic life support (BLS)		
Additional actions: 80 - Information, investigation & enforcement, other, 82 - Notify other agencies.			
Losses	Pre-Incident Values		
Property:	Property:	Civilian Injuries: 0	Fire Service Injuries: 0
Contents:	Contents:	Civilian Fatalities: 0	Fire Service Fatalities: 0
Total:	Total:	Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call: 3		Total # of personnel on call: 6	

NARRATIVE (1)

Narrative Title: Co incident

Narrative Author: HURTT, DANIEL

Narrative Date: 05/19/2019 17:51:35

Narrative Apparatus ID: IC-1

Narrative:

IC-1, E-1, and R-3 responded to the above address for a carbon monoxide leak called in by South Jersey Gas. Upon arrival we were met by the owners of the second floor who said they were experiencing headaches. R-3 assessed the patients CO levels and vitals, and refusals for further treatment were signed by both. E-1 investigated the second floor. South Jersey Gas was also on scene to help investigate. It was noticed that the exhaust pipe from the first floor was disconnected, (1st and 2nd floor shared a common chimney), so the second floor exhaust from the water heater was venting into the second floor. Entry was made into the first floor to investigate the disconnected exhaust pipe. It was noticed that there was extensive work being done, and the 1st floor heater was moved from the original position. It was also noticed that there was no permits in the window of the 1st floor. The gas meter for the 1st floor was locked out by South Jersey Gas, and a tag was left in the window of the 1st floor. The water heater for the 2nd floor was shut off and the owners were advised to have the chimney repaired. All Apparatus returned to service.

APPARATUS			
Fire Controlled Date / Time:		5/19/2019 3:56:54 PM	
Unit	R-3	Unit	IC-1
Type:	BLS unit	Type:	Mobile command post
Use:	EMS	Use:	Other
Response Mode:	()	Response Mode:	()
# of People	2	# of People	1
Alarm	05 /19/2019 15:26:17	Alarm	05 /19/2019 15:26:17
Dispatched	05 /19/2019 15:26:17	Dispatched	05 /19/2019 15:26:17
Enroute	05 /19/2019 15:27:01	Enroute	05 /19/2019 15:27:04
Arrived	05 /19/2019 15:31:00	Arrived	05 /19/2019 15:31:13
Cancelled	-- /--/-- --:--:--	Cancelled	-- /--/-- --:--:--
Cleared Scene	05 /19/2019 15:41:15	Cleared Scene	05 /19/2019 15:57:24
In Quarters	05 /19/2019 15:47:02	In Quarters	05 /19/2019 16:10:58
In Service	05 /19/2019 15:41:26	In Service	-- /--/-- --:--:--
Unit	E-1		
Type:	Engine		
Use:	Suppression		
Response Mode:	Lights and Sirens		
# of People	3		
Alarm	05 /19/2019 15:26:17		
Dispatched	05 /19/2019 15:26:17		
Enroute	05 /19/2019 15:27:04		
Arrived	05 /19/2019 15:31:13		
Cancelled	-- /--/-- --:--:--		
Cleared Scene	05 /19/2019 15:57:24		
In Quarters	05 /19/2019 16:10:58		
In Service	-- /--/-- --:--:--		
Number Of People not on apparatus: 0			

PEOPLE -- PERSON 1			
Is Owner	False	Business Name	
Telephone Number	610 764 8949	Involvement	2nd fl
Name	John May	Date of Birth	
Address			


PEOPLE -- PERSON 2			
Is Owner	False	Business Name	
Telephone Number		Involvement	1st. Fl
Name	Mark Cresenski	Date of Birth	
Address			

CUSTOM FIELDS FORM	
Is this property a primary residence or secondary/vacation residence	Secondary/vacation residence

PERSONNEL ON CALL			
Name	Personnel Rank	Role(s)	Apparatus
BORDONARO , THOMAS K	FF/EMT		R-3
COHEN , TREVOR S	FF/EMT		E-1
HOPKINS , JOHN P	FF/EMT		E-1
HURTT , DANIEL W			IC-1
MALIA , CHASE R	FF/EMT		R-3
NEWCOMER SR, JEFFREY M	FF/EMT		E-1

Member Making Report (LT/EMT DANIEL W HURTT): _____

Incident Reviewer (LT/EMT DANIEL W HURTT): _____



May 23, 2019

5601/6.01

PHILIP J GUENTHER, CONSTRUCTION OFFICIAL
1417 W Brigantine Ave
Brigantine, NJ 08203-2186

Re: Red Tag Notice

Dear CONSTRUCTION OFFICIAL:

Please be advised that South Jersey Gas Company (SJG) recently discontinued gas service to a customer's private appliance(s) at the properties listed below due to compliance and/or safety concerns that were observed. It should be noted that SJG advised the customer of said compliance and/or safety concerns, and stressed discontinued use of the appliance(s) until the situation(s) is corrected by a qualified contractor. Continued operation of the equipment without immediate corrective action could result in serious injury and/or property damage.

SJG's service technician left a red tag hazard notice affixed to the gas valve or piping for the customer(s) below. A sample of the Red Tag Hazard Notice appears below. The customer has the option to return to SJG the pre-addressed/stamped postcard portion of the tag advising that the situation has been remediated. Upon receiving the postcard from the customer, SJG will communicate that information to your office.

Should you have any questions, please call our Customer Care Center at 1-888-766-9900.

Sincerely,

South Jersey Gas Company
Customer Care Center

NAME	ADDRESS	CITY	STATE	POSTAL
LIVEZEY,CHRIS	4801A ATLANTIC BRIGANTINE BLVD	BRIGANTINE	NJ	08203
CRESCENZI,MARK	4801A ATLANTIC BRIGANTINE BLVD	BRIGANTINE	NJ	08203