


State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to NJAC 8:60 and 5:16)

Date of Notification (1) 8 / 23 / 17		Name of Building Owner/Operator (2) State of New Jersey / Job #1707-2210 Chk. NA							
Agencies Notified ☐ EPA ☒ DOLWD ☒ DHSS ☐ DCA (NJAC 5:23-8)	Type Notification ☐ Initial ☒ Amended Amendment # 1 ☐ Emergency (including justification) ☐ Cancellation	Street Address 33 West State Street, 9th Floor							
		City, State, Zip Code Trenton, NJ 08625							
		Name of Contact Mark Vetterl	Telephone Number 908-619-8675						
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) Health & Agriculture Building		Type of Facility (4) ☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e., private and commercial buildings, homes, etc.)							
Street Address 369 South Warren Street		Square Feet 140505	# of Floors 8						
City (5) Trenton	County (6) Mercer	County Code (7) (STATE USE ONLY)	Bldg. Age 53						
Name of Monitoring Firm Hired by Building Owner (8) USA Environmental Management, Inc.		Name of Abatement Contractor (9) Asbestos and Mold Services, Corp.							
Street Address 344 West State Street		Street Address 3859 Sylon Boulevard							
City, State, Zip Code Trenton, NJ 08618		City, State, Zip Code Hainesport, NJ 08036							
Project Manager for Monitoring Firm William Weisgarber	Telephone No. 609-656-8101	Telephone No. 609-702-0400	License No. 00862						
Start Date (10) 9 / 8 / 17	Scheduled Completion Date (11) 10 / 8 / 17	Name of OSHA Monitor EMSL Analytical, Inc.							
Occupancy Status During Abatement (Check only one) ☐ Facility Closed/Vacated During Entire Period of Abatement ☒ Abatement Performed Outside of Normal Facility Hours - Describe Time of Abatement: 5 WEEKENDS, FRIDAY to SUNDAY. AM- PM/ PM- AM		Street Address 200 U.S. Route 130 North							
Scope of Work (Check all that apply) ☒ ≥3 sf or ≥3 lf ☐ ≥160 sf or ≥260 lf		City, State, Zip Code Cinnaminson, NJ 08077							
☒ Renovation ☐ Demolition		☐ Full Containment with Negative Pressure ☐ Mini-Enclosure ☒ Glovebag Procedure ☐ Non-Exempted (*) and Non-Friable Procedure							
Location of Asbestos-Containing Material (ACM) TO BE ABATED IN Facility (13)	Is Location Normally Used Solely by Maintenance/Custodial Staff? (12)			Description of Asbestos Containing Material (ACM) (i.e., thermal systems insulation, surfacing, VAT, or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Encapsulate	Enclosure
Basement	☐	☐	☒	Pipe Insulation	9 LF	☒	☐	☐	☐
	☐	☐	☒			☒	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
Name of Registered Waste Hauler Champion Disposal, LLC		NJDEP Waste Hauler ID No. 32707	Cubic Yards of Waste 5	Name of Registered Landfill Fairless Landfill					
City, State Hainesport, NJ		Disposal Date 10/8/17	City, State Morrisville, PA						
Completed By (Print or Type) Kimberly A. Trumbetti	Title Office Coordinator	Signature 	Date 8-31-2017						