

State of New Jersey
NOTIFICATION OF ASBESTOS ABATEMENT
(Pursuant to N.J.A.C. 8:60 and 12:120)

CR# 3270

Date of Notification (1) 9/25/17		Name of Building Owner / Operator (2) State of New Jersey							
Agencies Notified ☐ EPA ☐ DEP ☒ DOL ☒ DOH ☐ DCA	Type Notification ☒ Initial ☐ Amended ☐ Emergency ☐ Cancellation	Street Address 33 W. State Street, 9th Floor City, State & Zip Code Trenton, NJ 08625 Name of Contact Georgette Bunch Telephone Number 609-633-2127							
FACILITY INFORMATION									
Name of Facility Where Abatement is Taking Place (3) NJ Dept. of Health Building		Type of Facility (4) ☐ School (K-12) ☐ Subchapter 8 (Other than K-12) ☒ Other (i.e. private & commercial buildings, homes, etc.)							
Street Address 369 South Warren Street		Square Feet	# of Floors						
City (5) Trenton	County (6) Mercer	Bldg. Age							
County Code (7)		Current Use (Prior if being demolished)							
Name of Monitoring Firm Hired by Building Owner (8) Environmental Connection Inc		ASCM No.	Name of Abatement Contractor (9) Bristol Environmental, Inc.						
Street Address 120 North Warren		Street Address 1123 Beaver Street							
City, State & Zip Code Trenton, NJ 08608		City, State & Zip Code Bristol, PA 19007							
Project Manager for Monitoring Firm Rollie Jones	Telephone Number 609-392-4200	Telephone Number (215)788-6040	License Number 00509						
Scheduled Start Date (10) 10/9/17	Scheduled Completion Date (11) 10/9/17	Name of OSHA Monitor Bristol Environmental Inc.							
Occupancy Status During Abatement (Check only one) ☒ Facility Closed/Vacated During Entire Period of Abatement ☐ Abatement Performed Outside of Normal Hours – 7am to 3pm Describe: ☐ Facility Occupied During Abatement		Street Address 1123 Beaver Street							
		City, State & Zip Code Bristol, PA 19007							
Scope of Work (Check all that apply)									
☒ ≥3 sf or ≥3 lf ☐ ≥160 sf ≥260 lf		☒ Renovation ☐ Demolition ☐ Full Containment with Negative Pressure ☐ Mini-Enclosure ☒ Glove Bag Procedures ☐ Non-Exempted and Non-Friable Procedure							
Location of Asbestos-Containing Material (ACM) <u>TO BE ABATED</u> in Facility (13)	Is Location Normally Used Solely by Maintenance or Custodial Staff? (12)			Description of Asbestos-Containing Material (ACM) (i.e., thermal systems insulation, surfacing, VAT or other miscellaneous)	Amount (Specify SF or LF)	Abatement Type			
	Yes	No	N/A			Removal	Repair	Clean Up	Enclosure
Basement	☐	☒	☐	Pipe Insulation	9 LF	☒	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
	☐	☐	☐			☐	☐	☐	☐
Name of Registered Waste Hauler Service Transport Inc.		NJDEP Waste Hauler ID No. 20990	Cubic Yards of Waste 1 Cu Yd	Name of Registered Landfill Fairless Landfill					
City, State New Castle, DE		Disposal Date 10/9/17	City, State Morrisville, PA						
Completed By (Print or Type) Gino Pizzigoni		Title Project Manager	Signature <i>Gino Pizzigoni / gm</i>				Date 9/25/17		