




# New Jersey Police Crash Investigation Report

Police Dept: **NEPTUNE CITY PD** Code: **01**  
 Station: \_\_\_\_\_ Case No: **20NC06057**

(Refer to vehicle by number)

|   | Veh<br>Occ | Pos<br>In/On | Eject | Phys<br>Cond | Age | Sex | Loc<br>Inj | Type<br>Inj | Ref<br>Med | Equip<br>Avail | Equip<br>Used | Bag<br>Dept | Hosp<br>Code | Names & Addresses of Occupants - If Deceased, Date & Time of Death |
|---|------------|--------------|-------|--------------|-----|-----|------------|-------------|------------|----------------|---------------|-------------|--------------|--------------------------------------------------------------------|
| A | 83         | 84           | 85    | 86           | 87  | 88  | 89         | 90          | 91         | 92             | 93            | 94          | 95           |                                                                    |
| L |            |              |       |              |     |     |            |             |            |                |               |             |              |                                                                    |
| E |            |              |       |              |     |     |            |             |            |                |               |             |              |                                                                    |
| I |            |              |       |              |     |     |            |             |            |                |               |             |              |                                                                    |
| N |            |              |       |              |     |     |            |             |            |                |               |             |              |                                                                    |
| V |            |              |       |              |     |     |            |             |            |                |               |             |              |                                                                    |
| O |            |              |       |              |     |     |            |             |            |                |               |             |              |                                                                    |
| L |            |              |       |              |     |     |            |             |            |                |               |             |              |                                                                    |
| V |            |              |       |              |     |     |            |             |            |                |               |             |              |                                                                    |
| E |            |              |       |              |     |     |            |             |            |                |               |             |              |                                                                    |
| I |            |              |       |              |     |     |            |             |            |                |               |             |              |                                                                    |
| D |            |              |       |              |     |     |            |             |            |                |               |             |              |                                                                    |

144 Crash Diagram (NOT TO SCALE)



145 Crash Description/Narrative

Vehicle 1 was travelling east in the right hand lane on State Route 33. Vehicle 2 was travelling north on Sixth Avenue. Vehicle 2 had a green light and entered the intersection of State Route 33, attempting to make a left turn onto State Route 33 west. Vehicle 1 had a red light and entered the intersection, colliding with Vehicle 2. The front driver side bumper of Vehicle 1 collided with the rear driver side fender of Vehicle 2. Vehicle 2 then spun around and stopped in the east bound lane of State Route 33, facing south. Vehicle 1 came to a stop on State Route 33 east. Vehicle 1 had extensive damage to the front driver side bumper and fender, and Vehicle 2 had extensive damage to the rear bumper and driver side fender.

No injuries were reported. Jim's Towing was notified and responded to tow both vehicles. Both vehicle were taken to Impact Auto Body by Jim's Towing.

It should be noted, two (2) Special Law Enforcement Officers (SLEO I) from Neptune Township Police Department witnessed the collision. SLEO I Jazikoff # 584 and SLEO I Gallagher # 638 both stated Vehicle 1 entered the intersection with a red light and collided with Vehicle 2 as it was making a left turn.

146 Officer's Signature  
**DEVLIN, C**

147 Badge #  
**35127**

148 Reviewer  
**KJM**

Badge #  
**075**

149 Case Status  
☐ Pending ☒ Complete