

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report											Case Number 20001293				Page <u>2</u> of <u>3</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE NJTR-1B

145. Crash Description/Narrative

V1 was backing in the parking lot of BP gas station.
V2 was stopped at the gas pump in the BP gas station.

V1 stated she backed into the V2.
V2 stated V1 backed into her vehicle.

Officer's on scene investigation revealed that D1 is at fault for backing unsafely. I observed minor damage to the rear of V1 and minor damage to the front of V1. Driver statements along with the damages to both vehicles support this Officer's findings.

Box 54/55:
State Farm
Company Code: 328
Policy#: 1395130A1132A
(631)661-1300

146. Officer's Signature TORRES A	147. Badge # 190	148. Reviewer JACOBSEN E	Badge # 157	149. Case Status ☐ Pending ☒ Complete
--------------------------------------	---------------------	-----------------------------	----------------	---


New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: NORTH BRUNSWICK Code: 01

Station: - Case No: 20001293

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



TORRES A

Officer's Signature

190

Badge Number