

New Jersey Police Crash Investigation Report												Case Number 20002125			Page <u>2</u> of <u>3</u>	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE NJTR-1B

145. Crash Description/Narrative

Vehicle 1 (V1) was travelling behind Vehicle 2 (V2) in the left lane on Rt 27 north. Driver of V1 stated V2 was driving erratically by suddenly stopping and going just past Finnegans Lane. Driver of V1 stated V2 suddenly stopped in the middle of the road to make a turn into 2993 Rt 27 and struck V2 from behind. Driver of V2 stressed that he was driving safely and used his turn signal indicating his left turn when he was struck from behind by V1. Based on driver statement and evidence at the scene, crash investigation revealed the driver of V1 at fault for driving too close to V2.

146. Officer's Signature TSUI L	147. Badge # 162	148. Reviewer COX J	Badge # 146	149. Case Status ☐ Pending ☒ Complete
---	----------------------------	-------------------------------	-----------------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: NORTH BRUNSWICK Code: 01
Station: - Case No: 20002125

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



TSUI L

Officer's Signature

162

Badge Number