

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report											Case Number 20002886				Page <u>2</u> of <u>3</u>	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE NJTR-1B

145. Crash Description/Narrative

Driver of Veh1 stated that she was driving North on Rt. 1 when she attempted to change lanes from the middle to the left most lane, striking Veh2.

Driver of Veh2 stated he was in the left most lane when Veh1 attempted to switch into his lane. He attempted to avoid the collision by swerving and applying the brakes but could not avoid Veh2.

Veh1 sustained moderate damage to drivers side rear door. Veh2 sustained damage to Passenger side front fender and door.

Both advised and provided with a report number for the incident.

146. Officer's Signature PENA N	147. Badge # 169	148. Reviewer FALCONE J	Badge # 136	149. Case Status ☐ Pending ☒ Complete
---	----------------------------	-----------------------------------	-----------------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: NORTH BRUNSWICK Code: 01
Station: PATROL Case No: 20002886

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



PENA N

169