

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report											Case Number 20003429				Page <u>2</u> of <u>3</u>	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE NJTR-1B

145. Crash Description/Narrative

The driver of vehicle #2 stated in effect that she was traveling on Route 1 S in the left lane. Vehicle #1 was traveling directly behind vehicle #2. As vehicle #2 approached the intersection with Adams Lane W traffic began to stop for the upcoming red traffic signal. After vehicle #2 stopped, vehicle #1 was unable to stop in time and the front of vehicle #1 struck the rear of vehicle #2.

The driver of vehicle #1 stated in effect that he was traveling on Route 1 S directly behind vehicle #2. As the vehicles approached the intersection with Adams Lane W, vehicle #2 began to slow down and stopped with traffic. The driver of vehicle #1 did not see vehicle #2 stop, the front of vehicle #1 then struck the rear of vehicle #2.

My investigation concludes that the driver of vehicle #1 is at fault for following too closely and driver inattention. No injuries were reported. Nothing further at this time.

No notes were generated.

146. Officer's Signature MACMILLAN R	147. Badge # 182	148. Reviewer FRANGELLA R	Badge # 149	149. Case Status ☐ Pending ☒ Complete
--	----------------------------	-------------------------------------	-----------------------	---


New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: NORTH BRUNSWICK Code: 01

Station: - Case No: 20003429

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



MACMILLAN R

182