

New Jersey Police Crash Investigation Report											Case Number 20004540				Page <u>2</u> of <u>3</u>	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE NJTR-1B

145. Crash Description/Narrative

V1 WAS PARKED ALONG THE CURBLINE OF NORTH OAKS BLVD FACING LIVINGSTON AVENUE. V2 STRUCK V1 IN A SAME DIRECTION REAR END, CAUSING DISABLING DAMAGE TO THE REAR OF V1, PUSHING THE VEHICLE ABOUT 4FT FORWARD OF ITS ORIGINAL PARKED POSITION. V2 FLED THE SCENE. THERE ARE NO SURVEILLANCE CAMERAS IN THE AREA AND NO VEHICLE DESCRIPTION AVAILABLE. THERE WERE NO CAR PARTS FROM THE COLLISION. IT APPEARS THE DRIVER OF V2 CLEANED UP THE AREA BEFORE LEAVING THE SCENE.


146. Officer's Signature PORMILLI C	147. Badge # 177	148. Reviewer FALCONE J	Badge # 136	149. Case Status ☐ Pending ☒ Complete
---	----------------------------	-----------------------------------	-----------------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: NORTH BRUNSWICK Code: 01
Station: - Case No: 20004540

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



PORMILLI C

177