

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report											Case Number 20003864				Page <u>2</u> of <u>3</u>	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE NJTR-1B

145. Crash Description/Narrative

The investigation revealed that Vehicle 1 was parked in the parking lot of in the area of 308 Lisa Pl when the operator of the vehicle returned to find that the vehicle had been struck by an unknown vehicle causing damage to the front bumper. The other vehicle involved left the scene and no witnesses were identified.

146. Officer's Signature KIKELHAN	147. Badge # 176	148. Reviewer MCCORMICK M	Badge # 100	149. Case Status ☐ Pending ☒ Complete
---	----------------------------	-------------------------------------	-----------------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: NORTH BRUNSWICK Code: 01

Station: - Case No: 20003864

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



KIKELHAN

Officer's Signature

176

Badge Number