

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report											Case Number 20005411				Page <u>2</u> of <u>3</u>	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE NJTR-1B

145. Crash Description/Narrative

Investigation revealed that as V1 was driving westbound on Washington Place, approximately 200 feet east of Miriam Drive, a deer ran into the roadway in front of V1, causing V1 to strike it. D1 stated that he was driving west on Washington Place when the deer ran into the roadway forcing him to strike it with his vehicle. There were no injuries reported from this crash.


146. Officer's Signature WORKMAN M	147. Badge # 196	148. Reviewer UZUNIS R	Badge # 167	149. Case Status ☐ Pending ☒ Complete
--	----------------------------	----------------------------------	-----------------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: NORTH BRUNSWICK Code: 01
Station: - Case No: 20005411

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



WORKMAN M

196