

New Jersey Police Crash Investigation Report											Case Number 20005531				Page <u>2</u> of <u>3</u>	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE NJTR-1B

145. Crash Description/Narrative

Vehicle 1 (V1) was travelling behind vehicle 2 (V2) in the right lane on How Lane heading towards Jersey Ave. Driver of V1 stated the light had turned green and though traffic was moving quicker than it was but ended up hitting V2 from behind and pushing it into another vehicle. Driver of V2 stated the light had just turned green and upon starting she was suddenly hit from behind by V1 and pushed into the vehicle in front of her. The vehicle in front of V2 did not have any visible damage and did not wish to be on the accident report. Visible damage to the front end on V1 with front air bag deployment and visible damage to the front and rear end on V2. Both vehicles were towed by Puleio's towing. Based on driver statements and evidence at the scene, crash investigation revealed the driver of V1 at fault for inattention and he was issued summons 1215E20001304 for 39:4-97.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
TSUI L	162	MCCORMICK M	100	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: NORTH BRUNSWICK Code: 01

Station: - Case No: 20005531

144 Crash Diagram (NOT TO SCALE)



TSUI L

Officer's Signature

162

Badge Number