

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report											Case Number 20006131				Page <u>2</u> of <u>3</u>	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE NJTR-1B

145. Crash Description/Narrative

Vehicle 1 was making a left turn from Georges Road onto Hermann Road. Vehicle 2 was making a right turn from Georges Road to Hermann Road.

Driver 1 stated that vehicle 2 made a right turn very fast and hit his vehicle as he was turning left. Driver 2 stated that his light was green and he was making a right turn from Georges Road onto Hermann Road. Vehicle 1 tried to cut his turn early to get in front of him but ended up striking vehicle 2.

I observed debris in the roadway that would indicate vehicle 1 would have had to have make an improper turn. I also observed dash cam footage from vehicle 2.

Investigation reveals driver 1 turned improperly by cutting of the angle of his turn short and also did not yield the right of way to vehicle 2.

146. Officer's Signature GEYER J	147. Badge # 206	148. Reviewer FRANGELLA R	Badge # 149		149. Case Status ☐ Pending ☒ Complete
--	----------------------------	-------------------------------------	-----------------------	--	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: NORTH BRUNSWICK Code: 01
Station: - Case No: 20006131

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



GEYER J

Officer's Signature

206

Badge Number