

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report											Case Number 20004427				Page <u>2</u> of <u>3</u>	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE NJTR-1B

145. Crash Description/Narrative

Investigation revealed that Vehicle 1 was parked on the street and unoccupied in front of 510 Pine St when an unknown vehicle hit Vehicle 1 and fled in an unknown direction.

The registered owner of the vehicle was notified and advised the crash may have occurred between the hours of 2100 and 0030. No video surveillance was observed in the immediate area where Vehicle 1 was parked. Vehicle 1 sustained damage to the left front fender. No injuries were reported at this time.

Nothing further to report.

146. Officer's Signature DOMINGUEZ J	147. Badge # 202	148. Reviewer UZUNIS R	Badge # 167		149. Case Status ☒ Pending ☐ Complete
--	----------------------------	----------------------------------	-----------------------	--	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: NORTH BRUNSWICK Code: 01

Station: - Case No: 20004427

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



DOMINGUEZ J

Officer's Signature

202

Badge Number