

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report											Case Number 20000309				Page <u>2</u> of <u>3</u>	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE NJTR-1B

145. Crash Description/Narrative

The operator of v1 stated in effect, via translation by Ptl. Fernandez, she was traveling on Church Lane eastbound. While traveling, approximately 200 feet east of Old Georges Road, she became light headed and struck a fire hydrant. V1 continued approximately 15 feet and sideswiped a PSE&G utility pole (60595NBW) before coming to a rest approximately 20 feet away. She declined medical attention on scene.

No report of injuries. V1 sustained heavy front passenger corner damage and was removed from the scene by Southside Recovery Service.

Upon initial observation of the operator and completion of the investigation I determined the cause of the mvc was not medically related but appeared to be driver inattention only. The operator of v1 was subsequently issued a mv summons for 39:4-97 (careless driving).

146. Officer's Signature FALLETTA C	147. Badge # 125	148. Reviewer FALCONE J	Badge # 136		149. Case Status ☐ Pending ☒ Complete
---	----------------------------	-----------------------------------	-----------------------	--	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: NORTH BRUNSWICK Code: 01

Station: - Case No: 20000309

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



FALLETTA C

Officer's Signature

125

Badge Number