

**New Jersey Police
Crash Investigation Report**

Police Dept: **NEPTUNE CITY PD** Code: **01**
 Station: **-** Case No: **20NC05056**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Dept	Hosp Code	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A														
L														
E														
I														
N														
V														
O														
L														
V														
E														
I														
D														

144 Crash Diagram (NOT TO SCALE)

PRIVATE PROPERTY MVA - NO DIAGRAM

145 Crash Description/Narrative

Box 55 - New York State Insurance (337 Garrison Prop and Cas Ins. Company)

Vehicle #2 was traveling West in the Private Property Parking Lot of 36 SR-35 (Family Dollar). Vehicle #1 was traveling East, attempting to park in a marked parking space in the Private Property Parking Lot of Family Dollar. While Vehicle #1 was attempting to park in a parking space, Vehicle #2 started to drive East in the parking lot towards the exit. Driver #1 put Vehicle #1 in reverse traveling East, while still facing West without looking to the rear. When Driver #1 attempted to park Vehicle #1 in a parking space, Driver #1 did not see Vehicle #2. The rear bumper of Vehicle #1 then struck the rear bumper Vehicle #2, causing minor damage. Vehicle #1 also sustained minor damage to the rear of the vehicle.

Both Driver #1 and Driver #2 advised they were not injured and declined medical treatment at this time.

Both Vehicle #1 and Vehicle #2 were able to be driven from the scene.

146 Officer's Signature

BROSCHART, D

147 Badge #

35131

148 Reviewer

MV

Badge #

106

149 Case Status

☐ Pending ☒ Complete