

05

A

8

c

D


**New Jersey Police
Crash Investigation Report**

Police Dept: NEPTUNE CITY PD Code: 01
 Station: - Case No: 20NC05436

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Dept	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
L														
E														
L														
I														
N														
V														
O														
L														
H														
V														
E														
I														
D														
J														

144 Crash Diagram (NOT TO SCALE)



145 Crash Description/Narrative

collided with the back of Vehicle 2. Vehicle 2 was stopped yielding to on coming traffic.

Vehicle 1 and Vehicle 2 were traveling north on the State Route 35 south interchange. It should be noted Vehicle 2 had a occupant in the front passenger's seat. Vehicle 2 stopped yielding to oncoming traffic at the interchange between SR 35 Southbound and the Sylvania Ave ramp into Avon. Driver 1 stated while Vehicle 2 was to yielding to oncoming traffic, he pressed his foot on the accelerator too hard and caused the front of Vehicle 1 to collide with the rear of Vehicle 2. Vehicle 2 was stopped merging into oncoming traffic at the time of the collision. Vehicle 1 sustained minor damage to the front bumper. Vehicle 2 sustained minor damage to the rear fender. No injuries were reported by either party. Both vehicles were driven from the scene.

146 Officer's Signature

WILLIAMS, GE

147 Badge #

35134

148 Reviewer

SGT. MORGAN

Badge #

#124

149 Case Status

☐ Pending ☒ Complete