

**New Jersey Police
Crash Investigation Report**

Police Dept: **NEPTUNE CITY PD** Code: **01**
 Station: **-** Case No: **20NC07621**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Dept	Hosp Code	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A														
L														
L														
I														
N														
V														
O														
L														
V														
E														
I														
D														

144 Crash Diagram (NOT TO SCALE)

145 Crash Description/Narrative

Box #126a - Fuel Attendant Office (Located next to the fuel pump station).

Vehicle #1 was traveling north in the parking lot of 79 SR-35; Mobile Gas Station. As Vehicle #1 was attempting to pull up next to the fuel pump area it collided with the fuel attendant's office. The drivers side of Vehicle #1 collided with the southwest corner of the fuel attendant office, causing a large pane of glass to be dislodged and shatter onto the ground. Vehicle #1 sustained minor scratch marks as a result of the collision. The driver of Vehicle #1 did not complain of pain or injury.

146 Officer's Signature

MORGAN, N

147 Badge #

35124

148 Reviewer

SGT. MORGAN

Badge #

#124

149 Case Status

☐ Pending ☒ Complete