



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 55297	
Work Order #	55297
Service Date	07/10/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	639
Caller	Sani Umar

Location	Customer
UNION VA Union Valley Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Gym is too cold.

Unit #:	Description:
Make:	Serial#:
Work Performed: Gym is too cold. Found local setpoint on thermostat is not working, making cooling valve be commanded 100% open. Steve added logic in the JACE to make the setpoint a remote settable point. Once modified, cooling valve commanded closed but was still discharging 48 degree air. Found cooling valve actuator bad. Removed HW valve actuator and installed on the cooling valve actuator temporarily until replacement actuators can be installed. Ordered actuators and must return to install.	

Recommendations

Summary						
Materials						
PO 12543						
Labor						
Technician	Hours					
David Dougherty	Reg Labor	3.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	55263
Work Order #	55263
Service Date	07/09/2020
Ticket Type	Ctls T&M
Category	ATC T&M Service
Job#	750
Caller	Contract

Location	Customer
GLENLAND Glen Landing Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Pick up rebuilt pump from Jarvis

Unit #:	Description:
Make:	Serial#:
Work Performed: Picked up rebuilt pump from jarvis and dropped off pump in the hallway outside of the mechanical room.	

Recommendations

Summary						
Materials						
N/A						
Labor						
Technician	Hours					
David Dougherty	Reg Labor	2.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 55156

Work Order #: 55156

Service Date: 07/09/2020

Ticket Type: Serv T&M

Category: HVAC T&M Service

Job#: 1840

Caller: Sani Umar

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Chiller is down, needs service

Unit #: GTBOE_LF_CHR1	Description: CHILLER
Make:	Serial#:
Work Performed: chiller is tripping, circuit one has a bad suction transducer plug, removed plug from circuit 2 and put it on circuit 1, circuit 2 was isolated from a previous contractor, ordered new plugs and sensors, will return when sensors are in to replace, chiller is back online, changed filter sock on system we installed while onsite	

Recommendations

Summary						
Materials						
none						
Labor						
Technician	Hours					
David Schilling	Reg Labor	5.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 54994	
Work Order #	54922
Service Date	07/16/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	821
Caller	Contract

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Follow up on Ticket #54922 CST office has no cooling

Unit #:	Description:
Make:	Serial#:
Work Performed: Disconnected and removed old pulley and bearings. Installed new bearings and pulley. Aligned pulleys. Installed new belts. Started up system and verified operation.	

Recommendations

Summary						
Materials						
PO 12598						
Labor						
Technician	Hours					
David Dougherty	Reg Labor	4.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	54980
Work Order #	54980
Service Date	07/02/2020
Ticket Type	Ctls T&M
Category	ATC T&M Service
Job#	821
Caller	Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
PHONE SUPPORT

Unit #:	Description:
Make:	Serial#:
Work Performed: Rooms 807 and 809 were toggling their fans on/off. UNT programs need to be checked with HVAC Pro but added programming in the server to run the units for the time being.	

Recommendations

Summary						
Materials						
Labor						
Technician	Hours					
	Reg Labor	1.00	O/T Labor	0.00	Prem	0.00

Customer Signature



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #:	54933
Work Order #	54933
Service Date	07/02/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	821
Caller	Contract

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Rm 529 space sensor is damaged PO12477 Broudy tech pick up on the fly

Unit #:	Description:
Make:	Serial#:
Work Performed: -Checked multiple rooms for complaints of no cooling. Found warm/cool adjust sliders set all the way up, making the setpoints too high. Went through all of 800 wing classrooms and set warm/cool adjust sliders to the middle. Room 829 space sensor is hanging off the wall and is broken. Replaced space temp sensor. Tested and verified operation. -Guidance office is overheating. Found cooling valve and motor operational, but did not have sufficient airflow. Upon further inspection, found blower motor running backwards. Rotation is only able to be changed by disassembling motor and rotating orientation. Dissembled unit and rotated blower assembly. Reinstalled. Started up unit and verified sufficient cooling and airflow to space.	

Recommendations

Summary						
Materials						
PO 12477						
Labor						
Technician	Hours					
David Dougherty	Reg Labor	6.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 54922	
Work Order #	54922
Service Date	07/02/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	821
Caller	Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
CST office has no cooling

Unit #:	Description:
Make:	Serial#:
Work Performed: CST office has no cooling. Found belt broken. Upon further inspection, found the blower bearings are bad, causing slack in the bushing and belt tension which is causing the belts to break. Ordered new bearings and sheave. Must return to install	

Recommendations

Summary						
Materials						
PO 12474						
Labor						
Technician	Hours					
David Dougherty	Reg Labor	2.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 54706

Work Order #: 54607

Service Date: 06/24/2020

Ticket Type: Ctl's T&M

Category: ATC T&M Service

Job#: 738

Caller: Contract

Location

CHARLES
Charles W. Lewis Middle School

Customer

Gloucester Twp. Public Schools
17 Erial Rd.
Blackwood, NJ 08012

Work Requested

RTU4A is not cooling

Unit #:

Make:

Description:

Serial#:

Work Performed:

Worked with Dave D. to test cooling. Uploaded program and attempted PID tuning reset. This did not appear to resolve the issue. Recommending that the cooling be reprogrammed to be thermostatic rather than PID-based.

Recommendations

Summary

Materials

Labor

Technician

Hours

Stephen Suboleski

Reg Labor

0.50

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	54703
Work Order #	54609
Service Date	06/25/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	793
Caller	Contract

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Follow up on Ticket #54609 Hallway FCU is leaking water

Unit #:	Description:
Make:	Serial#:
Work Performed: Found water leak was from condensate back out. Disconnected and removed condensate drain pan. Cleaned pan out. Reinstalled pan and set the correct pitch. Dropped condensate line clevis hanger to increase pitch. Sprayed condensate pan liner to seal any potential hairline cracks.	

Recommendations

Summary					
Materials					
N/A					
Technician			Labor		
David Dougherty			Hours		
			Reg Labor	3.00	O/T Labor 0.00
					Prem 0.00

Customer Signature
Printed Name:
Master HVAC/R Contractor: Renee Fiorelli



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	54654
Work Order #	54654
Service Date	06/26/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	750
Caller	Sani Umar

Location	Customer
GLENLAND Glen Landing Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Disconnect & remove Boiler pump for repairs.

Unit #:	Description:
Make:	Serial#:
Work Performed: Picked up 5" blank off plates. Isolated circulator pump #1. Drained section of HW loop. Disconnected and removed circulator pump. Installed blank off flanges to prevent any water leaks in case a valve is opened up by accident prior to the rebuilt pump being installed. Brought pump to Jarvis to be rebuilt under customer's account	

Recommendations

Summary					
Materials					
N/A					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	8.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 54609	
Work Order #	54609
Service Date	06/24/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	793
Caller	Contract

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Hallway FCU is leaking water

Unit #:	Description:
Make:	Serial#:
Work Performed: Hallway FCU is leaking water. Disassembled ceiling and unit to let remaining water drain and let unit air out overnight. Must return to find the cause of the leak.	

Recommendations

Summary					
Materials					
N/A					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	2.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	54608
Work Order #	54608
Service Date	06/24/2020
Ticket Type	Ctls T&M
Category	ATC T&M Service
Job#	1192
Caller	Contract

Location	Customer
GLOUTWPSCHADMIN Gloucester Twp. Public Schools Admin. Bldg.	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Bus transportation ductless has water leak

Unit #:	Description:
Make:	Serial#:
Work Performed: Ductless split system is reported to be leaking water. Water was not leaking upon arrival. Ran system and verified water is draining properly out of condensate drain. Checked system pressure and superheat. Filters are clean and coil appears to be clean on the surface. Recommend blowing out coil with compressed air to clear any dirt buildup that has formed during the construction project. Checked indoor unit as it appears to be mounted on a slight slant opposite of the drain. Unit is not perfectly level and is pitched backwards. If water leak continues, recommend disconnect evaporator head and remounting bracket.	

Recommendations

Summary						
Materials						
N/A						
Labor						
Technician	Hours					
David Dougherty	Reg Labor	3.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	54607
Work Order #	54607
Service Date	06/24/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	738
Caller	Contract

Location	Customer
CHARLES Charles W. Lewis Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
RTU4A is not cooling

Unit #:	Description:
Make:	Serial#:
Work Performed: JCI RTU-4A is not cooling. JCI has previously said it is a physical mechanical issue within the unit and that the controller is calling for cooling but the unit is not running. Upon arrival, space temp was 75 degrees with effective cooling of 73 degrees. Controller is commanding cooling on and off to maintain 75 degrees even though setpoint is 73. Override cooling command on to verify the system is operating as it should mechanically and is cooling space as designed. Lowered setpoint to 72 degrees and cooling command is being terminated when space temp is 74 degrees. Connected to controller and uploaded program. Verified the PID is enabling/disabling the call for cooling 2+ degrees over setpoint. The problem is definitely a control issue, not a mechanical issue.	

Recommendations

Summary						
Materials						
N/A						
Labor						
Technician	Hours					
David Dougherty	Reg Labor	3.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:		54606
Work Order #		54477
Service Date		06/25/2020
Ticket Type		CtIs T&M
Category		ATC T&M Service
Job#		793
Caller		Sani Umar

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Follow up on Ticket #54477 Main Office is overheating.

Unit #:	Description:
Make:	Serial#:
Work Performed: Picked up actuator and installed in unit. Verified cooling into space.	

Recommendations

Summary					
Materials					
PO 12340					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	2.50	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 54593	
Work Order #	54202
Service Date	06/26/2020
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1840
Caller	Dave Schilling

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Install filter sock system

Unit #: GTBOE_LF_CHR1	Description: CHILLER
Make:	Serial#:
Work Performed: finished installing sock system and piping, leak tested and insulated, pulled pump strainers and cleaned.	

Recommendations

Summary						
Materials						
12408						
Labor						
Technician	Hours					
David Schilling	Reg Labor	6.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson
Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #: 54513

Work Order #: 54513

Service Date: 06/24/2020

Ticket Type: Serv T&M

Category: HVAC T&M Service

Job#: 1141

Caller: Sani Umar

Location

CHARLES
Charles W. Lewis Middle School

Customer

Gloucester Twp. Public Schools
17 Erial Rd.
Blackwood, NJ 08012

Work Requested

COMBUSTION AND ADJUST - GET NOX READING

Unit #:

Description:

Make:

Serial#:

Work Performed:

Took a combustion efficiency analysis on the RHF #2 Boiler and recorded results.
Could not perform a test on Boiler #1. The blower motor starter kept pulling in and out. Diagnosed and found the program board on the For eye Flame Safeguard control is bad and needs to be replaced to run the boiler.
The problem will need to be resolved before a test can be completed.

The #2 Boiler has a Honeywell Control on it and could not be swapped out to complete the efficiencies.

Recommendations

Need to replace the EP160 Program board on the E100 Fireye Flame Safeguard Control on the LHF #1 boiler. {Prop3927 to follow}

Summary

Materials

Labor

Technician

Hours

Robert Reillo

Reg Labor

4.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 54512	
Work Order #	54512
Service Date	06/24/2020
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1578
Caller	Sani Umar

Location	Customer
GLENLAND Glen Landing Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
COMBUSTION AND ADJUST - GET NOX READING

Unit #: BLR1	Description: BLR1
Make:	Serial#:
Work Performed: Took a combustion efficiency analysis of the boiler (LG HB Smith) and made adjustments and recorded results.	

Recommendations

Summary					
Materials					
Labor					
Technician	Hours				
Robert Reillo	Reg Labor	4.00	O/T Labor	0.00	Prem 0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	54477
Work Order #	54477
Service Date	06/22/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	793
Caller	Sani Umar

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Main Office is overheating.

Unit #:	Description:
Make:	Serial#:
Work Performed: Main office is overheating. Traced back to a Trane FCU in the closet. Found air filter very dirty. Unable to find any spare filters on site. Tested unit and found CW actuator is not driving open with call for cooling. Actuator is bad and must be replaced. Opened bypass valve. Still no flow. Traced piping back and found multiple units in the surrounding area do not have any cooling. Found pump 7/8 were off in the mechanical room. Looked at old control graphics and verified pumps 7/8 need to run to provide cooling/heating to the interior loop. Turned pump on. Verified chilled water flow through loop. Ordered replacement actuator. Must return to install actuator.	

Recommendations

Summary						
Materials						
PO 12340						
Labor						
Technician	Hours					
David Dougherty	Reg Labor	8.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 54250	
Work Order #	54249
Service Date	06/25/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	793
Caller	Sani Umar

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Follow up on Ticket #54249 Library FCU not running.

Unit #:	Description:
Make:	Serial#:
Work Performed: Picked up motor and installed in unit. Rear bearing is bad. Replaced bearing. Ran unit and verified operation.	

Recommendations

Summary						
Materials						
PO 12341						
Labor						
Technician	Hours					
David Dougherty	Reg Labor	2.50	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	54249
Work Order #	54249
Service Date	06/18/2020
Ticket Type	Ctls T&M
Category	ATC T&M Service
Job#	793
Caller	Sani Umar

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Library FCU not running.

Unit #:	Description:
Make:	Serial#:
Work Performed: Library FCU is not running. Found motor trying to run but no spinning and very hot. Checked capacitor and found capacitor value to be below the 10% threshold and needs to be replaced. Replaced capacitor and waited for motor to cool down before restoring power. Once powered up, motor did not turn over. Motor is bad and needs to be replaced. Ordered new motor and will return to install	

Recommendations

Summary					
Materials					
PO 12331					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	2.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson
Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #: 54248

Work Order #: 54248

Service Date: 06/19/2020

Ticket Type: Ctls T&M

Category: ATC T&M Service

Job#: 793

Caller: Sani Umar

Location

LORING-F
Loring-Flemming School

Customer

Gloucester Twp. Public Schools
17 Erial Rd.
Blackwood, NJ 08012

Work Requested

B-3 classroom is too cold.

Unit #:

Description:

Make:

Serial#:

Work Performed:

-Classroom is too cold. Disassembled unit to be able to access control valve and pneumatic controls. Troubleshoot system. Found 2 relays not allowing the correct amount of air pressure through and replaced. Tested pneumatic dual temp valve with manual air pressure and found valve body to be passing, allowing chilled water to always flow through the coil and overcool space. Entire 3-Way valve body and actuator will have to be replaced with new piping. Ordered replacement valve. Must return to install.

-Began to investigate stage AHU which has been abandoned for a duration of time. Isolation valves are closed. All of the pneumatic components have been removed. There is a chance that the isolation valves could break when attempting to open them. It would take significant amount of time and components to rebuild the two stage AHU's to get them working again.

Recommendations

Summary

Materials

PO 12330

Labor

Technician

Hours

David Dougherty

Reg Labor

8.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 53172

Work Order #: 51220

Service Date: 05/22/2020

Ticket Type: Serv T&M

Category: HVAC T&M Service

Job#: 1336

Caller: Sani Umar

Location

ANN MULL2
Ann A.Mullen Middle School

Customer

Gloucester Twp. Public Schools
17 Erial Rd.
Blackwood, NJ 08012

Work Requested

CHILLER MAINTENANCE AND START UP

Unit #: GTAAMMS_CT

Description: COOLING TOWER

Make:

Serial#:

Work Performed:

worked with Dave Schilling on cooling tower. Grinded off all the old layer of sealant for new coat to be layed.

Recommendations

Summary

Materials

12126

Labor

Technician

James McDermott

Hours

Reg Labor

8.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:		53105
Work Order #		51220
Service Date		05/22/2020
Ticket Type		Serv T&M
Category		HVAC T&M Service
Job#		1336
Caller		Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
NEED TO RETURN TO FILL COOLING TOWER CHILLER MAINTENANCE AND START UP

Unit #: GTAAMMS_CT	Description: COOLING TOWER
Make:	Serial#:
Work Performed: finished grinding and prepping cooling tower basin to be epoxyed, need to return to complete	

Recommendations

Summary						
Materials						
12143; 11748						
Labor						
Technician	Hours					
David Schilling	Reg Labor	8.00	O/T Labor	0.00	Prem	0.00
Customer Signature						
Printed Name:						



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #: 53083

Work Order #: 51220

Service Date: 05/20/2020

Ticket Type: Serv T&M

Category: HVAC T&M Service

Job#: 1336

Caller: Sani Umar

Location

ANN MULL2
Ann A.Mullen Middle School

Customer

Gloucester Twp. Public Schools
17 Erial Rd.
Blackwood, NJ 08012

Work Requested

Follow up on Ticket #51220>>>NEED TO RETURN TO FILL COOLING TOWER CHILLER MAINTENANCE AND START UP

Unit #:

Description:

Make:

Serial#:

Work Performed:

cleaned and powerwashed cooling tower, began prepping the cooling tower basin to be re sealed,

Recommendations

Summary

Materials

11748; 12126

Labor

Technician

Hours

David Schilling

Reg Labor

8.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #: 53029

Work Order #: 53029

Service Date: 05/15/2020

Ticket Type: Ctls T&M

Category: ATC T&M Service

Job#: 1192

Caller: Contract

Location

GLOUTWPSCHADMIN

Gloucester Twp. Public Schools Admin. Bldg.

Customer

Gloucester Twp. Public Schools

17 Erial Rd.

Blackwood, NJ 08012

Work Requested

Install new PTAC unit in Transportation department

Unit #:

Description:

Make:

Serial#:

Work Performed:

- Disconnected and removed old PTAC unit and casing. Widen the wall for new PTAC casing. Installed new PTAC and verified operation.
- Verified flow through Loring Fleming Dual temp loop

Recommendations

Summary

Materials

N/A

Labor

Technician

Hours

David Dougherty

Reg Labor

8.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:

Master HVAC/R Contractor: Renee Fiorelli

Page 1 of 1

Master HVAC/R Contractor Lic#: 19HC00380500



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #: 52904

Work Order #: 52744

Service Date: 05/15/2020

Ticket Type: Serv T&M

Category: HVAC T&M Service

Job#: 1840

Caller: SCHILLING

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Follow up on Ticket #52744 - SEASONAL SWITCH OVER

drained glycol from chiller one and chiller 2 into buckets and stored onsite, filled both chilled water loops, tested chiller operation, both

Unit #: GTBOE_LF_CHRI	Description: CHILLER
Make:	Serial#:
Work Performed: picked up flow switch locally, isolated drained and replaced switch, tested operation, chiller back online	

Recommendations

Summary						
Materials						
flow switch						
Labor						
Technician	Hours					
David Schilling	Reg Labor	2.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	52897
Work Order #	52897
Service Date	05/13/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	639
Caller	Contract

Location	Customer
UNION VA Union Valley Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Water leak in mechanical Room

Unit #:	Description:
Make:	Serial#:
Work Performed: Found water leaking at HW 3-way valve from victaulic fitting. Tightened all victaulic fittings and verified no leaks present. Boiler on right gas pressure switch was tripped. Reset switch and fired up both boilers. Verified operation	

Recommendations

Summary					
Materials					
N/A					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	3.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 52896

Work Order #	52896
Service Date	05/13/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	793
Caller	Contract

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Start Up Chilled Water system

Unit #:	Description:
Make:	Serial#:
Work Performed: Changed mechanical system over from winter to summer. Verified correct valve position of change over valves. Started up chillers but was having flow issues. Continued purging air. Opened up small chiller pump suction diffusers and found the strainers were clogged with mud in the diffuser. As system was running, found chilled water was flowing through the boilers. Found both HW Bypass 3-way valves were calling to be closed but were open, allowing chilled water into the boilers. Closed valves but there was still chilled water flowing through boilers. Must return to continue troubleshooting.	
JCI	

Recommendations

Summary					
Materials					
N/A					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	4.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	52753
Work Order #	52753
Service Date	05/08/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	821
Caller	Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Replace radiation valve.

Unit #:	Description:
Make:	Serial#:
Work Performed: -Isolated radiation control valve and drained section. Cut out bad valve body and installed new control valve with actuator. Installed unions for future removal of valve body. Leak checked. Tested operation of actuator. -Began prepping P-TAC through the wall unit for replacement	

Recommendations

Summary						
Materials						
PO 12057						
Labor						
Technician	Hours					
David Dougherty	Reg Labor	8.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 52744

Work Order #: 52744

Service Date: 05/13/2020

Ticket Type: Serv T&M

Category: HVAC T&M Service

Job#: 1840

Caller: SCHILLING

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
SEASONAL SWITCH OVER PO 12082 FOR UNITED

Unit #: GTBOE_LF_CHR1	Description: CHILLER
Make:	Serial#:
Work Performed: drained glycol from chiller one and chiller 2 into buckets and stored onsite, filled both chilled water loops, tested chiller operation, both chillers need the coils cleaned so we will need to return, chiller one has a bad flow switch, ordered switch, will return to replace when part is in.	

Recommendations

Summary						
Materials						
none						
Labor						
Technician	Hours					
David Schilling	Reg Labor	8.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 52249

Work Order #: 52184

Service Date: 04/17/2020

Ticket Type: Ctl's T&M

Category: ATC T&M Service

Job#: 647

Caller: Sani Umar

Location	Customer
ERIAL EL Erial Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Follow up on Ticket #52184 Water leak in C-wing classroom.

Unit #:	Description:
Make:	Serial#:
Work Performed: Picked up new valve body and actuator. Finished draining loop. Once loop was drained, cut out bad HW valve actuator. Installed new valve body and actuator. Unable to fill system and test for leaks until facilities cuts in new isolation valves.	

Recommendations

Summary

Materials

PO 11945

Labor

Technician	Hours			
	Reg Labor	O/T Labor	Prem	
David Dougherty	4.50	0.00	0.00	

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	52184
Work Order #	52184
Service Date	04/15/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	647
Caller	Sani Umar

Location	Customer
ERIAL EL Erial Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Water leak in C-wing classroom.

Unit #:	Description:
Make:	Serial#:
Work Performed: Began to isolate HW system to stop water leak from FCU. Once drained, the bad valve body will have to be replaced. Ordered valve body and will have to return to install	

Recommendations

Summary					
Materials					
PO 11945					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	1.50	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson
Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #: 51349

Work Order #: 51220

Service Date: 05/19/2020

Ticket Type: Serv T&M

Category: HVAC T&M Service

Job#: 1336

Caller: Sani Umar

Location

ANN MULL2
Ann A.Mullen Middle School

Customer

Gloucester Twp. Public Schools
17 Erial Rd.
Blackwood, NJ 08012

Work Requested

Follow up on Ticket #51220>>>NEED TO RETURN TO FILL COOLING TOWER, CHILLER MAINTENANCE AND START UP

Unit #: CHI

Description: Chiller 1

Make: TRANE

Serial#:

Work Performed:

began chiller startup, started cleaning cooling tower need to return to continue

Recommendations

Summary

Materials

11748; 12126

Labor

Technician

Hours

David Schilling

Reg Labor

5.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	51269
Work Order #	51269
Service Date	03/13/2020
Ticket Type	Ctls T&M
Category	ATC T&M Service
Job#	639
Caller	Contract

Location	Customer
UNION VA Union Valley Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Main Office is overheating

Unit #:	Description:
Make:	Serial#:
Work Performed: Found AC2 lockout relay was energized, preventing the compressor from running. Reset lockout relay and compressor started up. Monitored operation to verify system began to cool space and came down to setpoint	

Recommendations

Summary						
Materials						
N/A						
Labor						
Technician	Hours					
David Dougherty	Reg Labor	2.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	51265
Work Order #	51265
Service Date	03/13/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	750
Caller	Contract

Location	Customer
GLENLAND Glen Landing Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
HW system is overheating

Unit #:	Description:
Make:	Serial#:
Work Performed: -School is overheating. Found this was because HW enable OA setpoint was set for 65 degrees. Lowered setpoint down to 60 degrees. Went through all schools on JCI system and lowered OA enable setpoint to prevent schools from overheating. -Gathered info for Chillers at Fleming and Mullen. -Contacted Jarvis for Glen Landing Pump repair	

Recommendations

Summary					
Materials					
N/A					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	4.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	51261
Work Order #	51261
Service Date	03/12/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	738
Caller	Contract

Location	Customer
CHARLES Charles W. Lewis Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Room 311 space temp is reading 150 degrees

Unit #:	Description:
Make:	Serial#:
Work Performed: Space temp is reading 150 degrees which is causing the heat to be disabled. Found the mixed air temp was also reading excessively high. Found both space temp and mixed air temp sensor wires had loose connections at the UNT controller. Re-crimped wire and reinstalled. Both sensors began to read correct temps. Monitored system and verified operation.	

Recommendations

Summary					
Materials					
N/A					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	2.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Work Order #	51260
Service Date	03/12/2020 51260
Ticket Type	Ctlis T&M
Category	ATC T&M Service
Job#	1192
Caller	Contract

✓

Location	Customer
OUTWPSCHADMIN Gloucester Twp. Public Schools Admin. Bldg.	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
U for secretary's office is overheating

Description:
Work Performed: U for secretary's office is overheating. Found the indoor air temperature sensor was located in an area that had outdoor air infiltrating and passing over the sensor. This was causing the sensor to read a low temperature and think the space was too cold and commanding the unit to run in heating mode. Repositioned the sensor so it is away from any outdoor air and is sensing the true space return air. Tested and verified operation. Cleaned return air filter.

Recommendations

Summary

Materials

/A

Technician	Labor				Hours	
	Reg Labor	O/T Labor	Prem			
David Dougherty	1.00	0.00				0.00

Customer Signature

--

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 52249	
Work Order #	52184
Service Date	04/17/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	647
Caller	Sani Umar

Location	Customer
ERIAL EL Erial Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Follow up on Ticket #52184 Water leak in C-wing classroom.

Unit #:	Description:
Make:	Serial#:
Work Performed: Picked up new valve body and actuator. Finished draining loop. Once loop was drained, cut out bad HW valve actuator. Installed new valve body and actuator. Unable to fill system and test for leaks until facilities cuts in new isolation valves.	

Recommendations

Summary						
Materials						
PO 11945						
Labor						
Technician	Hours					
David Dougherty	Reg Labor	4.50	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	51243
Work Order #	51243
Service Date	03/12/2020
Ticket Type	Ctls T&M
Category	ATC T&M Service
Job#	821
Caller	Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
CST Room overheating.

Unit #:	Description:
Make:	Serial#:
Work Performed: CST Room is overheating. Found HW valve actuator is bad. Replaced actuator with one from customer stock. Also found the baseboard control valve was open. Commanded valve closed but actuator did not respond. Actuator is bad and must be replaced. There are signs that the valve stem packing was leaking at some point. Valve body must be replaced in addition to the actuator. Ordered replacement valve body and actuator. Must return at a later date to install.	

Recommendations

Summary					
Materials					
PO 11760					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	4.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	51236
Work Order #	51220
Service Date	03/13/2020
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1336
Caller	Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
CHILLER MAINTENANCE AND START UP PO 11748 FOR MATERIALS

Unit #:	Description:
Make:	Serial#:
Work Performed: Assisted in CHILLER startup. Punched tubes with Good way Machine and mounted head back on chiller	

Recommendations

Summary						
Materials						
n/a						
Labor						
Technician	Hours					
Philip Dorman	Reg Labor	8.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	51224
Work Order #	54202
Service Date	06/23/2020
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1840
Caller	Sani Umar

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Install filter sock system

Unit #: GTBOE_LF_CHRI	Description: CHILLER
Make:	Serial#:
Work Performed: picked up water filter locally, began installing filter and piping, need to return to continue	

Recommendations

Summary					
Materials					
12361					
Labor					
Technician	Hours				
David Schilling	Reg Labor	7.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:		51223
Work Order #	51223	
Service Date	06/10/2020	
Ticket Type	Serv T&M	
Category	HVAC T&M Service	
Job#	1840	
Caller	Sani Umar	

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
CHILLER MAINTENANCE AND START UP

Unit #: GTBOE_LF_CHR1	Description: CHILLER
Make:	Serial#:
Work Performed: started cleaning coils on both chillers.	

Recommendations

Summary					
Materials					
11750; coil cleaner					
Labor					
Technician	Hours				
David Schilling	Reg Labor	5.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	51221
Work Order #	51221
Service Date	05/28/2020
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1578
Caller	Sani Umar

Location	Customer
GLENLAND Glen Landing Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
CHILELR MAINTENANCE AND START UP PO 11749 FOR MATERIALS

Unit #:	Description:
Make:	Serial#:
Work Performed: started chiller 1, and 2, tested operation readings for both chillers are in forms, started cleaning condenser coils, need to return to finish cleaning	

Recommendations
pipng for chilled water pump is sagging badly, we will need to install some hangers to support pipe, will need to return to fix issue

Summary					
Materials					
none					
Labor					
Technician	Hours				
David Schilling	Reg Labor	8.00	O/T Labor	0.00	Prem
					0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	51220
Work Order #	51220
Service Date	03/13/2020
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1336
Caller	Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
CHILLER MAINTENANCE AND START UP PO 11748 FOR MATERIALS

Unit #:	Description:
Make:	Serial#:
Work Performed: removed oil from sump, replaced oil filter, added new oil to correct level, changed purge dryer, drained condenser, dropped condenser head and brushed tubes, put head back up with new o ring, filled barrel and leak tested, need to return to fill cooling tower.	

Recommendations

Summary					
Materials					
po 11757					
Labor					
Technician	Hours				
David Schilling	Reg Labor	8.00	O/T Labor	0.00	Prem 0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #: 51080

Work Order #: 51080

Service Date: 06/05/2020

Ticket Type: Serv T&M

Category: HVAC Quote

Job#: 722

Caller: Sani Umar

Location

UNION VA
Union Valley Elementary School

Customer

Gloucester Twp. Public Schools
17 Erial Rd.
Blackwood, NJ 08012

Work Requested

Ticket created from Quote #3299 PO# 004484

Technician recommendations from Ticket#49089

Unit #:

Description:

Make:

Serial#:

Work Performed:

Boiler 1A, Replaced components as quoted. In addition, I found the gas actuator is leaking fluid and should also be replaced.

Recommendations

Replace Honeywell V4055A1062 gas actuator. Ordered at Broudy's PO 12215 will be in 6/8 for pu. Will need to adjust the burner with the analyzer when completed.

Summary

Materials

PO 11719

Labor

Technician

Robert Reillo

Hours

Reg Labor

4.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:

Master HVAC/R Contractor: Renee Fiorelli

Page 1 of 1

Master HVAC/R Contractor Lic#: 19HC00380500



Peterson
Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #:	51065
Work Order #	51065
Service Date	03/06/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	804
Caller	Contract

Location	Customer
GLENDORA Glendora Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Gym is overheating

Unit #:	Description:
Make:	Serial#:
Work Performed: JCI Gym is overheating with HW valve being commanded closed. Valve is physically open causing high DA temp. Commanded valve open and closed but actuator did not respond to commands. Found the signal being sent from JCI controller is a modulating DC signal but the actuator is a 24v floating actuator. JCI must come back out and change their signal and commission actuator.	

Recommendations

Summary					
Materials					
N/A					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	2.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #:	51008
Work Order #	51008
Service Date	03/06/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	804
Caller	Sani Umar

Location	Customer
GLENDORA Glendora Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Radiation valve making a banging noise.

Unit #:	Description:
Make:	Serial#:
Work Performed: Radiation piping in Nurse's office is making a banging noise when open/closing hydronic valve. Isolated and drained piping. Rotated valve body to change direction. Reconnected piping and filled system. Tested valve operation several times and banging noise is no longer there. Tested Main Office AHU for cooling as they are complaining they are too hot. Found RIB relay is bad and not making closed contacts for cooling enable. Replaced relay and verified operation.	

Recommendations

Summary					
Materials					
PO 11710					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	3.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	50770
Work Order #	50683
Service Date	02/28/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	804
Caller	Sani Umar

Location	Customer
GLENDORA Glendora Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Follow up on Ticket #50683 Nurse's office overheating.

Unit #:	Description:
Make:	Serial#:
Work Performed: -Drained baseboard loop and cut section of pipe out. Installed ball valves, unions, and pneumatic valve. Filled system and pressure tested. Verified operation. -Installed low ambient temperature switch in PTAC unit and tested. Installed PTAC in Latchkey office.	

Recommendations

Summary

Materials

Previous ticket has PO

Labor

Technician	Hours			
	Reg Labor	O/T Labor	Prem	
David Dougherty	7.00	0.00		0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	50683
Work Order #	50683
Service Date	02/27/2020
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	804
Caller	Sani Umar

Location	Customer
GLENDORA Glendora Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Nurse's office overheating.

Unit #:	Description:
Make:	Serial#:
Work Performed: Nurse's office is overheating. Upon troubleshooting, found the baseboard control valve actuator has broken off of the valve body itself, causing the hot water valve to be 100% open at all times. There is a fixed bookshelf cabinet that is unable to be moved to access the valve so will have to work through the cabinet. Valve must be replaced. Isolated baseboard section and began draining. Isolation valves are passing. Picked up material with new valve assembly. Must return to install.	

Recommendations

Summary					
Materials					
PO 11633					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	4.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	50500
Work Order #	50500
Service Date	02/26/2020
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	2394
Caller	Sani Umar

Location	Customer
CHEWS EL Chews Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
PTO room unit not functioning.

Unit #:	Description:
Make:	Serial#:
Work Performed: found unit not responding to a call for heat. checked unit function and bypassed tstat to operate controls. unit responds to jumping out tstat. retrieved new stat and wired to unit function. operation satisfactory. notified facilities that Johnson Controls tstat is malfunctioning and will need to be addressed due to warranty issue. Left new stat in play and let personnel know of condition.	

Recommendations

Summary					
Materials					
PO 11621, Broudys- thermostat					
Labor					
Technician	Hours				
David Birkey	Reg Labor	8.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name: