



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	44562
Work Order #	44562
Service Date	10/17/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1336
Caller	Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Investigate unit- classroom troubleshooting- Classroom 206

Unit #:	Description:
Make:	Serial#:
Work Performed: Found unit fan switched off. fan motor is not functioning. will need to replace. Unable to receive support from manufacturer. Will continue at later time.	

Recommendations

Summary

Materials

00

Labor

Technician

David Birkey

Hours

Reg Labor

1.50

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 44550	
Work Order #	44550
Service Date	10/17/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1336
Caller	Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Investigate exhaust fan girls locker room.

Unit #:	Description:
Make:	Serial#:
Work Performed: Found exhaust fan switched off on rooftop. also fan is out of alignment and rubbing on the housing. Corrected alignment and placed back into operation.	

Recommendations

Summary

Materials

00

Labor

Technician	Hours				
	Reg Labor	O/T Labor	Prem		
David Birkey	2.50	0.00	0.00		

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 44540

Work Order #	44537
Service Date	10/18/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1336
Caller	Sani Umar

Location

ANN MULL2
Ann A.Mullen Middle School

Customer

Gloucester Twp. Public Schools
17 Erial Rd.
Blackwood, NJ 08012

Work Requested

INSTALL 3 HEATING COILS

JOEL AND ADAM WORKING ON THIS

Unit #:

Make:

Description:

Serial#:

Work Performed:

Worked with Joel to begin replacement of unit coils.

Recommendations

Summary

Materials

n/a

Labor

Technician

Adam Jordan

Hours

Reg Labor

8.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:

Master HVAC/R Contractor: Renee Fiorelli



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 44537	
Work Order #	44537
Service Date	10/18/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1336
Caller	Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

INSTALL 3 HEATING COILS

Unit #:	Description:
Make:	Serial#:
Work Performed: Heating coil installation	

Recommendations

Summary

Materials

na

Labor

Technician	Hours				
	Reg Labor	O/T Labor	Prem		
Joel Aramburo	8.00	0.00	0.00		

Customer Signature

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 44512	
Work Order #	44512
Service Date	10/17/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	722
Caller	Sani Umar

Location	Customer
UNION VA Union Valley Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

motor install

Unit #:	Description:
Make:	Serial#:
Work Performed: Motor supplied by Gloucester Township Schools. Accessed old motor in FCU 4. Removed motor and installed new. Made electrical connections and restored power. Unit operation is satisfactory at this time.	

Recommendations

Summary

Materials

00 customer supplied all parts necessary

Labor

Technician	Hours				
	Reg Labor	O/T Labor	Prem		
David Birkey	4.00	0.00	0.00		

Customer Signature

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	44399
Work Order #	43874
Service Date	10/16/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1141
Caller	Sani Umar

Location	Customer
CHARLES Charles W. Lewis Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

INSTALL 2 DUCTLESS SPLIT SYSTEMS

CUSTOMER ORDERED MATERIALS.

Unit #:	Description:
Make:	Serial#:
Work Performed: Retrieved electrical materials from supply house and delivered to site. ran electric from disconnect to condenser. tied in control wire. evacuated line set. installed condensate pump. charged line set. operated unit. and cleaned up site.	

Recommendations

Summary

Materials

10479 conduit, condensate pump and wire. Johnstone Supply

Labor

Technician	Hours				
	Reg Labor	O/T Labor	Prem		
David Birkey	8.00	0.00	0.00	0.00	0.00

Customer Signature

[Handwritten Signature]

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	44340
Work Order #	43874
Service Date	10/15/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1141
Caller	Sani Umar

Location	Customer
CHARLES Charles W. Lewis Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

INSTALL 2 DUCTLESS SPLIT SYSTEMS

CUSTOMER ORDERED MATERIALS.

Unit #:	Description:
Make:	Serial#:
Work Performed: condenser arrived for Guidance office install. set condenser on mounting bracket. ran line set and made connections. checked for leaks. repaired 2 bad joints. checked again and found satisfactory check. left nitrogen holding charge. will return to continue install, electrical and condensate pump, evacuate and charge.	

Recommendations

Summary

Materials

00 customer supplied all parts necessary

Labor

Technician	Hours				
	Reg Labor	O/T Labor	Prem		
David Birkey	8.00	0.00	0.00	0.00	

Customer Signature

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	44154
Work Order #	43874
Service Date	10/14/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1141
Caller	Sani Umar

Location	Customer
CHARLES Charles W. Lewis Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
INSTALL 2 DUCTLESS SPLIT SYSTEMS CUSTOMER ORDERED MATERIALS.

Unit #:	Description:
Make:	Serial#:
Work Performed: disconnected and removed old evap head in room 219. installed new mounting plate and evap head. connected line sets and electrical. set new condenser and connected electrical and piping. pressure tested for leaks. set up and evacuated. charged lines with condenser holding charge. operation satisfactory at this time.	

Recommendations

Summary						
Materials						
00						
Labor						
Technician	Hours					
David Birkey	Reg Labor	8.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	44153	In Progress
Work Order #	43874	
Service Date	10/11/2019	
Ticket Type	Serv T&M	
Category	HVAC T&M Service	
Job#	1141	
Caller	Sani Umar	

Location	Customer
CHARLES Charles W. Lewis Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

INSTALL 2 DUCTLESS SPLIT SYSTEMS

CUSTOMER ORDERED MATERIALS.

Unit #:	Description:
Make:	Serial#:
Work Performed: Finished electric and start up of nurses office unit. mounted condenser bracket for guidance office. Awaiting condenser. Removed condenser and mounted bracket for special needs classroom. will return Monday when school is on holiday to continue special needs classroom.	

Recommendations

Summary

Materials

PO 10454 Johnstone supply for electrical connections

Labor

Technician	Hours			
	Reg Labor	O/T Labor	Prem	
David Birkey	8.00	0.00	0.00	0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #:	43951
Work Order #	43951
Service Date	10/04/2019
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	1901
Caller	Contract

Location	Customer
UNION VA Union Valley Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

FCU-48 is not cooling space

Unit #:	Description:
Make:	Serial#:
Work Performed: Found blower motor is not running. Verified 277v is being supplied to the motor. Found there is a rub through on one of the wires that shorted motor to ground. Motor is bad and must be replaced. Contacted Jarvis Motors who will be sending over price and availability to GTPS.	

Recommendations

Summary

Materials

None

Labor

Technician	Hours			
	Reg Labor	O/T Labor	Prem	
David Dougherty	2.00	0.00		0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	43950
Work Order #	43950
Service Date	10/04/2019
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	1192
Caller	Contract

Location	Customer
GLOUTWPSCHADMIN Gloucester Twp. Public Schools Admin. Bldg.	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Connect and setup new Comcast Modem

Unit #:	Description:
Make:	Serial#:
Work Performed: Transferred devices from old Comcast Modem to the new Comcast Modem. Enabled/Setup all port forwarding rules. Changed new IP address in the Server. Issued new IP address to Head Custodians.	

Recommendations

Summary					
Materials					
None					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	3.00	O/T Labor	0.00	Prem
				0.00	

Customer Signature
Printed Name:
Master HVAC/R Contractor: Renee Fiorelli



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 43949	
Work Order #	43949
Service Date	10/04/2019
Ticket Type	CtIs T&M
Category	ATC T&M Service
Job#	750
Caller	Contract

Location	Customer
GLENLAND Glen Landing Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Rm 608 is cold

Unit #:	Description:
Make:	Serial#:
Work Performed: -Room 608 is overcooling. Actuator is not moving even though it is getting a signal to drive open/close. Disconnected actuator and drove. Reinstalled actuator and stroked. Actuator drove open and closed. Actuator is in working condition. Suspect that valve needle was not touching actuator stem. -Gym exhaust fans are not operational. This is due to the gym AHU controllers being turned off/offline as these controllers control the exhaust fan enables. Until the controllers power are restored, the exhaust fans must be manually controlled. Reinstalled HOA switches to control both gym exhaust fans on the boys locker room side. Tested and verified operation.	

Recommendations

Summary

Materials

None

Labor

Technician	Hours				
	Reg Labor	O/T Labor	Prem		
David Dougherty	3.00	0.00	0.00		

Customer Signature

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 43877	
Work Order #	43874
Service Date	10/10/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1141
Caller	Sani Umar

Location	Customer
CHARLES Charles W. Lewis Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

INSTALL 2 DUCTLESS SPLIT SYSTEMS

CUSTOMER ORDERED MATERIALS.

Unit #:	Description:
Make:	Serial#:
Work Performed: Began layout for guidance office condenser wall mount.	

Recommendations

Summary

Materials

00

Labor

Technician	Hours				
	Reg Labor	O/T Labor	Prem		
David Birkey	1.50	0.00	0.00		

Customer Signature

N O R R P

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 43876

Work Order #: 43874

Service Date: 10/09/2019

Ticket Type: Serv T&M

Category: HVAC T&M Service

Job#: 1141

Caller: Sani Umar

Location

CHARLES
Charles W. Lewis Middle School

Customer

Gloucester Twp. Public Schools
17 Erial Rd.
Blackwood, NJ 08012

Work Requested

INSTALL 2 DUCTLESS SPLIT SYSTEMS

CUSTOMER ORDERED MATERIALS.

Unit #:

Make:

Description:

Serial#:

Work Performed:

Nurse office unit set and piped. Evacuated and leak checked. opened refrigerant lines. Awaiting electrical for power source. Set indoor unit for guidance office. Awaiting outdoor unit to run line set. Retrieved materials from supply house to finish nurse office and set guidance office unit.

Recommendations

Summary

Materials

PO 10427 Johnstone supply, installation materials.

Labor

Technician

David Birkey

Hours

Reg Labor

8.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:

Master HVAC/R Contractor: Renee Fiorelli



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 43875

Work Order #: 43874

Service Date: 10/08/2019

Ticket Type: Serv T&M

Category: HVAC T&M Service

Job#: 1141

Caller: Sani Umar

Location

CHARLES
Charles W. Lewis Middle School

Customer

Gloucester Twp. Public Schools
17 Erial Rd.
Blackwood, NJ 08012

Work Requested

INSTALL 2 DUCTLESS SPLIT SYSTEMS

CUSTOMER ORDERED MATERIALS.

Unit #:

Make:

Description:

Serial#:

Work Performed:

Set condenser on hanging mount due to unsettled ground. ran line set. Received disconnect. Will hook up electrical when electrician runs power cables. Will return to leak test and evacuate.

Recommendations

Summary

Materials

PO 10417 United refrigeration for disconnect box.

Labor

Technician

David Birkey

Hours

Reg Labor	O/T Labor	Prem
8.00	0.00	0.00

Customer Signature

Printed Name:

Master HVAC/R Contractor: Renee Fiorelli



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 43874

Work Order #: 43874

Service Date: 10/07/2019

Ticket Type: Serv T&M

Category: HVAC T&M Service

Job#: 1141

Caller: Sani Umar

Location

CHARLES
Charles W. Lewis Middle School

Customer

Gloucester Twp. Public Schools
17 Erial Rd.
Blackwood, NJ 08012

Work Requested

INSTALL 2 DUCTLESS SPLIT SYSTEMS

CUSTOMER ORDERED MATERIALS.

Unit #:

Description:

Make:

Serial#:

Work Performed:

located area in nurses office for install. removed old through wall unit and facilities carpenter patched hole. set indoor bracket and evap head. retrieved from supply house, condenser bracket to place on exterior wall due unsettled ground outdoors. will return to set condenser and run line set.

Recommendations

Summary

Materials

PO 10411 Johnstone supply for condenser bracket.

Labor

Technician

David Birkey

Hours

Reg Labor

7.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:

Master HVAC/R Contractor: Renee Fiorelli



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 43796	
Work Order #	43796
Service Date	09/30/2019
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	793
Caller	Contract

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Drain Dual Temp System

Unit #:	Description:
Make:	Serial#:
Work Performed: Isolated building to drain loop. Turned off both Chillers. Piped in drain valves onto both air separators. Drained building for Mechanical Contractors. Once their work was complete, filled system back up and opened all valves. Restored power to both Chillers. The old Trane Chiller is going out on low pressure. Found oil residue in condenser section indicating a possible leak. Dave Schilling will be returning to troubleshoot Trane Chiller.	

Recommendations

Summary					
Materials					
None					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	6.00	O/T Labor	4.50	Prem 0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 43787	
Work Order #	43759
Service Date	10/02/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1840
Caller	Sani Umar

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

chiller is down

Unit #:	Description:
Make:	Serial#:
Work Performed: Picked up flow switch locally, drained and isolated system, replaced switch, filled and bled system, ran chiller and checked operation. Chiller has no load on it so it short cycles. During the runtime it did operate properly.	

Recommendations

Summary

Materials

10372

Labor

Technician	Hours			
	Reg Labor	O/T Labor	Prem	
David Schilling	8.00	0.00	0.00	0.00

Customer Signature

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 43759	
Work Order #	43759
Service Date	10/01/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1840
Caller	Sani Umar

Location	Customer
LORING-F Loring-Flemming School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
chiller is down

Unit #:	Description:
Make:	Serial#:
Work Performed: Found a leak on the condenser header. Recovered chiller, recovered 3 lbs of r22, repaired leak, pressure tested, and evacuated to 600 microns and held for one hour. Charged chiller with 60 lbs of r22, ran chiller, and found flow switch not operating properly. Will return to repair. # New Refrigerant Added: Leak Test Recovery Set Up Refrigerant Type: Torch Set Up Vacuum Set Up	

Recommendations

Summary						
Materials						
10372 po for united						
Labor						
Technician	Hours					
David Schilling	Reg Labor	8.00	O/T Labor	0.00	Prem	0.00
Customer Signature						
Printed Name:						



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #: 43699	
Work Order #	43699
Service Date	09/30/2019
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	682
Caller	Sani Umar

Location	Customer
CHEWS EL Chews Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Pipe in hot water coil in Main Office.

Unit #:	Description:
Make:	Serial#:
Work Performed: Began disconnecting unit to access hot water coil and make material list. Picked up material from Ferguson. Unable to begin work as there was an emergency at Loring Fleming.	

Recommendations

Summary					
Materials					
PO 10358					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	2.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #: 43657

Work Order #: 43623

Service Date: 09/27/2019

Ticket Type: Ctl's T&M

Category: ATC T&M Service

Job#: 1923

Caller: Sani Umar

Location

ANN MULL2

Ann A.Mullen Middle School

Customer

Gloucester Twp. Public Schools

17 Erial Rd.

Blackwood, NJ 08012

Work Requested

PROGRAMMING

Unit #:

Description:

Make:

Serial#:

Work Performed:

Added VykonPro module to server and started the VykonPro service on the station. Added GlobalNumericWritable point to allow for batch releasing of overrides in system. Globally released overrides on unoccupied cooling setpoints in the Ann Mullen 800 wing.

Recommendations

Summary

Materials

Labor

Technician

Hours

Stephen Suboleski

Reg Labor

0.50

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #: 43623

Work Order # 43623

Service Date 09/27/2019

Ticket Type Ctl's T&M

Category ATC T&M Service

Job# 821

Caller Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

RTU-1 tripping high pressure circuit.

Unit #:	Description:
Make:	Serial#:
Work Performed: -RTU1 Circuit #2 is tripping on high pressure, as it has been all summer. Suspect that as the unit going into dehumidification mode, one of the stepper valves is malfunctioning. Put system in test mode and ran both compressors in circuit #2. Placed reheat valve in 100% command and tested stepper valve operation with temperature difference across the valve. There was no temperature difference across the valve in full open position indicating that the valve is operating as it should. Monitored the operation but circuit did not trip. Suspect the stepper valve is getting stuck intermittently. Called Daikin Applied Tech Support and am waiting for a return call. Until a return call is received, system was put back in auto mode. -Inspected FCU for room 833. Found belt is beginning to break and must be replaced. Pulleys are bad and must be replaced. Until the pulleys are replaced, picked replacement belts and installed. -Released Unoccupied Cooling Setpoint override on all FCU's in the 800 wing. FCU's should now set back at night and thus go into 100% cooling mode in the morning when the building becomes occupied again.	

Recommendations

Summary

Materials

PO 10354

Labor

Technician	Hours			
	Reg Labor	O/T Labor	Prem	
David Dougherty	8.00	0.00		0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	43353
Work Order #	43230
Service Date	09/20/2019
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	738
Caller	Contract

Location	Customer
CHARLES Charles W. Lewis Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Follow up on Ticket #43230 Investigate High Humidity in Rm 307

Unit #:	Description:
Make:	Serial#:
Work Performed: Connected to RTU UNT controller and uploaded program. Found the space temp sensor in the office with the electric heater was the primary space temp sensor for the RTU that controlled the heat and AC. The space temp sensor in the main area controlled a radiation control valve above the ceiling. The third space temp sensor was set to control a valve that is not physically installed. Removed the small office space temp sensor from the RTU. I made the main area space temp sensor the primary space temp sensor that the RTU is referencing. This will now control the operation of the RTU much better and keep a more uniform temperature in the space. The third space temp sensor is now controlling the radiation valve. Must return at a later date once the boilers are on to confirm flow through the baseboard.	

Recommendations

Summary					
Materials					
None					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	4.50	O/T Labor	0.00	Prem
0.00					
Customer Signature					
Printed Name:					



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	43230
Work Order #	43230
Service Date	09/18/2019
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	738
Caller	Contract

Location	Customer
CHARLES Charles W. Lewis Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Investigate High Humidity in Rm 307

Unit #:	Description:
Make:	Serial#:
Work Performed: Investigated high humidity issues as well as inconsistent temperatures. Found there is an electric heater in one of the offices that was making the RTU think it was too hot in the space and run in Cooling all day. Must return to disconnect sensor in the space.	

Recommendations

Summary

Materials

None

Labor

Technician	Hours			
	Reg Labor	O/T Labor	Prem	
David Dougherty	2.50	0.00	0.00	

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 42950	
Work Order #	42763
Service Date	09/20/2019
Ticket Type	Ctl's T&M
Category	ATC Quote
Job#	682
Caller	Contract

Location	Customer
CHEWS EL Chews Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Follow up on Ticket #42763 Troubleshoot Water Heater

Unit #:	Description:
Make:	Serial#:
Work Performed: Replaced damper actuator and verified operation of Water Heater	

Recommendations

Summary

Materials

Cash PO on previous ticket

Labor

Technician	Hours			
	Reg Labor	O/T Labor	Prem	
David Dougherty	3.00	0.00	0.00	

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #: 42972	
Work Order #	42972
Service Date	09/13/2019
Ticket Type	Ctls T&M
Category	ATC T&M Service
Job#	821
Caller	Contract

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Modify equipment schedule and setpoints

Unit #:

Description:

Make:

Serial#:

Work Performed:

Modified equipment schedules and setpoints for both Mullen and Union Valley. After modifying setpoints for G wing and RTU's, found all of the setpoints and occupied modes were overridden. Traced back and found Greg from Multi-Temp changed them. Walked through building and checked humidity readings. Ordered replacement damper for Chews Water Heater

Recommendations

Summary

Materials

None

Labor

Technician

Hours

David Dougherty

Reg Labor

5.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #:	42968
Work Order #	42968
Service Date	09/13/2019
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	738
Caller	Contract

Location	Customer
CHARLES Charles W. Lewis Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Ductless split system in Rm 219 is making a loud noise

Unit #:	Description:
Make:	Serial#:
Work Performed: Ductless Split System in classroom 219 is making a loud noise coming from the blower wheel. Disassembled evaporator head and found the plastic internal components on the blower wheel have ground down to nothing, not allowing the blower shaft to have a surface to catch onto. Blower wheel would have to be replaced which is not cost effective. Recommend replacing entire ductless split system considering the condition of both the indoor and outdoor units.	

Recommendations

Summary

Materials

None

Labor

Technician

David Dougherty

Hours

Reg Labor

3.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	42860
Work Order #	42860
Service Date	09/11/2019
Ticket Type	Ctls T&M
Category	ATC T&M Service
Job#	1923
Caller	Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
PROGRAMMING

Unit #:	Description:
Make:	Serial#:
Work Performed: Humidity issues in the 800 wing were reported. Added logic to turn off HRUs when OA enthalpy rises above 30 BTU/lb (adjustable).	

Recommendations

Summary						
Materials						
Labor						
Technician	Hours					
Stephen Suboleski	Reg Labor	1.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #:	42766
Work Order #	42766
Service Date	09/09/2019
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	738
Caller	Contract

Location	Customer
CHARLES Charles W. Lewis Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

N30 is offline

Unit #:	Description:
Make:	Serial#:
Work Performed: -N30 is offline. Traced out and found Comcast Modem port forwarding was disabled in the Modem configuration. Enabled port forwarding and pinged N30 from server. Graphics are back online -Booster Pump is making a loud grinding noise. Upon disassembling pump, found there is an issue with the pump, not the motor. Either the pump bearings are bad or there is an issue with the impeller. Recommend replacing entire pump assembly as well as relocating pump so it is not right up against the electrical panels in the event there is a water leak.	

Recommendations

Summary

Materials

None

Labor

Technician	Hours			
	Reg Labor	O/T Labor	Prem	0.00
David Dougherty	3.00	0.00	0.00	0.00

Customer Signature

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	42763
Work Order #	42763
Service Date	09/09/2019
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	682
Caller	Sani Umar

Location	Customer
CHEWS EL Chews Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Troubleshoot Water Heater

Unit #:	Description:
Make:	Serial#:
Work Performed: Upon troubleshooting found ignition control module was wired incorrectly. Switched wiring to correct configuration. Unit still did not fire up. Traced out and found control actuator end switch is bad. Damper actuator must be replaced.	

Recommendations

Summary

Materials

Cash Purchase submitted for reimbursement. PO 10201

Labor

Technician	Hours			
David Dougherty	Reg Labor	3.00	O/T Labor	0.00
			Prem	0.00

Customer Signature

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 42587	
Work Order #	42587
Service Date	09/05/2019
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	639
Caller	Contract

Location	Customer
UNION VA Union Valley Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Chiller is down

Unit #:	Description:
Make:	Serial#:
Work Performed: Chiller is down. Reset Chiller alarms. Chiller started up and ran. Verified operation. Screwed Chiller control door shut so no moisture can get inside electrical section.	

Recommendations

Summary

Materials

None

Labor

Technician	Hours				
	Reg Labor	O/T Labor	Prem		
David Dougherty	2.00	0.00	0.00		

Customer Signature

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 42538	
Work Order #	42538
Service Date	09/05/2019
Ticket Type	CtIs T&M
Category	ATC T&M Service
Job#	682
Caller	Sani Umar

Location	Customer
CHEWS EL Chews Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Repair flue vent for water heater.

Unit #:	Description:
Make:	Serial#:
Work Performed: Water heater has flue pipe broken off. Flue pipe was installed incorrectly from the beginning and must be corrected. Installed new flue pipe for both water heaters. Opened up all valves and fired up water heater on the left. The water heater on the right is not firing. Water heater must be troubleshot	

Recommendations

Summary

Materials

PO 10111

Labor

Technician	Hours				
	Reg Labor	O/T Labor	Prem		
David Dougherty	5.00	0.00	0.00		0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 41929	
Work Order #	41754
Service Date	08/22/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	722
Caller	Sani Umar

Location	Customer
UNION VA Union Valley Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Follow up on Ticket #41765 chiller down

Unit #: Chiller
Make: Trane

Description: Chiller
Serial#:

Work Performed:

Shut down Chiller and tested power to ensure safe working conditions. Isolated compressor for circuit B. Removed faulty oil pressure differential switch. Blew out oil lines with compressed nitrogen to ensure no blockage of debris they may cause nuisance trips of new Switch installed new oil differential switch. Open shut off valves to open compressor to refrigerant circuit. Returned system to normal operating conditions. Restore power, ran system, and checked operating pressures and system operating conditions.

Recommendations

Summary

Materials

00

Labor

Technician

Hours

Shaun Bliss

Reg Labor

4.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	41765
Work Order #	41754
Service Date	08/20/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	722
Caller	Sani Umar

Location	Customer
UNION VA Union Valley Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Chiller down

Unit #: Chiller	Description: Chiller
Make: Trane	Serial#: -
Work Performed: Returned to continue diagnosis of Trane air cooled chiller. upon arrival circuit be tripped on chilled water interlocked and oil flow alarm. Circuit a running and maintaining building near set point. Alarm history shows buffets in balance and overload a compressor circuit a as well as high-pressure cutout circuit a also oil flow alarm phase imbalance chilled water in interlock 4 compressor B. I believe the phase unbalanced is an old alarm and I recorded all alarm history and reset both circuit alarm histories as well as Diagnostics so that future alarms and trips will be noted with a date. Further inspection found building controls master schedule set to numerous occupied and unoccupied settings. Throughout the day, the chiller was overrode enabled so that would run continuous but chilled water pumps remained operated by building Master schedule. This is a conflict because while on occupied the chill water pumps would stop running and calls chiller to have nuisance trips and alarms. This is do to running conditions with no water flow. Found chilled water pump one enabled on so that would run continuous to prevent this condition. Inspection of vfd for pump found the vfd in off position reset vfd to Auto position and pump began to run. This should eliminate nuisance trips during unoccupied schedules. Need to return to replace	

Recommendations

Summary					
Materials					
00					
Labor					
Technician	Hours				
Shaun Bliss	Reg Labor	4.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 41765	
Work Order #	41754
Service Date	08/20/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	722
Caller	Sani Umar

Location	Customer
UNION VA Union Valley Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Unit #: Chiller
Make: Trane

Description: Chiller
Serial#:

differential pressure switch for oil flow circuit B.

Recommendations

Summary

Materials

Labor

Technician

Hours

Reg Labor

O/T Labor

Prem

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	40096
Work Order #	40081
Service Date	07/24/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	722
Caller	Sani Umar

Location	Customer
UNION VA Union Valley Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Follow up on Ticket #40081 CHECK CHILLER. SOME ELECTRICAL PROBLEMS FROM STORM.

PO 9666 FOR UNITED.

Unit #:	Description:
Make:	Serial#:
Work Performed: Replaced circuit 2 condenser, saturation refrigerant sensor, evacuated high side, pressure tested new sensor, evacuated and charged high back up, tested operation, Chiller is online and operating properly at this time.	

Recommendations

Summary

Materials

temp sensor

Labor

Technician

Hours

David Schilling

Reg Labor

8.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 39863	
Work Order #	39786
Service Date	07/15/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1336
Caller	Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Follow up on Ticket #39786 COOLING TOWER OVER FLOWING

Unit #:

Description:

Make:

Serial#:

Work Performed:

Retrieved new colling tower fill valve locally. Replaced valve and adusted float to correct water level. Chiller and coolling tower is back in operation and operating properly.

Recommendations

Summary

Materials

1 new fill valve

Labor

Technician	Hours			
	Reg Labor	O/T Labor	Prem	
David Schilling	4.00	0.00	0.00	

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	39786
Work Order #	39786
Service Date	07/12/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1336
Caller	Sani Umar

Location	Customer
ANN MULL2 Ann A.Mullen Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

COOLING TOWER OVER FLOWING

Unit #:	Description:
Make:	Serial#:
Work Performed: found cooling tower water was overflowing out of the overflow reservoir, attempted to adjust the float but it is so rusty and may snap off from any type of adjustments, I ordered a new float valve and float rod, will return when parts are in to replace.	

Recommendations

Summary					
Materials					
none					
Labor					
Technician	Hours				
David Schilling	Reg Labor	3.00	O/T Labor	0.00	Prem 0.00

Customer Signature
Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 39754	
Work Order #	39754
Service Date	07/10/2019
Ticket Type	Ctls T&M
Category	ATC T&M Service
Job#	804
Caller	Contract

Location	Customer
GLENDORA Glendora Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Main office has no A/C

Unit #:	Description:
Make:	Serial#:
Work Performed: Troubleshoot main office for no cooling. Pneumatic system is down and needs a new motor for air compressor. Tracked down motor and GTPS ordered. Until motor can be replaced. Traced out wiring from condenser to AHU and rewired so room thermostat will control the condenser directly. Tested and verified operation.	

Recommendations

Summary					
Materials					
None					
Labor					
Technician	Hours				
David Dougherty	Reg Labor	4.00	O/T Labor	0.00	Prem
					0.00
Customer Signature					
Printed Name:					



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 39753	
Work Order #	39753
Service Date	07/10/2019
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	1901
Caller	Contract

Location	Customer
UNION VA Union Valley Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
Rm 401 is overheating

Unit #:	Description:
Make:	Serial#:
Work Performed: Rm 401 is overheating. Found HW valve is being commanded open 100%. Controller shows it's online but it is actually bad and offline. Controller is switched on the graphics with room 400. Controller must be replaced. Replaced controller with PCG controller. Replaced space sensor and calibrated. Downloaded new program and commissioned. Verified operation.	

Recommendations

Summary						
Materials						
Customer Stock						
Labor						
Technician	Hours					
David Dougherty	Reg Labor	4.00	O/T Labor	0.00	Prem	0.00

Customer Signature
Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	39508
Work Order #	39508
Service Date	07/03/2019
Ticket Type	Ctls T&M
Category	ATC T&M Service
Job#	750
Caller	Contract

Location	Customer
GLENLAND Glen Landing Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Bind Sensor on Chiller

Unit #:	Description:
Make:	Serial#:
Work Performed: Worked with Dave Schilling to bind sensor on Chiller. Unable to complete the binding as the controller is corrupt and needs to be replaced first.	

Recommendations

Summary

Materials

None

Labor

Technician	Hours				
	Reg Labor	O/T Labor	Prem		
David Dougherty	3.00	0.00	0.00		

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 39456	
Work Order #	39039
Service Date	07/03/2019
Ticket Type	CtIs T&M
Category	ATC T&M Service
Job#	575
Caller	Sani Umar

Location	Customer
GLOUCEST3 Gloucester Township Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Follow up on Ticket #39167
Follow up on Ticket #39166
Follow up on Ticket #39039

Unit #:	Description:
Make:	Serial#:
Work Performed: Completed installation of Ductless	

Recommendations

Summary

Materials

PO 9468

Labor

Technician	Hours				
	Reg Labor	O/T Labor	Prem		
David Dougherty	5.00	0.00	0.00		

Customer Signature

Printed Name:



Peterson
Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #: 39421	
Work Order #	37510
Service Date	07/09/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1578
Caller	Sani Umar

Location	Customer
GLENLAND Glen Landing Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Follow up on Ticket #37510 Ticket created from Quote #2243 -- Need to return to replace faulty evaporator water temp sensor for Chiller number to leaving water temperature sensor. and to determine if any further issues exist with building automation enabling chilled water pumps from Ticket#37336

Unit #: CHILLER2

Description: CHILLER2

Make:

Serial#:

Work Performed:

replaced and programmed chilled water leaving temp sensor, started chiller and tested operation, online and operating properly maintaining chilled water set point.

Recommendations

Summary

Materials

1 temp sensor

Labor

Technician	Hours			
	Reg Labor	O/T Labor	Prem	
David Schilling	3.00	0.00		0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	39408
Work Order #	39362
Service Date	07/05/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1578
Caller	Sani Umar

Location	Customer
GLENLAND Glen Landing Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Follow up on Ticket #39362 CHILLER 2- CHILLED WATER PUMP NEEDS A NEW LOVEJOY COUPLING.

Unit #: CHILLER2

Description: CHILLER2

Make:

Serial#:

Work Performed:

cleaned couplings, replaced coupling insert, aligned coupling, tested operation, ok at this time

Recommendations

Summary

Materials

1 coupling insert; 9472

Labor

Technician

Hours

David Schilling

Reg Labor

2.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70

Medford, NJ 08055

Tel: (609) 714-3699 Fax: (609) 714-3698

Email: service@petersonservice.com

Service Ticket #: 39381

Work Order #: 39363

Service Date: 07/05/2019

Ticket Type: Serv T&M

Category: HVAC T&M Service

Job#: 1578

Caller: Sani Umar

Location

GLENLAND
Glen Landing Middle School

Customer

Gloucester Twp. Public Schools
17 Erial Rd.
Blackwood, NJ 08012

Work Requested

CHILLER 2- NEEDS A NEW DISPLAY SCREEN, PICK UP SCREEN FROM TOZOUR TRANE.

PO FOR TRANE IS 9473

Unit #: CHILLER2

Description: CHILLER2

Make:

Serial#:

Work Performed:

picked up display module locally, installed and programmed new module, will need to return to start up chiller.

Recommendations

Summary

Materials

display module

Labor

Technician

David Schilling

Hours

Reg Labor

4.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	39380
Work Order #	39372
Service Date	07/05/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	722
Caller	Sani Umar

Location	Customer
UNION VA Union Valley Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

CHILLER 1- NOT ABLE TO NAVIGATE THROUGH THE DISPLAY

Unit #: Chiller

Description: Chiller

Make: Trane

Serial#:

Work Performed:

picked up new display module locally, install and programmed module, ran chiller and tested operation, ok at this time.

Recommendations

Summary

Materials

display module - 9476

Labor

Technician

Hours

David Schilling

Reg Labor

4.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	39363
Work Order #	39363
Service Date	07/03/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1578
Caller	Sani Umar

Location	Customer
GLENLAND Glen Landing Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested
CHILLER 2- NEEDS A NEW DISPLAY SCREEN, PICK UP SCREEN FROM TOZOUR TRANE.

Unit #: CHILLER2	Description: CHILLER2
Make:	Serial#:
Work Performed: arived on site to change the leaving chilled water sensor and found display was blank, unable to connect lap top to bind new sensor, will need to Replace display screen first	

Recommendations

Summary					
Materials					
none					
Labor					
Technician	Hours				
David Schilling	Reg Labor	2.00	O/T Labor	0.00	Prem
					0.00

Customer Signature
Printed Name:
Master HVAC/R Contractor: Renee Fiorelli



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	39363
Work Order #	39363
Service Date	07/03/2019
Ticket Type	Serv T&M
Category	HVAC T&M Service
Job#	1578
Caller	Sani Umar

Location	Customer
GLENLAND Glen Landing Middle School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

CHILLER 2- NEEDS A NEW DISPLAY SCREEN, PICK UP SCREEN FROM TOZOUR TRANE.

Unit #: CHILLER2

Description: CHILLER2

Make:

Serial#:

Work Performed:

arived on site to change the leaving chilled water sensor and found display was blank, unable to connect lap top to bind new sensor, will need to Replace display screen first

Recommendations

Summary

Materials

none

Labor

Technician

Hours

David Schilling

Reg Labor

2.00

O/T Labor

0.00

Prem

0.00

Customer Signature

Printed Name:



Peterson Service Company

234 Route 70
Medford, NJ 08055
Tel: (609) 714-3699 Fax: (609) 714-3698
Email: service@petersonservice.com

Service Ticket #:	39167
Work Order #	39039
Service Date	07/01/2019
Ticket Type	Ctl's T&M
Category	ATC T&M Service
Job#	575
Caller	Sani Umar

Location	Customer
GLOUCEST3 Gloucester Township Elementary School	Gloucester Twp. Public Schools 17 Erial Rd. Blackwood, NJ 08012

Work Requested

Follow up on Ticket #39166
Follow up on Ticket #39039
Install ductless split system

Unit #:	Description:
Make:	Serial#:
Work Performed: Continued installing ductless split system	

Recommendations

Summary

Materials

PO# 9468, 9477

Labor

Technician	Hours			
	Reg Labor	O/T Labor	Prem	
David Dougherty	6.00	0.00	0.00	0.00

Customer Signature

Printed Name: