

[illegible]

**New Jersey Police
Crash Investigation Report**

Police Dept: **TOMS RIVER TWP** Code: **01**
 Station: **DISTRICT ONE** Case No: **20-41543**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Dept	Hosp Code	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	-	-	-	-			-	-	-	-	-	-	-	- -
L	-	-	-	-			-	-	-	-	-	-	-	- -
E	-	-	-	-			-	-	-	-	-	-	-	- -
I	-	-	-	-			-	-	-	-	-	-	-	- -
N	-	-	-	-			-	-	-	-	-	-	-	- -
V	-	-	-	-			-	-	-	-	-	-	-	- -
O	-	-	-	-			-	-	-	-	-	-	-	- -
L	-	-	-	-			-	-	-	-	-	-	-	- -
V	-	-	-	-			-	-	-	-	-	-	-	- -
E	-	-	-	-			-	-	-	-	-	-	-	- -
D	-	-	-	-			-	-	-	-	-	-	-	- -
J	-	-	-	-			-	-	-	-	-	-	-	- -

144 Crash Diagram (NOT TO SCALE)

***** SEE DIAGRAM PAGE *****

145 Crash Description/Narrative

Driver #1 indicated she was traveling south on Alden Dr and observed another uninvolved vehicle coming from the opposite direction. She perceived the vehicle as a hazard as it appeared to be to the west of the center line. She slowed and steered to the right to void this perceived hazard. In doing so, her vehicle's passenger side mirror contacted the mailbox at 940 Alden Rd.

Veh #1 sustained minor damage to the passenger side mirror. No injuries were reported at the scene.

146 Officer's Signature

BARTOSHEK, D.

147 Badge #

0316

148 Reviewer

SSE

Badge #

318


149 Case Status

☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: TOMS RIVER TWP Code: 01
Station: DISTRICT ONE Case No: 20-41543

144 Crash Diagram (NOT TO SCALE)



Not To Scale

BARTOSHEK, D.

Officer's Signature

0316

Badge Number