

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2021-00002654			Page <u>2</u> of <u>4</u>	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was traveling westbound on Rt. 88, approaching the intersection with Fort Street, directly behind

Vehicle 2. Vehicle 2 was traveling westbound on Rt. 88 coming to a stop in traffic. As Vehicle 2 slowed to a stop

the front of Vehicle 1 collided with the rear of Vehicle 2.

Driver 1 stated she was traveling westbound on Rt. 88, directly behind Vehicle 2. Driver 1 explained she saw

Vehicle 2 stopping, but when she pressed on the brakes, Vehicle 1 "stayed in gear" . Driver 1 advised she was

unable to stop and there were cars in oncoming traffic and cars turning right in the shoulder. She was unable to

avoid Vehicle 2. Subsequently, the front of Vehicle 1 collided with the rear of Vehicle 2. Driver 1 explained

that she had taken Vehicle 1 in for maintenance for the mechanical issue approximately 8 months ago.

Driver 2 stated she was traveling westbound on Rt. 88 and was stopping to make a left turn. Driver 2 explained as

she slowed to a stop the front of Vehicle 1 collided with the rear of Vehicle 2. Driver 2 was transported to

Ocean Medical Center, by EMS, for chest pain.

Based on my observations and the statements made by all parties involved, I determined that Driver 1 was at fault

146. Officer's Signature Kyle Dudak	147. Badge # 0313	148. Reviewer Jason R Shepherd	Badge # 167	149. Case Status ☐ Pending ☒ Complete
--	----------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00002654

145 Crash Description

for this collision. Vehicle 1 was following too closely and when Vehicle 2 came to a stop it did not have enough time to come to a safe stop behind it. According to the statements made by driver 1, mechanical issues on Vehicle 1 may have also contributed to this accident.

Driver 1 was issued one (1) summons: #E21000218 for 39:4-97 (Careless Driving)

Body worn camera activated.

Kyle Dudak

Officer's Signature

0313

Badge Number


New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00002654

144 Crash Diagram (NOT TO SCALE)

○ Indicate North

Not to Scale



Fort St.

Rt. 88



Access road to 1608 Rt. 88