

Edison Department of Public Works

Incident Report

☐ DIA TESTING
☐ COPY TO HR ☐ COPY TO DPW
☐ FAXED TO QUAL-LYNX
MVA-609-926-9270 Injury 732-562-2815

THIS FORM MUST BE FILLED OUT AND SUBMITTED TO THE HUMAN RESOURCES OFFICE WITHIN 24 HOURS OF ANY INCIDENT UNLESS OCCURRING ON WEEKEND OVERTIME HOURS

DIVISION: Sewers

Date of Report: MAY 22, 2020

Date of Incident: MAY 22, 2020 Time of Incident: 10:04 AM

Weather Condition: Sunny, bright.

Vehicle #: S-5 Vehicle / Equipment Category: Diesel Truck

Driver and Employees Involved: Joseph Alorso

Supervisor(s) of Driver and Employees Involved: Nick Vatarino

How Person completing this Report received notice of damage/incident: I was present in the vehicle during the incident when it occurred.

Damage Observed: Right top of windshield has a crack, part of door bent

Incident Description: S-5 Traveling down New Brunswick Ave as behind a Solterra recycle truck cardboard flew off back on & rack right top of windshield and damage to windshield & part of right door.

Location of Incident: New Brunswick Ave

Was anyone in need of medical attention: Yes ☐ No ☒ Was HR notified? Yes ☒ No ☐

Where any other vehicles / equipment involved: NO

NOTIFIED POLICE: Yes ☒ No ☐

Signature of Person completing this Report: Joseph Alorso

**New Jersey Police
Crash Investigation Report**

Police Dept: **EDISON POLICE DEPAR** Code: **01**Station: **-** Case No: **20025377**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Dept	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A L L I N V O L V E D J	83	84	85	86	87	88	89	90	91	92	93	94	95	

144 Crash Diagram (NOT TO SCALE)

Vehicle moved prior to arrival.

145 Crash Description/Narrative

V1 and V2 were both traveling on Brunswick Ave. when V1 had a piece of debris (cardboard) fall from the rear of the vehicle striking and cracking the windshield of V2. V1 did not stop. D2 advised me that V1 was a garbage truck owned by "Solterra", a recycling company. Unable to make contact with the company.

Due to V2 being a township vehicle, BCI responded and took photographs of the damage.

146 Officer's Signature

CHRISTIAN PAONE

147 Badge #

0480

148 Reviewer

DECHIRICO

Badge #

0199

149 Case Status

☐ Pending☒ Complete