

Edison Department of Public Works

Incident Report

[] D/A TESTING
[] COPY TO HR [] COPY TO DPW
[] FAXED TO QUAL-LYNX
MVA-609-926-9270 Injury 732-562-2815

THIS FORM MUST BE FILLED OUT AND SUBMITTED TO THE HUMAN RESOURCES
OFFICE WITHIN 24 HOURS OF ANY INCIDENT UNLESS OCCURRING ON WEEKEND
OVERTIME HOURS

DIVISION: SANITATION

Date of Report: 04-24-2020

Date of Incident: 04-24-2020 Time of Incident: 8:30 AM

Weather Condition: RAINY

Vehicle #: ER-10 Vehicle / Equipment Category: PACKER

Driver and Employees Involved: CHRISTOPHER RIGGI

Supervisor(s) of Driver and Employees Involved: JERMAINE OVERTON THOMAS
YOUNKER

How Person completing this Report received notice of damage/incident: CALLED TOM YOUNKER

Damage Observed: PASSENGER SIDE BUMPER

Incident Description: BACKED UP TO STOP AND BUMPER
CAUGHT THE FENCE.

Location of Incident: TOWNHALL

Was anyone in need of medical attention: Yes ☐ No ☒ Was HR notified? Yes ☒ No ☐

Where any other vehicles / equipment involved: NO

NOTIFIED POLICE: Yes ☒ No ☐ INCIDENT # 20021141

Signature of Person completing this Report: Tom Younker 04-24-2020

PAGE 1 OF 2		New Jersey Police Crash Investigation Report		☒ Reportable ☐ Non-Reportable ☐ Change Report	
05	1 Case Number		10 Crash Occurred On: 100 MUNICIPAL BLVD		11 Speed Limit
97	20021141				
01	2 Police Dept of		Road Name		12 Route No.
98	EDISON POLICE DEPART 01				13 Milepost
01	3 Station/Precinct		14 At Intersection With		18 Speed Limit
99			15 Feet		
07	4 Date of Crash		6 Time (use 2400 hrs)		7 Municipality Code
100a	04/24/20		0819		1205
01	5 Day Of Week		8 Total Killed		9 Total Injured
100b	FRIDAY				
04	23 Veh #		24 Policy No.		25 NJ Ins. Code
101	1		SELF INSURED		
02	☐ Parked ☐ Ped ☐ Pedalcyclist		☐ Resp To Emergency		☐ Hit & Run
102	26 Driver's First Name		29 Sex		56 Driver's First Name
02	CHRISTOPHER		M		
103	27 Number & Street		57 Number & Street		
02					
104	28 City		58 City		
1					
105	30 Eyes		31 State		60 Eyes
11	02		NJ		
106	32 Driver's License Number		33 DOB		62 Driver's License Number
-					
107	35 Owner's First Name		65 Owner's First Name		
-	EDISON TWSHP				
108	36 Number & Street		66 Number & Street		
21	100 MUNICIPAL BLVD				
109	37 City		67 City		
-	EDISON				
110	38 Make		68 Make		
03	FREIGHTLINE				
111	39 Model		69 Model		
-	TR				
112	40 Color		70 Color		
01	WT				
113	41 Year		71 Year		
-	2018				
114	42 Plate No.		72 Plate No.		
09	26467MG				
115	43 State		73 State		
-	NJ				
116	44 VIN		74 VIN		
03	1FVHG3DV9JHJL2834				
117	45 Expires		75 Expires		
-	08 20				
118	46 Vehicle Removed To		76 Vehicle Removed To		
01	☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded		☐ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded		
119	☐ Left At Scene ☐ Towed Impounded		☐ Left At Scene ☐ Towed Impounded		
120	47 Authority		77 Authority		
-	☐ Owner ☒ Driver ☐ Police		☐ Owner ☐ Driver ☐ Police		
121	48 Alcohol/Drug Test		78 Alcohol/Drug Test		
09	Given: ☒ No ☐ Yes ☐ Refused		Given: ☐ No ☐ Yes ☐ Refused		
122	Type: ☐ Breath ☐ Blood ☐ Urine		Type: ☐ Breath ☐ Blood ☐ Urine		
123	Results: 0. - % ☐ Pending		Results: 0. - % ☐ Pending		
124	49 Hazardous Material		79 Hazardous Material		
03	☒ None ☐ On Board ☐ Spill		☐ None ☐ On Board ☐ Spill		
125	Hazard Class		Hazard Class		
126	Placard No.		Placard No.		
127	50 Carrier No.		80 Carrier No.		
128	☐ USDOT ☐ None		☐ USDOT ☐ None		
129	☐ MC/MX		☐ MC/MX		
130	51 GVWR/GCWR		81 GVWR/GCWR		
131	☐ Weight <= 10,000 lbs		☐ Weight <= 10,000 lbs		
132	☐ Weight 10,001-26,000 lbs		☐ Weight 10,001-26,000 lbs		
133	☒ Weight >= 26,001 lbs		☐ Weight >= 26,001 lbs		
134	52 Motor Carrier or Government Entity		82 Motor Carrier or Government Entity		
135	Number & Street		Number & Street		
136	City		City		
137	State		State		
138	Zip		Zip		
139	135 Damage To Other Property		☒ Yes (If Yes, describe) ☐ No		
140	FENCE / GATE LEADING TO POLICE PARKING				
141	Oper. 136 Charge		Oper. 138 Charge		
142	137 Summons. No.		139 Summons. No.		
143	Oper. 140 Charge		Oper. 142 Charge		
144	141 Summons. No.		143 Summons. No.		
145					
146	83		Names & Addresses of Occupants - If Deceased, Date & Time of Death		
147	84		DRIVER 1		
148	85				
149	86				
150	87				
151	88				
152	89				
153	90				
154	91				
155	92				
156	93				
157	94				
158	95				
159					
160					
161					


New Jersey Police Crash Investigation Report

Police Dept: **EDISON POLICE DEPAR** Code: **01**Station: - Case No: **20021141**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Dept	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
L														
E														
I														
N														
V														
O														
L														
V														
E														
D														
J														

144 Crash Diagram (NOT TO SCALE)



Unit 1

145 Crash Description/Narrative

V1 (Edison Township Garbage truck ER-10) was backing out of the police vehicle parking lot when the front bumper caught the fence. The latch to the fence was bent, the sensor to open / close the fence was broken off and the front bumper of V1 was bent outward.

146 Officer's Signature

ALAN ESPOSITO

147 Badge #

0442

148 Reviewer

JACKSON

Badge #

0379

149 Case Status

☐ Pending ☒ Complete