

Edison Department of Public Works

Incident Report

THIS FORM MUST BE FILLED OUT AND SUBMITTED TO THE HUMAN RESOURCES
OFFICE WITHIN 24 HOURS OF ANY INCIDENT UNLESS OCCURRING ON WEEKEND
OVERTIME HOURS

DIVISION: Sanitations Date of Report: 1/24/20

Date of Incident: 1/22/20 Time of Incident: 8:40 AM

Weather Condition: Sunny

Vehicle #: G-8 Vehicle / Equipment Category: Garbage truck

Driver and Employees Involved: Robert Farinick

Supervisor(s) of Driver and Employees Involved: John Hansen / Rob Campbell

How Person completing this Report received notice of damage/incident: First hand,
was present for incident

Damage Observed: Broken Mirror

Incident Description: While driving G-8 the mirror of the
truck hit a mirror mounted on the side of the
building causing the mirror to fall off the building

Location of Incident: Linda Ln, Westgate Apartments

Was anyone in need of medical attention: Yes ☐ No ☒ Was HR notified? Yes ☒ No ☐

Were any other vehicles / equipment involved: No

NOTIFIED POLICE: Yes ☒ No ☐

Signature of Person completing this Report: Robert Farinick

PAGE 1 OF 2		New Jersey Police Crash Investigation Report		☐ Reportable ☒ Non-Reportable ☐ Change Report	
96	1 Case Number		10 Crash Occurred On:		11 Speed Limit
97	20004295		98 LINDA LN.		15
01	2 Police Dept of		At Intersection With		12 Route No.
98	EDISON POLICE DEPART 01		Feet		13 Milepost
01	3 Station/Precinct		N E of		18 Speed Limit
99			S W		
09	4 Date of Crash		6 Time		7 Municipality
100a	01/22/20		0805		1205
01	5 Day Of Week		8 Total Killed		9 Total Injured
100b	WEDNESDAY				
04	23 Veh #		24 Policy No.		25 NJ Ins. Code
101	1		SELF INSURED		
02	26 Driver's First Name		29 Sex		56 Driver's First Name
102	ROBERT T FARINICK		M		
01	27 Number & Street		57 Number & Street		
103					
01	28 City		58 City		
104					
1	30 Eyes		60 Eyes		
105	04 B		1EK		
11	32 Driver's License Number		33 DOB		34 Expires
106					
07	35 Owner's First Name		65 Owner's First Name		
107	EDISON TWP				
20	36 Number & Street		66 Number & Street		
108	100 MUNICIPAL BLVD.				
09	37 City		67 City		
109	EDISON				
110	38 Make		68 Make		
03	FREIGHTLINE				
111	39 Model		69 Model		
112	TR				
113	40 Color		70 Color		
114	WT				
115	41 Year		71 Year		
116	2011				
03	42 Plate No.		72 Plate No.		
117	MG88922				
118	43 State		73 State		
119	NJ				
120	44 VIN		74 VIN		
121	1FVHC7DV8BHBC6932				
122	45 Expires		75 Expires		
123	04 20				
124	46 Vehicle Removed To		76 Vehicle Removed To		
125	DRIVER				
126	☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded		☐ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded		
127	☐ Left At Scene ☐ Towed Impounded		☐ Left At Scene ☐ Towed Impounded		
128	47 Authority		77 Authority		
129	☐ Owner ☒ Driver ☐ Police		☐ Owner ☐ Driver ☐ Police		
130	48 Alcohol/Drug Test		78 Alcohol/Drug Test		
131	Given: ☒ No ☐ Yes ☐ Refused		Given: ☐ No ☐ Yes ☐ Refused		
132	Type: ☐ Breath ☐ Blood ☐ Urine		Type: ☐ Breath ☐ Blood ☐ Urine		
133	Results: 0. - % ☐ Pending		Results: 0. - % ☐ Pending		
134	49 Hazardous Material		79 Hazardous Material		
135	☐ None ☐ On Board ☐ Spill		☐ None ☐ On Board ☐ Spill		
136	50 Carrier No.		80 Carrier No.		
137	☐ USDOT ☐ None		☐ USDOT ☐ None		
138	☐ MC/MX ☐ None		☐ MC/MX ☐ None		
139	51 GVWR/GCWR		81 GVWR/GCWR		
140	☐ Weight <= 10,000 lbs		☐ Weight <= 10,000 lbs		
141	☐ Weight 10,001-26,000 lbs		☐ Weight 10,001-26,000 lbs		
142	☒ Weight >= 26,001 lbs		☐ Weight >= 26,001 lbs		
143	52 Motor Carrier or Government Entity		82 Motor Carrier or Government Entity		
144	EDISON TWP				
145	Number & Street		Number & Street		
146	100 MUNICIPAL BLVD.				
147	City		City		
148	EDISON				
149	State		State		
150	NJ				
151	Zip		Zip		
152	08817				
153	135 Damage To Other Property		☒ Yes (If Yes, describe) ☐ No		
154	EXTERIOR MIRROR ON BLDG #98				
155	Oper.				


New Jersey Police Crash Investigation Report

Police Dept: **EDISON POLICE DEPAR** Code: **01**Station: - Case No: **20004295**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Dept	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
L														
E														
I														
N														
V														
O														
L														
V														
E														
I														
D														
J														

144 Crash Diagram (NOT TO SCALE)



145 Crash Description/Narrative

D1 was navigating through the development of 98 Linda Ln. in a township garbage truck when his drivers side mirror made contact with an exterior mirror protruding from the building at 98 Linda Ln.. The mirror is an obstruction for large trucks and is not a standard fixture.

BCI / TWP supervisor on scene

146 Officer's Signature

JONATHAN KOLE

147 Badge #

0317

148 Reviewer

DECHIRICO

Badge #

0199

149 Case Status

☐ Pending☒ Complete