

Edison Department of Public Works

Incident Report

[] DIA TESTING
[] COPY TO HR [] COPY TO DPW
[] FAXED TO QUAL-LYNX
MVA-609-926-9270 Injury 732-562-2815

THIS FORM MUST BE FILLED OUT AND SUBMITTED TO THE HUMAN RESOURCES
OFFICE WITHIN 24 HOURS OF ANY INCIDENT UNLESS OCCURRING ON WEEKEND
OVERTIME HOURS

DIVISION: Parks Date of Report: 8/6/2020
Date of Incident: 08/05/2020 Time of Incident: 4:30 P.M.
Weather Condition: Clear
Vehicle #: G-34 Vehicle/Equipment Category: Bucket Truck
Driver and Employees Involved: Anthony Ray, Ryan Naiduk, Corey
Supervisor(s) of Driver and Employees Involved: William Thomas
How Person completing this Report received notice of damage/incident: Received
PHONE CALL FROM DRIVER STATING WHAT HAPPENED
Damage Observed: DAMAGE TO Bucket + Bucket PLATFORM
Incident Description: Vehicle WAS DRIVING DOWN ROAD
AND CAUGHT A LOW HANGING POWER LINE DUE
TO TROPICAL STORM
Location of Incident: MAONLINE RD.
Was anyone in need of medical attention: Yes ☐ No ☒ Was HR notified? Yes ☒ No ☐
Where any other vehicles / equipment involved: No
NOTIFIED POLICE: Yes ☒ No ☐
Signature of Person completing this Report: [Signature]

96	PAGE 1 OF 2		Fatal		New Jersey Police Crash Investigation Report										☐ Reportable ☒ Non-Reportable ☐ Change Report								
05	1 Case Number										10 Crash Occurred On: MADALINE DR										11 Speed Limit		118a
97	20038142										N										25		99
01	2 Police Dept of										Road Name										12 Route No.		118b
98	EDISON POLICE DEPART 01										Dir										25		-
01	3 Station/Predict										13 Milepost										18 Speed Limit		119a
99	50										14 15										25		-
07	4 Date of Crash										5 Day Of Week										6 Time		119b
100a	08/05/20										WEDNESDAY										1813		120a
01	1205										8 Total Killed										9 Total Injured		120b
100b	23 Veh #										24 Policy No.										25 NJ Ins. Code		01
04	1										SELF INSURED ID 19-98										53 Veh #		54 Policy No.
101	☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp To Emergency ☐ Hit & Run										☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp To Emergency ☐ Hit & Run										55 NJ Ins. Code		
02	26 Driver's First Name										27 Sex										56 Driver's First Name		59 Sex
102	ANTHONY										M										RAY		-
01	27 Number & Street										57 Number & Street										121a		
103	28 City										State Zip										58 City		59 State Zip
01	29 Eyes										DL Class										Restrictions		Endorsements
104	02										A										K		MN
1	30 Eyes										DL Class										Restrictions		Endorsements
105	32 Driver's License Number										33 DOB										34 Expires		62 Driver's License Number
11	35 Owner's First Name										Initial Last Name										65 Owner's First Name		Initial Last Name
106	☐ Same As Driver										TWP. OF										EDISON		-
107	36 Number & Street										66 Number & Street										124		
-	100 MUNICIPAL BLVD										67 City										State Zip		
108	37 City										State Zip										68 Make		69 Model
20	EDISON										NJ										08817		70 Color
-	38 Make										39 Model										40 Color		41 Year
-	WESTERN ST										UNKNOWN										WT		2019
110	44 VIN										45 Expires										74 VIN		75 Expires
03	SKKAAXDV3LLH5653										09										22		-
111	46 Vehicle Removed To										76 Vehicle Removed To										126a		
-	☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded										☐ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded										126b		
112	☐ Left At Scene ☐ Towed Impounded										☐ Left At Scene ☐ Towed Impounded										126c		
113	47 Authority										77 Authority										69		
-	☐ Owner ☒ Driver ☐ Police										☐ Owner ☐ Driver ☐ Police										127a		
114	48 Alcohol/Drug Test										49 Hazardous Material										78 Alcohol/Drug Test		79 Hazardous Material
-	Given: ☒ No ☐ Yes ☐ Refused										☐ None ☐ On Board ☐ Spill										Given: ☐ No ☐ Yes ☐ Refused		☐ None ☐ On Board ☐ Spill
115	Type: ☐ Breath ☐ Blood ☐ Urine										Results: 0. - % ☐ Pending										Type: ☐ Breath ☐ Blood ☐ Urine		Results: 0. - % ☐ Pending
116	50 Carrier No.										51 GVWR/GCWR										80 Carrier No.		81 GVWR/GCWR
02	☐ USDOT ☐ None										☐ Weight <= 10,000 lbs										☐ USDOT ☐ None		☐ Weight <= 10,000 lbs
117	☐ MC/MX										☐ Weight 10,001-26,000 lbs										☐ MC/MX		☐ Weight 10,001-26,000 lbs
-	☐ Weight >= 26,001 lbs										☐ Weight >= 26,001 lbs										127d		
118	52 Motor Carrier or Government Entity										82 Motor Carrier or Government Entity										128		
-	Number & Street										Number & Street										69		
119	City										State Zip										13		
120	135 Damage To Other Property										136 Charge										137 Summons. No.		
-	☒ Yes (If Yes, describe) ☐ No										138 Charge										139 Summons. No.		
121	UTILITY POLE # 65709ED WAS PULLED DOWN										140 Charge										141 Summons. No.		
122	142 Charge										143 Summons. No.										03		
123	83										84										85		
124	86										87										88		
125	89										90										91		
126	92										93										94		
127	95										Names & Addresses of Occupants - If Deceased, Date & Time of Death										129		
128	V1										01										01		
129	52										M										-		
130	-										-										-		
131	-										-										-		
132	-										-										-		
133	-										-										-		
134	-										-										-		


New Jersey Police Crash Investigation Report

Police Dept: **EDISON POLICE DEPAR** Code: **01**Station: - Case No: **20038142**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Dept	Hosp Code	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A														
L														
L														
I														
N														
V														
O														
L														
V														
E														
D														
J														

144 Crash Diagram (NOT TO SCALE)



145 Crash Description/Narrative

The driver of Vehicle #1 stated that he was traveling east on Madeline Drive and he felt the utility pole come down on his truck. This Officers on scene investigation found the wire was hanging low and hooked onto the bucket of the truck, as it was passing by and pulled the pole down on top of the vehicle.

146 Officer's Signature

STEPHEN FINGAL

147 Badge #

0444

148 Reviewer

DECHIRICO

Badge #

0199

149 Case Status

☐ Pending☒ Complete