


NJTR-1 (Rev. 01/17)

[illegible]

145. Crash Description/Narrative


Driver of vehicle 1, stated he was pulling out of the driveway when the pedestrian jumped in front of the vehicle. Same stated the pedestrian hit the passenger side of his vehicle and he immediately stop

Pedestrian stated he was walking on the side walk and was suddenly struck by vehicle 1

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Castro Roa, Lina: PO C864		RSCHALEN		☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report	Police Dept. <u>Elizabeth</u>	Code <u>01</u>
	Station <u> </u>	Case No. <u>20-046814</u>

Motor Vehicle Crash Description



[illegible]

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Description

Police Dept: Elizabeth

Code: 0 1

Station:

Case No.: 20-046814

(Refer to vehicle by number)

[illegible]

Castro Roa, Lina: PO C864

NJTR-1M (Rev. 01/17)

Officer's Signature

Badge Number