

The diagram illustrates a collision between two vehicles on a multi-lane road. At the top, a grey box contains the text "Not To Scale" in red. To the right, the text "ROUTE 1 SOUTH" is displayed. The road is depicted with multiple horizontal lanes. Two vehicles, labeled "VEHICLE 1" and "VEHICLE 2" in red boxes, are shown in the center lanes. Red arrows point from these labels to the vehicles. A red arrow points to the front of Vehicle 1, and another red arrow points to the front of Vehicle 2. The two vehicles are positioned such that their fronts are touching, indicating a collision. A red arrow points to the point of contact, which is labeled "POINT OF IMPACT" in a red box. The road curves to the right in the lower portion of the diagram. A circular compass rose in the bottom right corner indicates North (N) with an arrow pointing left.

D1 stated he was driving South on Route 1. D1 stated a vehicle was coming onto the highway at a high rate of speed. D1 stated the vehicle in front of him (V2) slammed on their breaks. D1 stated he slammed on his breaks, however, the vehicle did not stop before making impact with the rear portion of V2.

D2 stated he was driving South on Route 1. D2 stated a vehicle was coming onto the highway at a high rate of speed. D2 stated he stated he thought the on coming vehicle was going to slow down. D2 stated the on coming vehicle continued at a high rate of speed. D2 stated this vehicle caused him to slam on his breaks. D2 stated once he slammed on his breaks V1 struck the rear portion of his vehicle.

New Jersey Police Crash Investigation Report Motor Vehicle Crash Description	Police Dept. <u>Elizabeth</u> Station _____	Code <u>0 1</u> Case No. <u>20-048683</u>
--	---	---



