


NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 20-049570		Page <u>2</u> of <u>2</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death	
E	---	---	---	---	---	---	---	---	---	---	---	---	---	----- -----	
F	---	---	---	---	---	---	---	---	---	---	---	---	---	----- -----	
G	---	---	---	---	---	---	---	---	---	---	---	---	---	----- -----	
H	---	---	---	---	---	---	---	---	---	---	---	---	---	----- -----	
I	---	---	---	---	---	---	---	---	---	---	---	---	---	----- -----	
J	---	---	---	---	---	---	---	---	---	---	---	---	---	----- -----	

Not To Scale



145. Crash Description/Narrative

Vehicle 1 is unknown.

Owner of vehicle 2 stated that when she looked outside her window, she noticed her parked vehicle had been struck and noticed her bumper was laying on the ground. Vehicle sustained damage to the front end and driver side fender as well as moderate damage to the driver side door front and rear door.

Owner of V2 stated that she never saw the accident and didn't hear anything. Same also noted that there are no cameras in the immediate area. **BWR**

146. Officer's Signature

Jimenez, Diego: PO J987

147. Badge #

373

148. Reviewer


BTURNER / T798

Badge #

149. Case Status

☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report Motor Vehicle Crash Description	Police Dept. <u>Elizabeth</u> Station _____	Code <u>0 1</u> Case No. <u>20-049570</u>
--	---	---



New Jersey Police Crash Investigation Report

Motor Vehicle Crash Description

Police Dept: Elizabeth

Code: 0 1

Station:

Case No.: 20-049570

(Refer to vehicle by number)

[illegible]

Jimenez, Diego: PO J987

373

