


NJTR-1 (Rev. 01/17)

[illegible]


145. Crash Description/Narrative

Driver of vehicle #1 stated that he was traveling West on North Avenue when vehicle #2, which was traveling the opposite way, collided with his car when vehicle #2 suddenly made a left turn onto Salem Avenue.

Driver of vehicle #2 stated that he did not see vehicle #1 coming in the opposite direction when he made his left turn onto Salem Avenue from North Avenue.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Matos, Victor: PO M424	137			☐ Pending ☐ Complete

New Jersey Police Crash Investigation Report	Police Dept. <u>Elizabeth</u>	Code <u>0 1</u>
Motor Vehicle Crash Description	Station _____	Case No. <u>19-173654</u>



[illegible]

