

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00041069			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Driver of vehicle #1 was traveling West on Rt. 88 directly behind vehicle #2. Vehicle #1 rear ended vehicle #2 as they were stopping in traffic.

Driver of vehicle #1 stated he was traveling behind vehicle #2. He stated vehicle #2 stopped short in traffic causing him to rear end their vehicle. He stated he attempted to hit the brakes, however he wasn't able to stop in time.

Driver of vehicle #2 stated she was stopping in traffic. She stated vehicle #1 was following closely behind her vehicle and rear ended her as she was stopping in traffic.

My investigation revealed driver of vehicle #1 was following too closely behind vehicle #2 which contributed to the crash.


146. Officer's Signature Victoria L. Finelli	147. Badge # 273	148. Reviewer Robert A Hine	Badge # 158	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00041069

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Victoria L Finelli

273