Page 1 of 3 ☐ Fatal

New Jersey Police Crash Investigation Report

☐ Reportable ☒ Non-Reportable ☐ Change Report

1. Case Number: 2018-00035596

2. Police Dept. of: Brick Police — Code: 01

3. Station/Precinct: —

10. Crash Occurred On: 425 JACK MARTIN BLVD (Road Name) — Dir: —

☐ At Intersection with
☐ Feet ☐ Miles ☐N ☐E ☐S ☐W of:

11. Speed Limit: —

12. Route No. — Suffix — 13. Milepost —

18. Speed Limit: —

19. Ramp ☐To: ☐From: 17. Cross Road Name/Route No. —

☐NB ☐EB ☐SB ☐WB

20 Route Name/Route No. —

21. Latitude — 22. Longitude —

4. Date of Crash (mm dd yy): 06 14 18

5. Day of Week: Su M Tu W (T) F Sa

6. Time (use 2400 hrs.): 1506

7. Municipality Code: 1506

8. Total Killed: —

9. Total Injured: —

Vehicle 1

23. Veh. #: 01

24. Policy No.: —

25. NJ Ins. Code: —

☐ Parked ☐ Ped ☐ Pedalcylist ☐ Resp. to Emergency ☒ Hit & Run

26. Driver's First Name — Initial — Last Name: —

29. Sex: —

27. Number & Street: —

28. City — State — Zip: —

30. Eyes — DL Class — Restrictions — Endorsements — 31. State: —

32. Driver's License Number — 33. DOB (mm dd yy) — 34. Expires (mm yy)

35. Owner's First Name — Initial — Last Name

☐ Same as Driver —

36. Number & Street: —

37. City — State — Zip: —

38. Make — 39. Model — 40. Color — 41. Year — 42. Plate No. — 43. State

44. VIN — 45. Expires: —

46. Vehicle Removed to:

☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded
☐ Left at Scene ☐ Towed Impounded

47. Authority
☐ Owner ☒ Driver ☐ Police

48. Alcohol Drug Test
Given: ☐ No ☐ Yes ☐ Refused
Type: ☐ Breath ☐ Blood ☐ Urine
Results: 0.-- % ☐ Pending

49. Hazardous Material
☒ None ☐ On Board ☐ Spill
Hazard Class — Placard No.

50. Carrier No.
☐ USDOT ☒ None
☐ MC/MX

51. GVWR / GCWR *(trucks & buses only)*
☐ ≤ 10,000 lbs.
☐ 10,001 - 26,000 lbs.
☐ ≥ 26,001 lbs.

52. Motor Carrier or Government Entity: —

Number & Street: —

City — State — Zip: —

Vehicle 2

53. Veh. #: 02

54. Policy No.: 0495068-F02-30H

55. NJ Ins. Code: 962

☒ Parked ☐ Ped ☐ Pedalcylist ☐ Resp. to Emergency ☐ Hit & Run

56. Driver's First Name — Initial — Last Name: —

59. Sex: —

57. Number & Street: —

58. City — State — Zip: —

60. Eyes — DL Class — Restrictions — Endorsements — 61. State: —

62. Driver's License Number — 63. DOB (mm dd yy) — 64. Expires (mm yy)

65. Owner's First Name — Initial — Last Name

☐ Same as Driver ANDREW J REPAK

66. Number & Street: 208 CANDLEWICK LN

67. City: BRIDGEWATER — State: NJ — Zip: 08807

68. Make: Lincoln — 69. Model: MKZ — 70. Color: BK — 71. Year: 2014 — 72. Plate No.: L44HHY — 73. State: NJ

74. VIN: 3LN6L2LU8ER810989 — 75. Expires: 12/18

76. Vehicle Removed to:

☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded
☐ Left at Scene ☐ Towed Impounded

77. Authority
☐ Owner ☒ Driver ☐ Police

78. Alcohol Drug Test
Given: ☐ No ☐ Yes ☐ Refused
Type: ☐ Breath ☐ Blood ☐ Urine
Results: 0.-- % ☐ Pending

79. Hazardous Material
☒ None ☐ On Board ☐ Spill
Hazard Class — Placard No.

80. Carrier No.
☐ USDOT ☒ None
☐ MC/MX

81. GVWR / GCWR *(trucks & buses only)*
☐ ≤ 10,000 lbs.
☐ 10,001 - 26,000 lbs.
☐ ≥ 26,001 lbs.

82. Motor Carrier or Government Entity: —

Number & Street: —

City — State — Zip: —

135. Damage to Other Property ☐ Yes *(If Yes, describe)* ☒ No

Oper.	Charge	Summons No.	Oper.	Charge	Summons No.
—	—	—	—	—	—
—	—	—	—	—	—

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants *If Deceased, Date & Time of Death*
A	01	01	01	00	0	00	00	00	—	00	00	00	—	Hit & Run 0
B														
C														
D														

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants *If Deceased, Date & Time of Death*
E														
F														
G														
H														
I														
J														

144. Crash Diagram

Show NORTH by Arrow (Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene indicated the following: Vehicle 2 faced west while parked (unoccupied) in the parking garage located at 425 Jack Martin Boulevard. The rear passenger side bumper was struck by another vehicle which left light colored transfer marks. The damage was consistent with another vehicle backing into the parked vehicle.

I spoke to the owner of vehicle 2 and he stated the following:

The owner parked his vehicle in the parking garage at approximately 0700 hours today and did not notice any damage the rear bumper of the vehicle. When he returned to his vehicle at 1506 hours, he saw damage to the vehicle. The owner spoke to the Hospital's security who told him there are no surveillance cameras pointing in the area of his vehicle.

I checked the surrounding area and did not locate a vehicle with damage that would be consistent with the accident.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Ryan G Wynn	261	James J Kelly	233	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report Motor Vehicle Crash Diagram	Police Dept: Brick Police Code: 01 Station: — Case No: 2018-00035596

144 Crash Diagram (NOT TO SCALE)

Indicate North

Parking Garage
425 Jack Martin Boulevard



Ryan G Wynn
Officer's Signature

261
Badge Number