

New Jersey Police Crash Investigation Report												Case Number 2018-00038034			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was stopped in traffic, east on Route 88 just west of Van Zile Road when vehicle 1 rear ended her.

Driver 1 stated he was traveling east on Route 88 directly behind vehicle 2 when he took his eyes off of the road. When driver 1 put his attention back on the road he realized traffic was stopped and was unable to stop, rear ending vehicle 2.

Driver 2 stated she was traveling east on Route 88 and that she was stopped in traffic just west of Van Zile Road when vehicle 1 rear ended her.

Investigation revealed that the cause of the crash was due to driver 1 taking his attention off the road and not knowing that traffic in front of him had stopped.


146. Officer's Signature Michael A DeFluri	147. Badge # 270	148. Reviewer Jason M Matthews	Badge # 210	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00038034

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Michael A DeFluri

Officer's Signature

270

Badge Number