

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00038768			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 01 jumped the curb in a Handicap parking space at 2060 Rt 88 striking a sign and a bush.

Driver of Vehicle 01 stated while waiting for his wife he was parked in a handicapped parking space at 2060 Rt 88 facing Rt 88 when his foot slipped of the brake and his vehicle jumped the curb striking a sign and a bush.

Driver of Vehicle 01 called Triple AAA Towing to remove the vehicle.

146. Officer's Signature Robert Koch	147. Badge # 170	148. Reviewer James J Kelly	Badge # 233	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00038768

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Rt 88

Sidewalk

Parking Lot

2060 Rt 88

Robert Koch

Officer's Signature

170

Badge Number