

New Jersey Police Crash Investigation Report												Case Number 2018-00034106			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Driver of vehicle #2 was stopped on Burrsville Rd. making a left turn onto Jack Martin Blvd. Driver of vehicle #1 did not see vehicle #2 stopped at the intersection and rear ended vehicle #2.

Driver #1 stated she was going straight through the intersection, saw a green light and did not see vehicle #2 stopped and waiting to make a left turn.

Driver #2 stated he was waiting for traffic to pass Southbound on Burrsville Rd. in order for him to turn left onto Jack Martin Blvd. Driver #1 rear ended him as he was stopped at the light with his blinker on.

My investigation revealed driver #2 was stopped at the intersection waiting to turn left. Driver #1 rear ended vehicle #2.

146. Officer's Signature Victoria L. Finelli	147. Badge # 273	148. Reviewer James J Kelly	Badge # 233	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:


Case No: 2018-00034106

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



NOT TO SCALE



Victoria L Finelli

Officer's Signature

273

Badge Number