

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00034101			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #2 was traveling westbound in the Walmart parking lot after pulling out of a parking space. Vehicle #1 was backing out of a parking space. Vehicle #1, while backing, struck Vehicle #2 with its rear, causing minor damage to the front license plate and bumper of Vehicle #2. Vehicle #1 also sustained minor damage to the rear bumper on the passenger side.

Driver of Vehicle #1 stated that while backing he did not see Vehicle 2. Nor did his back sensor on his truck alert him that an object was behind him.

Driver of Vehicle #2 stated that after pulling out into the lane of travel, he stopped briefly to fix his sunglasses. Driver #2 further stated that When he observed Vehicle #1 backing he honked his horn but Vehicle #1 kept backing up, resulting in the crash.

Based upon my observations, and statements made by both drivers, I concluded Driver of Vehicle #1 is at fault for unsafe backing.


146. Officer's Signature Stephen Robert Bailey	147. Badge # 0293	148. Reviewer James J Kelly	Badge # 233	149. Case Status ☐ Pending ☒ Complete
---	----------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police Code: 01
Station: Case No: 2018-00034101

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



PARKING LOT



Stephen Robert Bailey

0293