

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00030717			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Crash investigation reveals a two vehicle crash in the parking lot of the Walmart store located at 1872 Route 88.

Vehicle 2 was backed out of a marked parking spot in said parking lot facing west. After vehicle 2 backed out of a marked parking spot in the store lot, vehicle 1 began backing out of a marked parking spot. As vehicle 1 backed out, the driver of vehicle 1 stated she didn't see vehicle 2 had just backed out causing the rear of vehicle 1 to crash into the rear of vehicle 2. No injuries were reported and both vehicles sustained minor damage. Driver of vehicle 1 is at fault for the crash.

146. Officer's Signature Thomas P Caulfield	147. Badge # 235	148. Reviewer Arthur D Rivaldo	Badge # 179	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01


Station:

Case No: 2018-00030717


144 Crash Diagram (NOT TO SCALE)

○ Indicate North

Walmart
1872 Route 88



NOT TO SCALE



Thomas P Caulfield

235