

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00025098			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #2 was stopping in traffic, south on Burrsville Rd., at the intersection of Rt. 88, at a stop sign.

Vehicle #1 was starting in traffic, south on Burrsville Rd., directly behind vehicle #2.

Driver #1 stated vehicle #2 started moving forward, and came to a stop. Driver #1 believed vehicle #2 was going to proceed through the intersection, however, it did not. Driver #1 stated she was unable to stop in time to avoid collision, and the front bumper of vehicle #1 collided with the rear bumper of vehicle #2. Minor scratches were observed on the front bumper of vehicle #1 and a large crack and scratches were observed on the rear bumper of vehicle #2.

Driver #2 stated she began moving forward to get a clearer view of the intersection and came to a stop, when vehicle #1 collided into her vehicle.

No injuries were reported at the scene, and both vehicles were moved prior to my arrival.

146. Officer's Signature Joseph L. Rossi	147. Badge # 240	148. Reviewer Henry J. Drew	Badge # 147	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00025098

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Joseph L Rossi

Officer's Signature

240

Badge Number